


Appendix F **Test Photos**

Appendix F. Test Photos



Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. : F1 of F5 TEL: 886-3-327-3456 Report Version : Rev. 01



Test Photos Appendix F




Side view

SPORTON INTERNATIONAL INC. Page No. : F2 of F5
TEL: 886-3-327-3456 Report Version : Rev. 01




Test Photos Appendix F

2. Photographs of Radiated Emissions Test Configuration (Blow 1G) For radiated emissions 9kHz~30MHz



Front view




Rear view

SPORTON INTERNATIONAL INC. Page No. : F3 of F5 TEL: 886-3-327-3456 Report Version : Rev. 01




Test Photos Appendix F

Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. : F4 of F5
TEL: 886-3-327-3456 Report Version : Rev. 01




Test Photos Appendix F


3. Photographs of Radiated Emissions Test Configuration (Above 1G)

Mode 1





Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F5 of F5

Report Version

: Rev. 01