

Appendix E. Test Setup Photos



Bottom of the DUT with Phantom 0 cm Gap (Sample 1 with Battery 1)



Report No.: FA1O2634

Bottom of the DUT with Phantom 0 cm Gap (Sample 2 with Battery 2)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: ZQO-DWPCIE83 Page Number : E1 of E1
Report Issued Date : Dec. 02, 2011
Report Version : Rev. 01