

# 8. SETUP PHOTOS


#### **RADIATED RF MEASUREMENT SETUP**






Page 28 of 30

FAX: (510) 661-0888 TEL: (510) 771-1000




## AC MAINS LINE CONDUCTED EMISSION



Page 29 of 30

### **SUPPORT LAPTOP**





# **END OF REPORT**

Page 30 of 30