Test report No.
 : 10003538H-C-R1

 Page
 : 21 of 22

 Issued date
 : March 11, 2013

 Revised date
 : March 12, 2013

 FCC ID
 : ZQUCHC-S6245-5

APPENDIX 3: Photographs of test setup

Conducted emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

 Test report No.
 : 10003538H-C-R1

 Page
 : 22 of 22

 Issued date
 : March 11, 2013

 Revised date
 : March 12, 2013

 FCC ID
 : ZQUCHC-S6245-5

Radiated emission




Photo 1




Photo 2

End of Report

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124