Test report No. : 11555571H-C-R2
Page : 22 of 24
Issued date : March 7, 2017
FCC ID : ZQUZC10L

APPENDIX 3: Photographs of test setup

Conducted emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11555571H-C-R2
Page : 23 of 24
Issued date : March 7, 2017
FCC ID : ZQUZC10L

Radiated emission




Photo 1



Photo 2


UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11555571H-C-R2
Page : 24 of 24
Issued date : March 7, 2017
FCC ID : ZQUZC10L

With/Without Tag





* The cover is closed during the tests.

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124