Test report No. : 32EE0060-HO-C-R1

Page : 21 of 22 Issued date : March 7, 2012 Revised date : March 14, 2012 FCC ID : ZQUCHC-S6145-5

APPENDIX 3: Photographs of test setup

Conducted emission




Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 32EE0060-HO-C-R1

 Page
 : 22 of 22

 Issued date
 : March 7, 2012

 Revised date
 : March 14, 2012

 FCC ID
 : ZQUCHC-S6145-5

Radiated emission




Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124