Test report No. : 11796546H-D
Page : 22 of 24
Issued date : July 27, 2017
FCC ID : ZQU-D1150410

APPENDIX 3: Photographs of test setup

Conducted emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11796546H-D
Page : 23 of 24
Issued date : July 27, 2017
FCC ID : ZQU-D1150410

Radiated emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


 Test report No.
 : 11796546H-D

 Page
 : 24 of 24


 Issued date
 : July 27, 2017

 FCC ID
 : ZQU-D1150410

With/Without Tag



With Tag



Without tag (Worst)
*The cover is closed during the tests.

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124