Page
 : 13 of 24

 Issued date
 : July 20, 2011

 Revised date
 : August 10, 2011

 FCC ID
 : ZQUDP-1045-5

APPENDIX 1: Photographs of test setup

Conducted emission




Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

 Page
 : 14 of 24

 Issued date
 : July 20, 2011

 Revised date
 : August 10, 2011

 FCC ID
 : ZQUDP-1045-5

Radiated emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

 Page
 : 15 of 24

 Issued date
 : July 20, 2011

 Revised date
 : August 10, 2011

 FCC ID
 : ZQUDP-1045-5

Worst Case Position

Below 30MHz EUT: X-axis / ANT:Z-axis

Above 30MHz EUT: Horizontal:Z-axis / Vertical:Z-axis ANT: Horizontal:Z-axis / Vertical:Z-axis

EUT






Y-axis







Z-axis





UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


 Page
 : 16 of 24

 Issued date
 : July 20, 2011

 Revised date
 : August 10, 2011

 FCC ID
 : ZQUDP-1045-5

Worst Case Position



With Tag



Without Tag(Worst)

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN