
## INTERTEK TESTING SERVICES

Report No. : HK11081225-1

Span 1 MHz

Sample No.: 1/2





100 kHz/

Center 433.95 MHz