


page 1 of 7

ANNEX A: TEST SETUP PHOTOS




112414_1.JPG: Zonescan 820 Logger with internal antenna, test setup fully anechoic chamber

Examiner: Thomas KÜHN Test Report No.: F112414E1, 2nd version
Date of issue: 18 January 2012 Order No.: F112414



page 2 of 7

ANNEX A: TEST SETUP PHOTOS




112414_4.JPG: Zonescan 820 Logger with external antenna, test setup fully anechoic chamber

Examiner: Thomas KÜHN Test Report No.: F112414E1, 2nd version
Date of issue: 18 January 2012 Order No.: F112414E1, 2nd version
11-112414



ANNEX A: TEST SETUP PHOTOS



112414_8.JPG: Zonescan 820 Logger with external antenna, test setup fully anechoic chamber


 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112414E1, 2nd version

 Date of issue:
 18 January 2012
 Order No.:
 11-112414
 page 3 of 7



page 4 of 7

ANNEX A: TEST SETUP PHOTOS




112414_2.JPG: Zonescan 820 Logger with internal antenna, test setup fully anechoic chamber

Examiner: Thomas KÜHN Test Report No.: F112414E1, 2nd version
Date of issue: 18 January 2012 Order No.: F112414E1, 2nd version
11-112414



page 5 of 7

ANNEX A: TEST SETUP PHOTOS



112414_7.JPG: Zonescan 820 Logger with external antenna, test setup fully anechoic chamber

Test Report No.: F112414E1, 2nd version Order No.: 11-112414

Examiner: Thomas KÜHN
Date of issue: 18 January 2012



ANNEX A: TEST SETUP PHOTOS



112414_9.JPG: Zonescan 820 Logger with internal antenna, test setup open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112414E1, 2nd version

 Date of issue:
 18 January 2012
 Order No.:
 11-112414
 page 6 of 7



page 7 of 7

ANNEX A: TEST SETUP PHOTOS



112414_10.JPG: Zonescan 820 Logger with external antenna, test setup open area test site

Examiner: Thomas KÜHN
Date of issue: 18 January 2012 Test Report No.: F112414E1, 2nd version Order No.: 11-112414