



113573\_e.JPG: ZONESCAN 820 ALPHA, internal view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113573E1

 Date of issue:
 16 November 2011
 Order No.:
 11-113573

 page 1 of 8






113573\_d.JPG: ZONESCAN 820 ALPHA, internal view (batteries removed)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113573E1

 Date of issue:
 16 November 2011
 Order No.:
 11-113573
 page 2 of 8






113573\_i.JPG: ZONESCAN 820 ALPHA, PCB, top view (battery holder and GPRS module removed)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113573E1

 Date of issue:
 16 November 2011
 Order No.:
 11-113573
 page 3 of 8






113573\_g.JPG: ZONESCAN 820 ALPHA, PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113573E1

 Date of issue:
 16 November 2011
 Order No.:
 11-113573
 page 4 of 8





113573\_k.JPG: ZONESCAN 820 ALPHA, PCB, bottom view (shielding removed)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113573E1

 Date of issue:
 16 November 2011
 Order No.:
 11-113573

 page 5 of 8






113573\_n.JPG: ZONESCAN 820 ALPHA, GPRS module, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113573E1

 Date of issue:
 16 November 2011
 Order No.:
 11-113573
 page 6 of 8





113573\_o.JPG: ZONESCAN 820 ALPHA, GPRS module, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113573E1

 Date of issue:
 16 November 2011
 Order No.:
 11-113573
 page 7 of 8





113573\_m.JPG ZONESCAN 820 ALPHA, GSM / GPS antenna

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F113573E1

 Date of issue:
 16 November 2011
 Order No.:
 11-113573

 page 8 of 8