


page 1 of 8


ANNEX A: TEST SETUP PHOTOS



112416_1.JPG: Zonescan 820 Commlink, test set-up fully anechoic chamber (pos. 1)

Examiner: Thomas KÜHN Test Report No.: F112416E2, 2nd version
Date of issue: 18 January 2012 Order No.: F112416E2, 2nd version
11-112416





112416_7.JPG: Zonescan 820 Commlink, test set-up fully anechoic chamber (pos. 2)


Test Report No.: F112416E2, 2nd version Order No.: 11-112416

Examiner: Thomas KÜHN
Date of issue: 18 January 2012 page 2 of 8



page 3 of 8


ANNEX A: TEST SETUP PHOTOS



112416_10.JPG: Zonescan 820 Commlink, test set-up fully anechoic chamber (pos. 3)

Examiner: Thomas KÜHN Test Report No.: F112416E2, 2nd version
Date of issue: 18 January 2012 Order No.: F112416E






112416_13.JPG: Zonescan 820 Commlink, test set-up fully anechoic chamber (pos. 3)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112416E2, 2nd version

 Date of issue:
 18 January 2012
 Order No.:
 11-112416
 page 4 of 8






112416_3.JPG: Zonescan 820 Commlink, test set-up fully anechoic chamber (pos. 1)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112416E2, 2nd version

 Date of issue:
 18 January 2012
 Order No.:
 11-112416
 page 5 of 8





112416_5.JPG: Zonescan 820 Commlink, test set-up fully anechoic chamber (pos. 2)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112416E2, 2nd version

 Date of issue:
 18 January 2012
 Order No.:
 11-112416
 page 6 of 8






112416_14.JPG: Zonescan 820 Commlink, test set-up open area test site (pos. 1)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112416E2, 2nd version

 Date of issue:
 18 January 2012
 Order No.:
 11-112416
 page 7 of 8





112416_35.JPG: Zonescan 820 Commlink, test set-up shielded chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112416E2, 2nd version

 Date of issue:
 18 January 2012
 Order No.:
 11-112416
 page 8 of 8