


181805_05.jpg: EUT - cabinet opened, PCB side

 Examiner:
 Wolfgang KASALOWSKY
 Report Number:
 F181805E4

 Date of issue:
 21.01.2019
 Order Number:
 18-111805
 page 1 of 6





181805_17.jpg: EUT – cabinet opened, PCB removed from cabinet

 Examiner:
 Wolfgang KASALOWSKY
 Report Number:
 F181805E4

 Date of issue:
 21.01.2019
 Order Number:
 18-111805

Page 2 of 6





181805_06.jpg: EUT - cabinet opened, sensor side

 Examiner:
 Wolfgang KASALOWSKY
 Report Number:
 F181805E4

 Date of issue:
 21.01.2019
 Order Number:
 18-111805

 page 3 of 6
 page 3 of 6






181805_07.jpg: EUT - top view, PCB top view

 Examiner:
 Wolfgang KASALOWSKY
 Report Number:
 F181805E4

 Date of issue:
 21.01.2019
 Order Number:
 18-111805

 page 4 of 6






181805_08.jpg: EUT - inside top view, PCB bottom view

 Examiner:
 Wolfgang KASALOWSKY
 Report Number:
 F181805E4

 Date of issue:
 21.01.2019
 Order Number:
 18-111805

 page 5 of 6
 page 5 of 6





181805_13.jpg: Power supply HSB10 - housing opened

 Examiner:
 Wolfgang KASALOWSKY
 Report Number:
 F181805E4

 Date of issue:
 21.01.2019
 Order Number:
 18-111805

 page 6 of 6
 page 6 of 6