


Annex A Test setup photos



161597_14.JPG: ZONESCAN 820 Solar Alpha, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F161597E1


 Date of issue:
 04/24/2017
 Order No.:
 16-111597

 page 1 of 7
 7



page 2 of 7

Annex A Test setup photos




161597_13.JPG: ZONESCAN 820 Solar Alpha, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F161597E1

 Date of issue:
 04/24/2017
 Order No.:
 16-111597



Annex A Test setup photos



161597_7.JPG: ZONESCAN 820 Solar Alpha, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F161597E1


 Date of issue:
 04/24/2017
 Order No.:
 16-111597

 page 3 of 7
 7



page 4 of 7

Annex A Test setup photos



161597_8.JPG: ZONESCAN 820 Solar Alpha, test setup fully anechoic chamber


 Examiner:
 Thomas KÜHN
 Test Report No.:
 F161597E1

 Date of issue:
 04/24/2017
 Order No.:
 16-111597



page 5 of 7

Annex A **Test setup photos**




161597_11.JPG: ZONESCAN 820 Solar Alpha, test setup open area test site

Examiner: Thomas KÜHN Date of issue: 04/24/2017 Test Report No.: F161597E1 Order No.: 16-111597



page 6 of 7

Annex A **Test setup photos**



161597_12.JPG: ZONESCAN 820 Solar Alpha, test setup shielded chamber

Examiner: Thomas KÜHN Date of issue: 04/24/2017 Test Report No.: F161597E1 Order No.: 16-111597



Annex A Test setup photos



161597_15.JPG: ZONESCAN 820 Solar Alpha, test setup shielded chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F161597E1

 Date of issue:
 04/24/2017
 Order No.:
 16-111597

 page 7 of 7
 page 7 of 7