



Annex A Test setup photos



170032_a.JPG: EASYSCAN Link, test setup fully anechoic chamber



Annex A **Test setup photos**




170032_c.JPG: EASYSCAN Link, test setup fully anechoic chamber

Examiner: Thomas KÜHN Date of issue: 05/08/2017

Test Report No.: F170032E1 Order No.: 17-110032




Annex A Test setup photos



170032_b.JPG: EASYSCAN Link, test setup fully anechoic chamber



Annex A Test setup photos



170032_d.JPG: EASYSCAN Link, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F170032E1


 Date of issue:
 05/08/2017
 Order No.:
 17-110032

17-110032 page 4 of 7



page 5 of 7

Annex A Test setup photos



170032_e.JPG: EASYSCAN Link, test setup fully anechoic chamber



page 6 of 7

Annex A Test setup photos



170032_g.JPG: EASYSCAN Link, test setup open area test site



page 7 of 7

Annex A Test setup photos



170032_f.JPG: EASYSCAN Link, test setup shielded chamber