
APPENDIX B. Photographs of EUT




Report No. : EP411403-07



TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B16
ISSUED DATE : Dec. 22, 2014







TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B16
ISSUED DATE : Dec. 22, 2014













TEL: 886-3-327-3456 FAX: 886-3-327-0973 ISSUED DATE : Dec. 22, 2014






TEL: 886-3-327-3456 FAX: 886-3-327-0973 ISSUED DATE : Dec. 22, 2014













SPORTON International Inc.



