



Report No. : FR620407AN

# **Appendix A. Test Photos**

1. Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 




**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR620407AN



**SIDE VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A2 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01





## 1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No. : FR620407AN

**FRONT VIEW** 



Page No.

Report Version

: A3 of A7

: Rev. 01

**REAR VIEW** 

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456



## FCC Test Report


Report No.: FR620407AN

: A4 of A7


: Rev. 01

For radiated emissions 30MHz~1GHz

Non-beamforming



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version






Report No.: FR620407AN

### Beamforming



#### **FRONT VIEW**



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7

Report Version

: Rev. 01




## FCC Test Report


Report No.: FR620407AN

For radiated emissions above 1GHz

Non-beamforming



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A6 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01






Report No.: FR620407AN

#### Beamforming



#### **FRONT VIEW**



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A7

Report Version

: Rev. 01