


Inside view of EUT



Report no. ETLE140214.0221, Page D1 of D7



Top side view of main board



Report no. ETLE140214.0221, Page D2 of D7



Bottom side view of main board with Chip Antenna



Report no. ETLE140214.0221, Page D3 of D7



Top side view of BT module



Report no. ETLE140214.0221, Page D4 of D7




Top side view of Chip Antenna



Report no. ETLE140214.0221, Page D5 of D7




Top side view of touch key board



Report no. ETLE140214.0221, Page D6 of D7



Bottom side view of touch key board



Report no. ETLE140214.0221, Page D7 of D7