
> **Report No.** : E1/2014/70052 : 20 Page of **30**

# 3. Photographs of Test







Report No. : E1/2014/70052
Page : 21 of 30

### **RE Testing Set-up**


Below 1GHz





Report No. : E1/2014/70052
Page : 22 of 30

#### **Above 1GHz**







Report No. : E1/2014/70052
Page : 23 of 30

## 4. Photographs of Product

Exterior 32G







Report No. : E1/2014/70052
Page : 24 of 30



8G



Report No. : E1/2014/70052
Page : 25 of 30






Report No. : E1/2014/70052
Page : 26 of 30

16G







Report No. : E1/2014/70052
Page : 27 of 30




Report No. : E1/2014/70052
Page : 28 of 30


#### **Interior**







Report No. : E1/2014/70052
Page : 29 of 30





Report No. : E1/2014/70052
Page : 30 of 30





\*\* End of Report \*\*