

Appendix A. Test Photos

Report No.: FR3O3047

SPORTON INTERNATIONAL INC. Page No. : A1 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01



1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



Page No.

Report Version

: A2 of A8

: Rev. 01

REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456





SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01




2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A4 of A8 TEL: 886-3-327-3456 Report Version : Rev. 01



For radiated emissions 30MHz~1GHz



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A8
Report Version : Rev. 01



For radiated emissions 3GHz to 5GHz



FRONT VIEW




REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A6 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01



For radiated emissions above 1 GHz to 18 GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A7 of A8
Report Version : Rev. 01





Toshiba Corporation

Model: TJM35420LT

MADE IN CHINA

Report No.: FR3O3047

EUT take a close-up

SPORTON INTERNATIONAL INC. Page No. : A8 of A8
TEL: 886-3-327-3456 Report Version : Rev. 01