Appendix A. Test Photos


REPORT NO.: FC401804

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01



1.1. Photographs of Conducted Power line Test Configuration

• The photographs show the configuration that generates the maximum emission.



REPORT NO.: FC401804

FRONT VIEW

REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01



REPORT NO. : FC4O1804



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

CC EMC TEST REPORT REPORT NO. : FC401804

2 Photographs of Radiated Emissions Test Configuration
 The photographs show the configuration that generates the maximum emission.

For radiated emissions (Below 1GHz)



FRONT VIEW

REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A4 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC EMC TEST REPORT

REPORT NO.: FC401804

For radiated emissions (Above 1GHz)



FRONT VIEW

REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01