


Report No.: FR792901-03B


Appendix C. Setup Photographs

<Radiated Emission>

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID : ZW9AXCY1

Page Number : C1 of C2 Report Issued Date : Feb. 23, 2018 Report Version : Rev. 01 Report Template No.: BU5-FR15CWL Version 2.0



RF Test Report No.: FR792901-03B

Near View



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : C2 of C2
Report Issued Date : Feb. 23, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0