


Appendix C. Setup Photographs

<Radiated Emission> For 802.11n HT40

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : C1 of C2
Report Issued Date : Jun. 22, 2018
Report Version : Rev. 01

Report No.: FR852902D

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5



CC Test Report No.: FR852902D

Near View



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : C2 of C2
Report Issued Date : Jun. 22, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5