Appendix A. Setup Photographs


<Radiated Emission>

Z Plane for 22H

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : A1 of A3
Report Issued Date : Sep. 03, 2014
Report Version : Rev. 01

Report No.: FG460901A




Y Plane for 24E

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : A2 of A3
Report Issued Date : Sep. 03, 2014
Report Version : Rev. 01


Report No.: FG460901A

X Plane for 27L

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : A3 of A3
Report Issued Date : Sep. 03, 2014
Report Version : Rev. 01