

Report No.: FR792901C


## Appendix D. Setup Photographs

## <Radiated Emission>

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1

: D1 of D2 Page Number Report Issued Date : Jan. 17, 2018 : Rev. 01 Report Version

Report Template No.: BU5-FR15EWL MA Version 2.0





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1

Page Number : D2 of D2 Report Issued Date : Jan. 17, 2018 Report Version : Rev. 01

Report No. : FR792901C

Report Template No.: BU5-FR15EWL MA Version 2.0