



Appendix D. Setup Photographs

<Radiated Emission>

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : D1 of D2
Report Issued Date : Jan. 17, 2018
Report Version : Rev. 01


Report No.: FR792901A

Report Template No.: BU5-FR15CBT4.2 Version 2.0



FCC RF Test Report

Near View



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: ZW9AXCY1 Page Number : D2 of D2
Report Issued Date : Jan. 17, 2018
Report Version : Rev. 01

Report No.: FR792901A

Report Template No.: BU5-FR15CBT4.2 Version 2.0