



Report No. : FA460901


Appendix D. SAR Test Setup Photos






Right Cheek

Right Tilted





Left Cheek

Left Tilted

SPORTON INTERNATIONAL (SHENZHEN) INC. TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

FCC ID: ZW9HSTNH-B406M

Page D1 of D2

Issued Date : Sep. 03, 2014

Form version. : 140820





Report No. : FA460901

Front of the DUT with Phantom 1 cm Gap


Back of the DUT with Phantom 1 cm Gap



Left side of the DUT with Phantom 1 cm Gap



Bottom side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 0 cm Gap (Extremity SAR)

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 / FAX: 86-755-8637-9595

FCC ID: ZW9HSTNH-B406M

Page D2 of D2

Issued Date : Sep. 03, 2014

Form version. : 140820