

## 3. Internal Photograph of EUT


Brand Name: HP; Model Name: HSTNH-B406M

Report No.: EP460901



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 22 of 40
Report Issued Date : Sep. 03, 2014






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 23 of 40
Report Issued Date : Sep. 03, 2014
Report Version : Rev. 01

Report No.: EP460901


Brand Name: HP; Model Name: HSTNH-B406M



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 24 of 40
Report Issued Date : Sep. 03, 2014




Report No.: EP460901




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 25 of 40 Report Issued Date: Sep. 03, 2014 Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 26 of 40 Report Issued Date : Sep. 03, 2014







TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 27 of 40 Report Issued Date : Sep. 03, 2014


: Rev. 01


Report Version







TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 28 of 40
Report Issued Date : Sep. 03, 2014





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 29 of 40
Report Issued Date : Sep. 03, 2014






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 30 of 40 Report Issued Date : Sep. 03, 2014




Report No.: EP460901



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 31 of 40 Report Issued Date: Sep. 03, 2014




Report No.: EP460901



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 32 of 40 Report Issued Date: Sep. 03, 2014

Report No.: EP460901



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 33 of 40
Report Issued Date : Sep. 03, 2014
Report Version : Rev. 01

Report No.: EP460901




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 34 of 40
Report Issued Date : Sep. 03, 2014

Report No.: EP460901




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 35 of 40
Report Issued Date : Sep. 03, 2014

Report No.: EP460901




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 36 of 40
Report Issued Date : Sep. 03, 2014
Report Version : Rev. 01

Report No.: EP460901



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 37 of 40
Report Issued Date : Sep. 03, 2014

Report No.: EP460901




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 38 of 40 Report Issued Date : Sep. 03, 2014

: Rev. 01

Report Version

Report No.: EP460901




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 39 of 40

Report Issued Date : Sep. 03, 2014



Report No.: EP460901



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: ZW9HSTNH-B406M Page Number : 40 of 40 Report Issued Date : Sep. 03, 2014