

Figure 1: Internal Photo of MiSeq System – Installed RFID #1 (PCB)

Report Number: 31161819.002 EUT: MiSeq System Model: MiSeq System

EMC / Rev 9/6/2011




Figure 2: Internal Photo of MiSeq System – Installed RFID #1 (Loop antenna)

EUT: MiSeq System Model: MiSeq System

EMC / Rev 9/6/2011




Figure 3: Internal Photo of MiSeq System – RFID #2 (Component Side)

EUT: MiSeq System Model: MiSeq System

EMC / Rev 9/6/2011




Figure 4: Internal Photo of MiSeq System – RFID #2 (Soldered Side)

EUT: MiSeq System Model: MiSeq System

EMC / Rev 9/6/2011




Figure 5: Internal Photo of MiSeq System –Installed RFID #2 (Chiller)

Report Number: 31161819.002 EUT: MiSeq System Model: MiSeq System

EMC / Rev 9/6/2011




Figure 6: Internal Photo of MiSeq System – RFID #3 (PR2), Component Side

EUT: MiSeq System Model: MiSeq System

EMC / Rev 9/6/2011




Figure 7: Internal Photo of MiSeq System – RFID #3 (PR2), Soldered Side

EUT: MiSeq System Model: MiSeq System

EMC / Rev 9/6/2011




Figure 8: Internal Photo of MiSeq System – Installed RFID #3 (PR2).

Report Number: 31161819.002 EUT: MiSeq System Model: MiSeq System

EMC / Rev 9/6/2011