
INTERTEK TESTING SERVICES

Report No.: HK12030691-1

Sample No.: 1/1



Timing Plot – Pursuant to FCC Part 15 Section 231(a) Requirement

(Pass/Fail)

Code: FCC15C_f / Effective Date: 24 Jun 2011