


SPORTON LAB. Report No.: FR180348

## **Appendix A. Test Photos**

Radiated Emissions 30 MHz - 1GHz, EUT Setups: Setup\_01



Radiated Emissions 30 MHz - 1GHz, EUT Setups: Setup\_02



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 1 of 2

Report Version : Rev. 01



SPORTON LAB. Report No.: FR180348

## Radiated Emissions 1 GHz - 40GHz, EUT Setups: Setup\_01



Radiated Emissions 1 GHz - 40GHz, EUT Setups: Setup\_02



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255