Test report No.

: 32IE0158-HO-01-B

Page Issued date IC Number : 17 of 18

: July 24, 2012 : 9889A-SX10WAGIT

## **APPENDIX 3: Photographs of test setup**

## **Radiated Spurious Emission**




Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No.

: 32IE0158-HO-01-B

Page

: 18 of 18 : July 24, 2012


Issued date IC Number


: 9889A-SX10WAGIT


## **Worst Case Position**

(Module Horizontal: Y-axis/ Vertical: X-axis) (Antenna Horizontal: Y-axis/ Vertical: Y-axis)


Module








**Z**-axis



Antenna


X-axis



Y-axis



**Z**-axis



**End of Report** 

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone Facsimile

: +81 596 24 8116 : +81 596 24 8124