
	4	3	2	1		
Rev	1	Description		Date	Drawn	Appd.
		CE alert mark added. ECO		16.11.11	rwe	AC
3.0	CE Alert mark remov	ed. FCC ID is now ZYH-W2	2CBW003	04.12.11	rwe	AC



This is not an artwork.
To make this label, use Zebra S4M printer, 5095 ribbon & file containing artwork and printer settings:

4105731_30 Type plate 1 USA.lbl

YLEISTOLERANSSI TOLERANCES		MATERIAL 4105 716	SUUNN. DESIGNED PIRT. DRAWN RWE 3.10.2011 RWE 3.10.20	11
	SUHDE SCALE 1:1	Country Sets	TARK. CHECKED HYV. APPROVED AC 4.10.201	1
			TUOTE PRODUCT X-Met 7x00	
INSTRUMENTS		Type Plate 1 Artwork X-Met 7x00 USA	$\begin{array}{c c} \text{OSAL.N:O PART LIST} & \text{Rev.} \\ \textbf{3.0} \end{array}$	
			4105 731	

3

D