

Page : 1 of 3

Issued date : Jan. 31, 2020

FCC ID : ZZ6-WUBT-236ACN

Radiated Spurious Emission Setup Configurations

Above 1GHz





Underwriters Laboratories Taiwan Co., Ltd.Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948





Page : 2 of 3

Issued date : Jan. 31, 2020

FCC ID : ZZ6-WUBT-236ACN

Below 1GHz





Underwriters Laboratories Taiwan Co., Ltd.
Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948




Page : 3 of 3

Issued date : Jan. 31, 2020

FCC ID : ZZ6-WUBT-236ACN

9kHz ~ 30MHz





Underwriters Laboratories Taiwan Co., Ltd.
Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948