


Appendix B

Date: 2018-06-20

FCC Report Number: 60.790.18.021.01, ISED Report Number: 60.960.18.024.01

Model No.(HVIN): PX102





Page 1 of 3 TÜV SÜD Hong Kong Ltd.




Appendix B

Date: 2018-06-20

FCC Report Number: 60.790.18.021.01, ISED Report Number: 60.960.18.024.01

Model No.: PX102





Page 2 of 3
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Appendix B

Date: 2018-06-20

FCC Report Number: 60.790.18.021.01, ISED Report Number: 60.960.18.024.01

Model No.: PX102





Page 3 of 3 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong