


Date: 2018-06-20

FCC Report Number: 60.790.18.021.01, ISED Report Number: 60.960.18.024.01

Model No.(HVIN): PX102





Page 1 of 4 TÜV SÜD Hong Kong Ltd.


3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong




Date: 2018-06-20

FCC Report Number: 60.790.18.021.01, ISED Report Number: 60.960.18.024.01

Model No.(HVIN):PX102





Page 2 of 4 TÜV SÜD Hong Kong Ltd.


3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong




Date: 2018-06-20

FCC Report Number: 60.790.18.021.01, ISED Report Number: 60.960.18.024.01

Model No.(HVIN):PX102



BLE and ANT+ Antenna 2402-2480MHz



Page 3 of 4
TÜV SÜD Hong Kong Ltd.
3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-06-20

FCC Report Number: 60.790.18.021.01, ISED Report Number: 60.960.18.024.01

Model No.(HVIN):PX102

