

AIRCRAFT MAINTENANCE MANUAL

TABLE OF CONTENTS


<u>PAGEBLOCK TASK</u>	<u>REVISION STATUS</u>	<u>REVISION DATE</u>
09-10-00/200 TOWING - MAINTENANCE PRACTICES	U	Oct 30/15
09-10-00-500-801-A AIRCRAFT TOWING	U	Oct 31/17
09-10-01/200 CONFIG-1 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> TOWBARLESS TOWING - MAINTENANCE PRACTICES	U	Apr 28/17
09-10-01-500-801-A CONFIG-1 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> AIRCRAFT TOWING WITH DOUGLAS TBL-50 VEHICLE	U	Oct 30/15
09-10-01-500-802-A CONFIG-1 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> AIRCRAFT TOWING WITH LEKTRO AP8750B-AL VEHICLE	U	Oct 30/15
09-10-01-500-803-A CONFIG-1 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> AIRCRAFT TOWING WITH TLD TPX-100E VEHICLE	U	Oct 30/15
09-10-01-500-804-A CONFIG-1 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> AIRCRAFT TOWING WITH LEKTRO AP8850SDA-AL-100/50 VEHICLE	U	Oct 30/15
09-10-01-500-805-A CONFIG-1 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> AIRCRAFT TOWING WITH GOLDSCHAFER AST-3 VEHICLE	U	Oct 30/15
09-10-01-500-806-A CONFIG-1 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> AIRCRAFT TOWING WITH LEKTRO 8925 OR 8950 VEHICLE	U	Apr 28/17
09-10-01-500-807-A CONFIG-1 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> AIRCRAFT TOWING WITH TRONAIR JP100 VEHICLE	U	Apr 28/17
09-10-01/200 CONFIG-2 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> TOWBARLESS TOWING - MAINTENANCE PRACTICES	U	Apr 28/17
09-10-01-500-801-A CONFIG-2 <i>EFFECTIVITY: POST-MOD. S.B.145-32-0102</i> AIRCRAFT TOWING WITH DOUGLAS TBL-50 VEHICLE	U	Oct 30/15

Revision Status: U - Unchanged, R - Revised, N - New, D - Deleted

EMB-145 - AMM 1285

TOC

Chapter 09
Page 1 of 2
Rev 55 - Oct 29/18



EMB145 - EMB135

AIRCRAFT
MAINTENANCE MANUAL

PAGEBLOCK TASK	REVISION STATUS	REVISION DATE
09-10-01-500-802-A CONFIG-2 <i>EFFECTIVITY: POST-MOD. S.B. 145-32-0102</i> AIRCRAFT TOWING WITH LEKTRO AP8750B-AL VEHICLE	U	Oct 30/15
09-10-01-500-803-A CONFIG-2 <i>EFFECTIVITY: POST-MOD. S.B. 145-32-0102</i> AIRCRAFT TOWING WITH TLD TPX-100E VEHICLE	U	Oct 30/15
09-10-01-500-804-A CONFIG-2 <i>EFFECTIVITY: POST-MOD. S.B. 145-32-0102</i> AIRCRAFT TOWING WITH LEKTRO AP8850SDA-AL-100/50 VEHICLE	U	Oct 30/15
09-10-01-500-805-A CONFIG-2 <i>EFFECTIVITY: POST-MOD. S.B. 145-32-0102</i> AIRCRAFT TOWING WITH GOLDHOFER AST-3 VEHICLE	U	Oct 30/15
09-10-01-500-806-A CONFIG-2 <i>EFFECTIVITY: POST-MOD. S.B. 145-32-0102</i> AIRCRAFT TOWING WITH LEKTRO 8925 OR 8950 VEHICLE	U	Apr 28/17
09-10-01-500-807-A CONFIG-2 <i>EFFECTIVITY: POST-MOD. S.B. 145-32-0102</i> AIRCRAFT TOWING WITH TRONAIR JP100 VEHICLE	U	Apr 28/17
09-20-00/200 CONFIG-1 <i>EFFECTIVITY: ACFT MODEL(S) EMB-145</i> TAXIING - MAINTENANCE PRACTICES	U	Oct 30/15
09-20-00-500-801-A CONFIG-1 <i>EFFECTIVITY: ACFT MODEL(S) EMB-145</i> AIRCRAFT TAXIING	U	Oct 30/15
09-20-00/200 CONFIG-2 <i>EFFECTIVITY: ACFT MODEL(S) EMB-135</i> TAXIING - MAINTENANCE PRACTICES	U	Oct 30/15
09-20-00-500-801-A CONFIG-2 <i>EFFECTIVITY: ACFT MODEL(S) EMB-135</i> AIRCRAFT TAXIING	U	Oct 30/15

Revision Status: U - Unchanged, R - Revised, N - New, D - Deleted

EMB-145 - AMM 1285

TOC

Chapter 09
Page 2 of 2
Rev 55 - Oct 29/18