

HIGHLIGHTS

The table below lists the contents that have been technically revised in the current revision of this manual. Other revised contents, if any, that do not appear in the table below are considered editorially revised, they having no technical implications.

SUBJECT	DESCRIPTION
PAGE BLOCK 05-30-12/600	Deleted item that was causing confusion to the operator.
TASK 05-50-26-200-802-A/600	Improved steps of Mechanical/Electromechanical Gust Lock Inspection
TASK 05-50-28-200-801-A/600	Updated scenario on General topic.
PAGE BLOCK 20-30-02/200	Added oil (Radcolube NLT) as alternative on Table 203
	Added GN148 as alternative on Table 205
PAGE BLOCK 20-30-03/200	Revised table to add alternative product
PAGE BLOCK 20-30-04/200	Changed the information of SPEC AMS 1526C according to vendors request (PCR 162897)
PAGE BLOCK 20-30-05/200	Added alternative
	Revised table to include procedure
	Included alternative consumable
TASK 21-00-00-860-801-A/200	Updated procedure related to cooling packs status.
TASK 21-00-00-860-803-A/200	Updated procedure related to cooling packs status.
TASK 21-00-00-860-804-A/200	Updated procedure related to cooling packs status.
TASK 21-20-00-700-801-A/500	Updated procedure for PASS CABIN temperature selector in manual position.
TASK 21-51-02-000-801-A/400	Updated task
TASK 21-51-02-400-801-A/400	Updated task
TASK 21-51-03-000-801-A/400	Revised figure.
TASK 21-51-03-400-801-A/400	Updated installation instructions.
TASK 21-51-03-210-801-A/600	Updated instructions on follow-on.
TASK 21-51-04-000-801-A/400	Revised Figure 402.
	Revised figure.
	Editorial update on removal instructions.

SUBJECT	DESCRIPTION
TASK 21-51-04-400-801-A/400	Updated procedure to show replacement of the cap, fitting and O'ring if applicable to the aircraft configuration.
	Updated clamps installation.
	Updated Preparation topic.
	Added instructions to check and adjust the rod assemblies.
	Editorial update on installation instructions.
TASK 21-60-00-700-801-A/500	Updated procedure for CKPT and PASS CABIN temperature selector in manual position.
TASK 26-21-02-700-802-A/500	EFFECTIVITY: Removed reference to CMM
TASK 26-21-02-200-801-A/600	Removed the description related the pressure indication which is related the charging. Data plate must be followed.
TASK 26-22-01-200-801-A/600	Removed the description related the pressure indication which is related the charging. Data plate must be followed.
TASK 27-11-00-200-801-A/600	Typo Correction
TASK 27-12-03-040-801-A/400	Included step to install rigging pin before removal of aileron damper, and editorial correction
TASK 27-12-03-440-801-A/400	Included step to remove rigging pin after installation of aileron damper, and editorial correction
TASK 27-21-01-200-803-A/600	Typo correction
TASK 27-25-00-700-801-A/500	Included a reference to the FIM TASK 27-22-00/301 in case of problems during the test
TASK 27-40-00-700-802-A/500	Included information to energize the aircraft using APU
TASK 27-40-02-600-801-A/300	EFFECTIVITY: Added oil (Radcolube NLT) as alternative
TASK 27-51-01-700-801-A/500	Editorial correction in Access section replacing RH by LH in zone 5721
TASK 27-51-15-000-801-A/400	Included WARNING related to corrosion-inhibiting compound
TASK 27-51-15-400-801-A/400	Included step to apply corrosion-inhibiting compound to the roller

SUBJECT	DESCRIPTION
TASK 28-11-00-700-805-A/500	EFFECTIVITY: All Revised the text of the table
TASK 31-31-00-700-801-A/500	EFFECTIVITY: Added setup procedure for GSE 475
TASK 31-31-00-700-804-A/500	Added setup procedure for GSE 475 Updated the base test of Aircraft Type parameter from decimal to binary Updated the parameter name for the test of Aircraft Serial Number, from Aircraft Type to Aircraft Serial Number
TASK 32-10-01-400-801-A/400	Delete step (20) Revise Figure reference and editorial changes Delete step (20) Revise Figure reference and editorial changes
TASK 32-10-03-400-801-A/400	Included instruction to remove/install articulation nut
TASK 32-10-07-400-801-A/400	Included information about torque for screws of the MLG door
TASK 32-34-03-000-801-A/400	Included information to remove the teleflex-cable
TASK 32-34-03-400-801-A/400	Included information to install the teleflex-cable
TASK 32-49-02-400-801-A/400	Revised the range of torque wrench
TASK 33-50-00-700-801-A/500	Removed step to do the functional test
TASK 35-11-02-700-801-A/500	Updated procedure. Updated procedure.
TASK 36-11-05-040-801-A/400	EFFECTIVITY: Updated procedure to remove an unnecessary step
TASK 36-12-03-000-803-A/400	Added step to clean the filter
TASK 36-12-03-400-803-A/400	Updated the consumable list
PAGE BLOCK 36-12-03/700	Added Pageblock: SERVO CONTROLLED BLEED AIR VALVE - CLEANING/PAINTING
TASK 36-12-03-130-801-A/700	Added Task: APU-BLEED VALVE FILTER - CLEANING
SUBJECT 38-32-09	Added Subject: TOILET-UNIT MOTOR PUMP FILTER

SUBJECT	DESCRIPTION
PAGE BLOCK 38-32-09/400	Added Pageblock: TOILET-UNIT MOTOR PUMP FILTER - REMOVAL/INSTALLATION
TASK 38-32-09-000-801-A/400	Added Task: Toilet-Unit Motor Pump Filter
TASK 38-32-09-400-801-A/400	Added Task: Toilet-Unit Motor Pump Filter
TASK 45-45-00-970-801-A/200	EFFECTIVITY: Updated the effectivity in step to push the JSTK button
TASK 49-14-01-400-801-A/400	Included step to synchronize the controller and DMM.
TASK 51-21-03-100-801-A/700	Changed consumable materials information according to the vendor request (PCR 162897)
TASK 53-12-01-000-801-A/400	Updated illustration.
TASK 53-12-01-400-801-A/400	Updated illustration.
TASK 53-12-02-000-801-A/400	Updated illustration.
TASK 53-12-02-400-801-A/400	Updated illustration.
TASK 55-22-02-400-001-A/400	Deleted Task
TASK 55-22-02-400-801-A/400	Added Task: ELEVATOR SPRING AND SERVO-TAB FABRIC COVER - INSTALLATION
TASK 56-10-01-300-801-A/800	Revised to remove sealant Part Number AC-251
TASK 56-20-01-400-801-A/400	EFFECTIVITY: Updated the procedure to remove the restriction for maximum and minimum contour deviation
TASK 71-20-00-400-801-A/400	Removed duplicated step