


Primero hacer una lista de los sensores y el rango de pines que utiliza

Después, desglosar por cada componente los números de los pines y su función



NA	—	40
NA	—	39
NA	—	38
NA	—	37
NA	—	36
NA	—	35
NA	—	34
NA	—	33
NA	—	32
C4	—	31
C3	—	30
C2	—	29
C1	—	28
F4	—	27
F3	—	26
F2	—	25
F1	—	24
SW4	—	23
SW3	—	22
SW2	—	21
SW1	—	20
L5	—	19
L4	—	18
L3	—	17
L2	—	16
L1	—	15
SCL	—	14
SDA	—	13
DI	—	12
DO	—	11
AO	—	10
DO	—	9
DO	—	8
AO	—	7
SDA	—	6
SCK	—	5
MOSI	—	4
MISO	—	3
IRQ	—	2
RST	—	1