

92 Broad Street, Chesham, Bucks. Telephone: (02405) 75151. Telex: 837571

AMENDMENT TO NASBUG MONITOR PROGRAMME

As from July 10th 1978 all MM2708 EPROMs being supplied with NASCOM 1 kits contain a modified monitor programme - "NASBUG 1.T2"

The following modifications should be made to the NASCOM 1 Software Notes.

Page No

Details

"PART 17, SECTION C: NASEUG MONITOR LISTING"

60

Delete: Lines 0042 and 0048

Insert: Two Lines as follows:-

CO42 DB O2 17 30 F7 IN A, (O2); RLA; JRNC - O7;

0047 DB 01 C9

IN A, (O1); RET

(This change to 5 bytes vastly reduces the cassette

load error rate).

62

Delete: Contents of locations 0109 (Bl.)

and 010B (B9)

2

Insert: A9 at location 0109 and

Al at location OlOB.

(These two changes in the keyboard look-up table relocate the left and right handed prompt symbols as shifted comma and full stop respectively).

77

Delete: Left and right prompt symbols over keys M & N

Insert: Left and right prompt symbols over the comma

and full stop keys respectively.

JULY 1978

P. A. GREENHALGH

P.A. Greadalph