```
void loop() {
// loop through all 11 pins
for (byte pin=0; pin<=7; pin++)
  selectMuxPinl(pin): // Select one at a time from muxl
  int inputValuel = analogRead(Al); // read zl
  int hitBarl = checkSensor(inputValuel, pin);
  secfpin1 = hitBarl:
for (byte pin=0; pin<=7; pin++)
  selectMuxPin2(pin); // Select one at a time from mux2
  int inputValue2 = analogRead(A2); // read z2
  int hitBar2 = checkSensor(inputValue2, pin);
  seq[pin+7] = hitBar2;
hasInput = checkInput(seq);
if (hasInput == 1) {
  for (int j=0; j<16; j++)
    Serial.print(seg[i]):
  Serial.println():
 delay(300):
```