




Channel content, not driver input: scripted automation content continues across the switch; driver brake onset and strength are not identifiable.