





Half A



5. Keep sharp edges K.
- 6.*Reference only dimensions
- 7.H14,h14,IT14/2.
- 8.Hardness after welding HRC35-40.

Mark ordinal number ($h=10$) & PSI logo.
Depth of marking-0.2...0.3 mm.



210.11.11.2	ASSEMBLY NUMBER/ HONEY EXPOSURE	14	MATERIAL CAST IRON (GG500)	INDICATE PARTIAL QUANTITY CLASS-88-10-5'-6"	JOB TITLE/MACHINE PHOTO VT-280	SCALE 1:1
180.11.11.1	INTERIOR CENTER DIAMETER	68	ALL edges (HRC 35..40)	DESIGNED/ DRAWN:		
180.11.11.1	IF DIMENSION PLACEMENT	54	QUANTITY/ DIRECTION	DATE/ DATE	553-BLK1-2	1:1
180.11.11.1	REVISIONS/DESCRIPTION					
180.11.11.1	PLACEMENT					