

Date printed:

|            |               |      |          | Batch | n Record |
|------------|---------------|------|----------|-------|----------|
|            | Machine name: | ZLAB |          |       |          |
|            | Batch:        | 169  |          |       |          |
| 06/07/2021 | Time printed: |      | 16:04:27 | Page  | 1/4      |

## Alarm List

| Machine Number: | 900X905020   |
|-----------------|--------------|
| Operator:       | Operater     |
| Product:        | pq070621for1 |
|                 |              |
| Date printed:   | 06/07/2021   |
| Time printed:   | 16:04:27     |

| Date / Name / Signature |  |
|-------------------------|--|
|                         |  |



Date printed:

|            |               |          |   | Batch | Record |
|------------|---------------|----------|---|-------|--------|
|            | Machine name: | ZLAB     |   |       |        |
|            | Batch:        | 169      |   |       |        |
| 06/07/2021 | Time printed: | 16:04:27 | F | Page  | 2/4    |

|      |            |          | <u>'</u> |                 | Old value   | New value      |
|------|------------|----------|----------|-----------------|-------------|----------------|
| Туре | Date       | Time     | Operator | No. Description | Info 1      | Info 2         |
| AT   | 06/07/2021 | 15:42:25 | Operater | 3081            | pg070621for | 1 pg070621for1 |

## Alarm List

| Machine Number: | 900X905020   |
|-----------------|--------------|
| Operator:       | Operater     |
| Product:        | pq070621for1 |
|                 |              |
| Date printed:   | 06/07/2021   |
| Time printed:   | 16:04:27     |

| Data (Nama (Olamatana   |  |
|-------------------------|--|
| Date / Name / Signature |  |



Machine name: ZLAB

Batch: 169

| Date printed: 06/07/2021 | Time printed: 16:04:27 | Page 3 / 4

**Batch Record** 

|               |            |          |          |      |                              | Old value     | New value     |
|---------------|------------|----------|----------|------|------------------------------|---------------|---------------|
| Туре          | Date       | Time     | Operator | No.  | Description                  | Info 1        | Info 2        |
| €3            | 06/07/2021 | 15:42:22 | Operater | 1009 | Door and window open alarm   |               |               |
| <b>©</b>      | 06/07/2021 | 15:42:22 | Operater | 1009 | Insufficient vacuum pressure |               |               |
| Ö             | 06/07/2021 | 15:42:22 | Operater | 103  | Batch not set                |               |               |
| AT            | 06/07/2021 | 15:43:07 | Operater | 303  | Create batch                 | 444           | pq07062021no1 |
| AT            | 06/07/2021 | 15:47:07 | Operater | 303  | active reset button          |               |               |
| €3            | 06/07/2021 | 15:47:07 | Operater | 1009 | Door and window open alarm   |               |               |
|               | 06/07/2021 | 15:47:07 | Operater | 1033 | Batch not set                |               |               |
| <b>8</b><br>8 | 06/07/2021 | 15:47:07 | Operater | 1009 | Door and window open alarm   |               |               |
| AT            | 06/07/2021 | 15:47:08 | Operater | 303  | active reset button          |               |               |
| <b>(3)</b>    | 06/07/2021 | 15:47:08 | Operater | 100  | Inverter fault               |               |               |
| €3            | 06/07/2021 | 15:47:08 | Operater | 1033 | Batch not set                |               |               |
| <b>(3)</b>    | 06/07/2021 | 15:47:08 | Operater | 100  | Inverter fault               |               |               |
| AT            | 06/07/2021 | 15:47:08 | Operater | 303  | active reset button          |               |               |
| <b>3</b>      | 06/07/2021 | 15:47:08 | Operater | 1033 | Batch not set                |               |               |
| €3            | 06/07/2021 | 15:47:08 | Operater | 100  | Inverter fault               |               |               |
| €3            | 06/07/2021 | 15:47:08 | Operater | 1033 | Batch not set                |               |               |
| AT            | 06/07/2021 | 15:47:08 | Operater | 303  | active reset button          |               |               |
| €3            | 06/07/2021 | 15:47:08 | Operater | 100  | Inverter fault               |               |               |
| €3            | 06/07/2021 | 15:47:08 | Operater | 103  | Batch not set                |               |               |
| AT            | 06/07/2021 | 15:47:09 | Operater | 303  | active reset button          |               |               |
| €3            | 06/07/2021 | 15:47:09 | Operater | 100  | Inverter fault               |               |               |
| <b>83</b>     | 06/07/2021 | 15:47:09 | Operater | 1033 | Batch not set                |               |               |
| AT            | 06/07/2021 | 15:47:16 | Operater | 303  | Create batch                 | pq07062021no1 | 169           |
| AT            | 06/07/2021 | 15:47:29 | Operater | 303  | active start button          |               |               |
| AT            | 06/07/2021 | 15:47:30 | Operater | 303  | active reset button          |               |               |
| AT            | 06/07/2021 | 15:47:30 | Operater | 303  | active reset button          |               |               |
| AT            | 06/07/2021 | 15:47:31 | Operater | 303  | active reset button          |               |               |
| AT            | 06/07/2021 | 15:47:31 | Operater | 303  | active start button          |               |               |
| AT            | 06/07/2021 | 15:49:00 | Operater | 3036 | active stop button           |               |               |
| AT            | 06/07/2021 | 15:49:23 | Operater | 303  | active reset button          |               |               |
| AT            | 06/07/2021 | 15:49:23 | Operater | 303  | active reset button          |               |               |



Machine name: ZLAB

Batch: 169

| Date printed: 06/07/2021 | Time printed: 16:04:27 | Page 4 / 4

**Batch Record** 

|      |            |          |          |      |                              |  | Old value | New value |
|------|------------|----------|----------|------|------------------------------|--|-----------|-----------|
| Туре | Date       | Time     | Operator | No.  | Description                  |  | Info 1    | Info 2    |
| AT   | 06/07/2021 | 15:49:23 | Operater | 303  | active reset button          |  |           |           |
| AT   | 06/07/2021 | 15:49:24 | Operater | 303  | active start button          |  |           |           |
| €3   | 06/07/2021 | 15:50:24 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |
| €3   | 06/07/2021 | 16:00:47 | Operater | 1009 | Door and window open alarm   |  |           |           |
| ₿    | 06/07/2021 | 16:00:47 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |
| €3   | 06/07/2021 | 16:01:16 | Operater | 1003 | Hand wheel spin out alarm    |  |           |           |
| 8    | 06/07/2021 | 16:01:16 | Operater | 1009 | Door and window open alarm   |  |           |           |
| ₿    | 06/07/2021 | 16:01:16 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |
| ΑT   | 06/07/2021 | 16:04:22 | Operater | 303  | active reset button          |  |           |           |
| ₿    | 06/07/2021 | 16:04:22 | Operater | 1009 | Door and window open alarm   |  |           |           |
| 8    | 06/07/2021 | 16:04:22 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |
| 3    | 06/07/2021 | 16:04:22 | Operater | 1009 | Door and window open alarm   |  |           |           |
| ΑT   | 06/07/2021 | 16:04:22 | Operater | 303  | active reset button          |  |           |           |
| ₿ .  | 06/07/2021 | 16:04:22 | Operater | 100  | Inverter fault               |  |           |           |
| 8    | 06/07/2021 | 16:04:22 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |
| ₿ .  | 06/07/2021 | 16:04:22 | Operater | 100  | Inverter fault               |  |           |           |
| 8    | 06/07/2021 | 16:04:22 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |
| AT   | 06/07/2021 | 16:04:22 | Operater | 303  | active reset button          |  |           |           |
| 8    | 06/07/2021 | 16:04:23 | Operater | 100  | Inverter fault               |  |           |           |
| 3    | 06/07/2021 | 16:04:23 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |
| ΑT   | 06/07/2021 | 16:04:23 | Operater | 303  | active reset button          |  |           |           |
| 3    | 06/07/2021 | 16:04:23 | Operater | 100  | Inverter fault               |  |           |           |
| 8    | 06/07/2021 | 16:04:23 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |
| AT   | 06/07/2021 | 16:04:23 | Operater | 303  | active reset button          |  |           |           |
| €3   | 06/07/2021 | 16:04:23 | Operater | 100  | Inverter fault               |  |           |           |
| Ē.   | 06/07/2021 | 16:04:23 | Operater | 1009 | Insufficient vacuum pressure |  |           |           |