

Date printed:

			Batch	n Record
	Machine name:	ZLAB		
	Batch:	pq030621format3		
06/03/2021	Time printed:	17:22:40	Page	1 / 47

## **Alarm List**

Machine Number:	900X905020
Operator:	Operater
Product:	PQ030621FOR3
Date printed:	06/03/2021
Time printed:	17:22:40

Date / Name / Signature	



Date printed:

			Batc	h Record
	Machine name:	ZLAB		
	Batch:	pq030621format3		
06/03/2021	Time printed:	17:22:40	Page	2 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	15:11:43	Operater	7227	Operater	Administrator
AT	06/03/2021	15:11:47	Administrator	3081	Efditera_240_mg_pla	ac Efditera_240_mg_plac
AT	06/03/2021	17:16:47	Administrator	3082	PQ030621FOR3	PQ030621FOR3
AT	06/03/2021	17:16:54	Administrator	3081	PQ030621FOR3	PQ030621FOR3
AT	06/03/2021	17:21:09	Administrator	3081	1	1
AT	06/03/2021	17:21:12	Administrator	3081	PQ030621FOR3	PQ030621FOR3

## Alarm List

Machine Number:	900X905020
Operator:	Operater
Product:	PQ030621FOR3
Date printed:	06/03/2021
Time printed:	17:22:40

Date / Name / Signature	



Date printed:

Type Date Time Operator No. Description Info 1 Info 2



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 4 / 47

_			_				Old value	New value
Туре	Date	Time	Operator	No.	Description		Info 1	Info 2
8	06/03/2021	14:54:39	Operater	1003	Hand wheel spin out alarm			
€3	06/03/2021	14:54:39	Operater	100	Door and window open alarm	1		
€3	06/03/2021	14:54:40	Operater	1000	Air pressure alarm			
€3	06/03/2021	15:11:51	Administrator	100	Insufficient vacuum pressure			
€3	06/03/2021	15:12:22	Administrator	1010	Insufficient of empty capsules	3		
AT	06/03/2021	15:17:12	Administrator	303	7 active reset button			
€3	06/03/2021	15:17:12	Administrator	100	B Hand wheel spin out alarm			
₿	06/03/2021	15:17:12	Administrator	100	Door and window open alarm	1		
€3	06/03/2021	15:17:12	Administrator	100	Air pressure alarm			
₿	06/03/2021	15:17:12	Administrator	1009	Insufficient vacuum pressure			
€3	06/03/2021	15:17:12	Administrator	101	Insufficient of empty capsules	3		
AT	06/03/2021	15:17:12	Administrator	303	7 active reset button			
€3	06/03/2021	15:17:12	Administrator	100	B Hand wheel spin out alarm			
€3	06/03/2021	15:17:12	Administrator	100	5 Door and window open alarm	ı		
€3	06/03/2021	15:17:12	Administrator	100	Air pressure alarm			
₿	06/03/2021	15:17:12	Administrator	1009	Insufficient vacuum pressure			
AT	06/03/2021	15:17:12	Administrator	303	7 active reset button			
₿	06/03/2021	15:17:12	Administrator	101	Insufficient of empty capsules	3		
€3	06/03/2021	15:17:12	Administrator	100	B Hand wheel spin out alarm			
₿	06/03/2021	15:17:13	Administrator	100	5 Door and window open alarm	ı		
€3	06/03/2021	15:17:13	Administrator	100	Air pressure alarm			
AT	06/03/2021	15:17:13	Administrator	303	7 active reset button			
€3	06/03/2021	15:17:13	Administrator	1009	Insufficient vacuum pressure			
€3	06/03/2021	15:17:13	Administrator	101	Insufficient of empty capsules	3		
€3	06/03/2021	15:17:13	Administrator	100	B Hand wheel spin out alarm			
€3	06/03/2021	15:17:13	Administrator	100	5 Door and window open alarm	1		
€3	06/03/2021	15:17:13	Administrator	100	Air pressure alarm			
€3	06/03/2021	15:17:13	Administrator	1009	Insufficient vacuum pressure			
€3	06/03/2021	15:17:13	Administrator	101	Insufficient of empty capsules	3		
€3	06/03/2021	15:50:54	Administrator	100	3 Hand wheel spin out alarm			
€3	06/03/2021	15:50:54	Administrator	100	5 Door and window open alarm	1		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 5 / 47

						Old value	New value
Туре	Date	Time	Operator	No.	Description	Info 1	Info 2
€3	06/03/2021	15:50:55	Administrator	100	Air pressure alarm		
€3	06/03/2021	15:50:55	Administrator	100	Insufficient vacuum pressure		
€3	06/03/2021	15:50:55	Administrator	101	Insufficient of empty capsules		
€3	06/03/2021	15:50:55	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:06	Administrator	303	active reset button		
€3	06/03/2021	15:51:06	Administrator	100	Hand wheel spin out alarm		
8	06/03/2021	15:51:06	Administrator	100	Door and window open alarm		
8	06/03/2021	15:51:06	Administrator	100	Insufficient vacuum pressure		
₿	06/03/2021	15:51:06	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:06	Administrator	303	active reset button		
₿	06/03/2021	15:51:06	Administrator	100	Hand wheel spin out alarm		
8	06/03/2021	15:51:06	Administrator	100	Door and window open alarm		
3	06/03/2021	15:51:06	Administrator	100	Insufficient vacuum pressure		
ΑT	06/03/2021	15:51:06	Administrator	303	active reset button		
3	06/03/2021	15:51:06	Administrator	103	The point action button is connected		
8	06/03/2021	15:51:06	Administrator	100	Hand wheel spin out alarm		
8	06/03/2021	15:51:06	Administrator	100	Door and window open alarm		
<b>3</b>	06/03/2021	15:51:07	Administrator	100	Insufficient vacuum pressure		
AT	06/03/2021	15:51:07	Administrator	303	active reset button		
8	06/03/2021	15:51:07	Administrator	103	The point action button is connected		
8	06/03/2021	15:51:07	Administrator	100	Hand wheel spin out alarm		
8	06/03/2021	15:51:07	Administrator	100	Door and window open alarm		
₿ .	06/03/2021	15:51:07	Administrator	100	Insufficient vacuum pressure		
8	06/03/2021	15:51:07	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:07	Administrator	303	active reset button		
<b>83</b>	06/03/2021	15:51:07	Administrator	100	Hand wheel spin out alarm		
3	06/03/2021	15:51:07	Administrator	100	Door and window open alarm		
8	06/03/2021	15:51:08	Administrator	100	Insufficient vacuum pressure		
₿	06/03/2021	15:51:08	Administrator	103	The point action button is connected		
€3	06/03/2021	15:51:15	Administrator	100	Hand wheel spin out alarm		
<b>3</b>	06/03/2021	15:51:15	Administrator	100	Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 6 / 47

	_		_			Old value	New value
Гуре	Date	Time	Operator	No. Description	<u> </u>	Info 1	Info 2
8	06/03/2021	15:51:15	Administrator	1034 The point ac	ction button is connected		
3	06/03/2021	15:51:15	Administrator	1003 Hand wheel	spin out alarm		
*	06/03/2021	15:51:15	Administrator	1005 Door and wi	ndow open alarm		
3	06/03/2021	15:51:15	Administrator	1009 Insufficient v	vacuum pressure		
3	06/03/2021	15:51:15	Administrator	1034 The point ac	ction button is connected		
3	06/03/2021	15:51:16	Administrator	1003 Hand wheel	spin out alarm		
3	06/03/2021	15:51:16	Administrator	1005 Door and win	ndow open alarm		
3	06/03/2021	15:51:16	Administrator	1034 The point ac	ction button is connected		
AT.	06/03/2021	15:51:18	Administrator	3037 active reset	button		
3	06/03/2021	15:51:18	Administrator	1005 Door and wii	ndow open alarm		
3	06/03/2021	15:51:18	Administrator	1034 The point ac	ction button is connected		
7	06/03/2021	15:51:18	Administrator	3037 active reset	button		
3	06/03/2021	15:51:18	Administrator	1005 Door and win	ndow open alarm		
3	06/03/2021	15:51:18	Administrator	1034 The point ac	ction button is connected		
T	06/03/2021	15:51:19	Administrator	3037 active reset	button		
3	06/03/2021	15:51:19	Administrator	1005 Door and wii	ndow open alarm		
3	06/03/2021	15:51:19	Administrator	1034 The point ac	ction button is connected		
T	06/03/2021	15:51:19	Administrator	3034 active jog bu	utton		
T	06/03/2021	15:51:20	Administrator	3037 active reset	button		
3	06/03/2021	15:51:20	Administrator	1005 Door and wii	ndow open alarm		
3	06/03/2021	15:51:20	Administrator	1034 The point ac	ction button is connected		
VI.	06/03/2021	15:51:20	Administrator	3037 active reset	button		
3	06/03/2021	15:51:20	Administrator	1005 Door and wii	ndow open alarm		
3	06/03/2021	15:51:20	Administrator	1034 The point ac	ction button is connected		
Ī	06/03/2021	15:51:21	Administrator	3037 active reset	button		
3	06/03/2021	15:51:21	Administrator	1005 Door and wii	ndow open alarm		
3	06/03/2021	15:51:21	Administrator	1034 The point ac	ction button is connected		
Ī	06/03/2021	15:51:22	Administrator	3037 active reset	button		
3	06/03/2021	15:51:22	Administrator	1005 Door and wii	ndow open alarm		
3	06/03/2021	15:51:22	Administrator	1034 The point ac	ction button is connected		
<b>VI</b>	06/03/2021	15:51:23	Administrator	3037 active reset	button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 7 / 47

		_				Old value	New value
Туре	Date	Time	Operator	No.	Description	Info 1	Info 2
€3	06/03/2021	15:51:23	Administrator	100	Door and window open alarm		
€3	06/03/2021	15:51:23	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:30	Administrator	303	active reset button		
€3	06/03/2021	15:51:30	Administrator	100	Door and window open alarm		
€3	06/03/2021	15:51:31	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:31	Administrator	303	active reset button		
ጨ	06/03/2021	15:51:31	Administrator	100	Door and window open alarm		
€3	06/03/2021	15:51:31	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:43	Administrator	303	active reset button		
€3	06/03/2021	15:51:43	Administrator	100	Door and window open alarm		
₿	06/03/2021	15:51:43	Administrator	103	The point action button is connected		
€3_	06/03/2021	15:51:43	Administrator	100	Door and window open alarm		
€3	06/03/2021	15:51:44	Administrator	100	Inverter fault		
€3	06/03/2021	15:51:44	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:44	Administrator	303	active reset button		
€3	06/03/2021	15:51:44	Administrator	100	Door and window open alarm		
€3	06/03/2021	15:51:44	Administrator	100	Inverter fault		
₿_	06/03/2021	15:51:44	Administrator	103	The point action button is connected		
ΑT	06/03/2021	15:51:45	Administrator	303	active reset button		
₿_	06/03/2021	15:51:45	Administrator	100	Door and window open alarm		
₿	06/03/2021	15:51:45	Administrator	100	Inverter fault		
₿_	06/03/2021	15:51:45	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:46	Administrator	303	active reset button		
₿_	06/03/2021	15:51:46	Administrator	100	Door and window open alarm		
€3	06/03/2021	15:51:46	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:48	Administrator	303	active reset button		
₿	06/03/2021	15:51:48	Administrator	100	Door and window open alarm		
❸_	06/03/2021	15:51:48	Administrator	103	The point action button is connected		
AT	06/03/2021	15:51:48	Administrator	303	active reset button		
❷_	06/03/2021	15:51:48	Administrator	100	Door and window open alarm		
€	06/03/2021	15:51:48	Administrator	103	The point action button is connected		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 8 / 47

			I		Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	15:51:49	Administrator	3037 active reset button		
<b>3</b>	06/03/2021	15:51:49	Administrator	1005 Door and window open alarm		
Ö	06/03/2021	15:51:49	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:51:54	Administrator	3037 active reset button		
8	06/03/2021	15:51:54	Administrator	1005 Door and window open alarm		
Ö	06/03/2021	15:51:54	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:51:55	Administrator	3037 active reset button		
<b>≅</b>	06/03/2021	15:51:55	Administrator	1005 Door and window open alarm		
Ö	06/03/2021	15:51:55	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:51:56	Administrator	3037 active reset button		
<u>3</u>	06/03/2021	15:51:56	Administrator	1005 Door and window open alarm		
Ö	06/03/2021	15:51:56	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:51:57	Administrator	3037 active reset button		
€3	06/03/2021	15:51:57	Administrator	1005 Door and window open alarm		
<b>©</b>	06/03/2021	15:51:57	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:51:57	Administrator	3037 active reset button		
<b>3</b>	06/03/2021	15:51:57	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:51:57	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:51:58	Administrator	3037 active reset button		
<b>⋘</b>	06/03/2021	15:51:58	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:51:58	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:51:58	Administrator	3037 active reset button		
€3	06/03/2021	15:51:58	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:51:58	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:01	Administrator	3037 active reset button		
<b>⋘</b>	06/03/2021	15:52:01	Administrator	1005 Door and window open alarm		
8	06/03/2021	15:52:01	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:03	Administrator	3037 active reset button		
€3	06/03/2021	15:52:03	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:03	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:04	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 9 / 47

						Old value	New value
Гуре	Date	Time	Operator	No.	Description	Info 1	Info 2
8	06/03/2021	15:52:04	Administrator	100	Door and window open alarm		
Š	06/03/2021	15:52:04	Administrator	103	The point action button is connected		
N T	06/03/2021	15:52:15	Administrator	303	active reset button		
3	06/03/2021	15:52:15	Administrator	100	Door and window open alarm		
3	06/03/2021	15:52:15	Administrator	103	The point action button is connected		
3	06/03/2021	15:52:15	Administrator	100	Door and window open alarm		
3	06/03/2021	15:52:15	Administrator	100	Inverter fault		
3	06/03/2021	15:52:15	Administrator	103	The point action button is connected		
AT .	06/03/2021	15:52:16	Administrator	303	active reset button		
8	06/03/2021	15:52:16	Administrator	100	Door and window open alarm		
3	06/03/2021	15:52:16	Administrator	103	The point action button is connected		
<b>ΑT</b>	06/03/2021	15:52:17	Administrator	303	active reset button		
3	06/03/2021	15:52:17	Administrator	100	Door and window open alarm		
3	06/03/2021	15:52:17	Administrator	103	The point action button is connected		
7	06/03/2021	15:52:17	Administrator	303	active reset button		
*	06/03/2021	15:52:18	Administrator	100	Door and window open alarm		
3	06/03/2021	15:52:18	Administrator	103	The point action button is connected		
XI.	06/03/2021	15:52:18	Administrator	303	active reset button		
3	06/03/2021	15:52:18	Administrator	100	Door and window open alarm		
3	06/03/2021	15:52:18	Administrator	103	The point action button is connected		
ZI .	06/03/2021	15:52:19	Administrator	303	active reset button		
3	06/03/2021	15:52:19	Administrator	100	Door and window open alarm		
3	06/03/2021	15:52:19	Administrator	103	The point action button is connected		
<u> </u>	06/03/2021	15:52:19	Administrator	303	active reset button		
3	06/03/2021	15:52:19	Administrator	100	Door and window open alarm		
3_	06/03/2021	15:52:19	Administrator	103	The point action button is connected		
7	06/03/2021	15:52:20	Administrator	303	active reset button		
3	06/03/2021	15:52:20	Administrator	100	Door and window open alarm		
3	06/03/2021	15:52:20	Administrator	103	The point action button is connected		
<b>1</b>	06/03/2021	15:52:23	Administrator	303	active reset button		
3	06/03/2021	15:52:23	Administrator	100	Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 10 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
€3	06/03/2021	15:52:23	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:24	Administrator	3037 active reset button		
€3	06/03/2021	15:52:24	Administrator	1005 Door and window open alarm		
<b>©</b>	06/03/2021	15:52:24	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:24	Administrator	3037 active reset button		
€3	06/03/2021	15:52:24	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:24	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:25	Administrator	3037 active reset button		
€3	06/03/2021	15:52:25	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:25	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:25	Administrator	3037 active reset button		
€3	06/03/2021	15:52:25	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:25	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:26	Administrator	3037 active reset button		
8	06/03/2021	15:52:26	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:26	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:27	Administrator	3037 active reset button		
₿	06/03/2021	15:52:27	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:27	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:27	Administrator	3037 active reset button		
₿	06/03/2021	15:52:27	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:27	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:28	Administrator	3037 active reset button		
₿	06/03/2021	15:52:28	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:28	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:30	Administrator	3037 active reset button		
€3	06/03/2021	15:52:30	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:30	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:30	Administrator	3037 active reset button		
€3	06/03/2021	15:52:30	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:30	Administrator	1034 The point action button is connected		



Batch: pq030621format3

Date printed: 06/03/2021 Time printed: 17:22:40 Page 11 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	15:52:32	Administrator	3037 active reset button		
8	06/03/2021	15:52:32	Administrator	1005 Door and window open alarm		
<b>€</b>	06/03/2021	15:52:32	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:32	Administrator	3037 active reset button		
€3	06/03/2021	15:52:32	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:32	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:32	Administrator	3037 active reset button		
€3	06/03/2021	15:52:32	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:32	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:33	Administrator	3037 active reset button		
€3	06/03/2021	15:52:33	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:33	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:34	Administrator	3037 active reset button		
€3	06/03/2021	15:52:34	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:34	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:35	Administrator	3037 active reset button		
€3	06/03/2021	15:52:35	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:35	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:35	Administrator	3037 active reset button		
<b>3</b>	06/03/2021	15:52:35	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:35	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:36	Administrator	3037 active reset button		
€3	06/03/2021	15:52:36	Administrator	1005 Door and window open alarm		
<b>(3)</b>	06/03/2021	15:52:36	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:37	Administrator	3037 active reset button		
€3	06/03/2021	15:52:37	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:37	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:38	Administrator	3037 active reset button		
€3	06/03/2021	15:52:38	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:38	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:38	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 12 / 47

Type	Date	Time	Operator	No. Description	Old value Info 1	New value Info 2
Туре	Date	Tille	Operator	ivo. Description	IIIIO I	IIIIU Z
₿	06/03/2021	15:52:38	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:38	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:39	Administrator	3037 active reset button		
₿	06/03/2021	15:52:39	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:39	Administrator	1034 The point action button is connected		
€	06/03/2021	15:52:42	Administrator	1004 Emergency stop alarm		
₿	06/03/2021	15:52:42	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:42	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:44	Administrator	3037 active reset button		
€3	06/03/2021	15:52:44	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:44	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:44	Administrator	3037 active reset button		
€3	06/03/2021	15:52:44	Administrator	1005 Door and window open alarm		
<b>⊗</b>	06/03/2021	15:52:45	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:45	Administrator	3037 active reset button		
€3	06/03/2021	15:52:45	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:45	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:46	Administrator	3037 active reset button		
₿	06/03/2021	15:52:46	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:46	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:46	Administrator	3037 active reset button		
₿	06/03/2021	15:52:46	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:47	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:47	Administrator	3037 active reset button		
<b>◎</b>	06/03/2021	15:52:47	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:47	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:47	Administrator	3037 active reset button		
€3	06/03/2021	15:52:48	Administrator	1005 Door and window open alarm		
<b>⊗</b>	06/03/2021	15:52:48	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:48	Administrator	3037 active reset button		
€3	06/03/2021	15:52:48	Administrator	1005 Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 13 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
€3	06/03/2021	15:52:48	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:48	Administrator	3037 active reset button		
€3	06/03/2021	15:52:48	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:49	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:49	Administrator	3037 active reset button		
€3	06/03/2021	15:52:49	Administrator	1005 Door and window open alarm		
€3	06/03/2021	15:52:49	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:49	Administrator	3037 active reset button		
€	06/03/2021	15:52:49	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:49	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:51	Administrator	3037 active reset button		
€3_	06/03/2021	15:52:51	Administrator	1005 Door and window open alarm		
8	06/03/2021	15:52:51	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:51	Administrator	3037 active reset button		
8	06/03/2021	15:52:51	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:51	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:54	Administrator	3037 active reset button		
₿_	06/03/2021	15:52:55	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:52:55	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:55	Administrator	3037 active reset button		
₿	06/03/2021	15:52:55	Administrator	1005 Door and window open alarm		
₿_	06/03/2021	15:52:55	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:55	Administrator	3037 active reset button		
₿_	06/03/2021	15:52:55	Administrator	1005 Door and window open alarm		
8	06/03/2021	15:52:55	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:56	Administrator	3037 active reset button		
8	06/03/2021	15:52:56	Administrator	1005 Door and window open alarm		
₿_	06/03/2021	15:52:56	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:56	Administrator	3037 active reset button		
8	06/03/2021	15:52:56	Administrator	1005 Door and window open alarm		
<b>3</b>	06/03/2021	15:52:56	Administrator	1034 The point action button is connected		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 14 / 47

					Old value	New value
Гуре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	15:52:56	Administrator	3037 active reset button		
8	06/03/2021	15:52:56	Administrator	1005 Door and window open alarm		
<u>.</u>	06/03/2021	15:52:56	Administrator	1034 The point action button is connected		
AT	06/03/2021	15:52:57	Administrator	3037 active reset button		
3	06/03/2021	15:52:57	Administrator	1005 Door and window open alarm		
3	06/03/2021	15:52:57	Administrator	1034 The point action button is connected		
XT.	06/03/2021	15:52:57	Administrator	3037 active reset button		
3	06/03/2021	15:52:57	Administrator	1005 Door and window open alarm		
3	06/03/2021	15:52:57	Administrator	1034 The point action button is connected		
7	06/03/2021	15:53:05	Administrator	3034 active jog button		
VT.	06/03/2021	15:53:05	Administrator	3037 active reset button		
3	06/03/2021	15:53:05	Administrator	1005 Door and window open alarm		
3	06/03/2021	15:53:05	Administrator	1005 Door and window open alarm		
3	06/03/2021	15:53:05	Administrator	1007 Inverter fault		
T	06/03/2021	15:53:06	Administrator	3037 active reset button		
3	06/03/2021	15:53:06	Administrator	1007 Inverter fault		
T	06/03/2021	15:53:06	Administrator	3037 active reset button		
3	06/03/2021	15:53:06	Administrator	1007 Inverter fault		
T	06/03/2021	15:53:06	Administrator	3037 active reset button		
Ī	06/03/2021	15:53:07	Administrator	3037 active reset button		
VT.	06/03/2021	15:53:08	Administrator	3037 active reset button		
Ī	06/03/2021	15:53:15	Administrator	3034 active jog button		
3	06/03/2021	15:53:15	Administrator	1005 Door and window open alarm		
Ī	06/03/2021	15:53:15	Administrator	3037 active reset button		
3	06/03/2021	15:53:15	Administrator	1005 Door and window open alarm		
Ī	06/03/2021	15:53:16	Administrator	3037 active reset button		
3	06/03/2021	15:53:16	Administrator	1005 Door and window open alarm		
Ī	06/03/2021	15:53:16	Administrator	3037 active reset button		
3	06/03/2021	15:53:16	Administrator	1005 Door and window open alarm		
V	06/03/2021	15:53:17	Administrator	3037 active reset button		
3	06/03/2021	15:53:17	Administrator	1005 Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 15 / 47

							Old value	New value
Туре	Date	Time	Operator	No.	Description		Info 1	Info 2
AT	06/03/2021	15:53:19	Administrator	30:	37 active reset button			
€3	06/03/2021	15:53:19	Administrator	100	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:20	Administrator	30	37 active reset button			
<b>(3)</b>	06/03/2021	15:53:20	Administrator	100	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:20	Administrator	30	37 active reset button			
<b>(3)</b>	06/03/2021	15:53:20	Administrator	100	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:21	Administrator	30	34 active jog button			
AT	06/03/2021	15:53:22	Administrator	30	37 active reset button			
AT	06/03/2021	15:53:22	Administrator	30	37 active reset button			
AT	06/03/2021	15:53:22	Administrator	30	37 active reset button			
AT	06/03/2021	15:53:23	Administrator	30	37 active reset button			
AT	06/03/2021	15:53:23	Administrator	30	37 active reset button			
AT	06/03/2021	15:53:24	Administrator	30	34 active jog button			
€3	06/03/2021	15:53:24	Administrator	100	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:28	Administrator	30	37 active reset button			
€3	06/03/2021	15:53:28	Administrator	100	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:29	Administrator	30	37 active reset button			
€3	06/03/2021	15:53:29	Administrator	10	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:29	Administrator	30	37 active reset button			
₿_	06/03/2021	15:53:29	Administrator	10	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:29	Administrator	30	37 active reset button			
₿_	06/03/2021	15:53:29	Administrator	10	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:29	Administrator	30	37 active reset button			
<b></b>	06/03/2021	15:53:29	Administrator	100	05 Door and window open alar	ırm		
₿	06/03/2021	15:53:35	Administrator	100	05 Door and window open alar	ırm		
₿_	06/03/2021	15:53:35	Administrator	10	34 The point action button is co	connected		
AT	06/03/2021	15:53:41	Administrator	30:	37 active reset button			
₿_	06/03/2021	15:53:41	Administrator	10	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:41	Administrator	30:	37 active reset button			
₿_	06/03/2021	15:53:41	Administrator	100	05 Door and window open alar	ırm		
AT	06/03/2021	15:53:42	Administrator	30	37 active reset button			



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 16 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
<b>€3</b>	06/03/2021	15:53:42	Administrator	1005 Door and window open alarm		
AT	06/03/2021	15:53:42	Administrator	3034 active jog button		
AT	06/03/2021	15:53:43	Administrator	3037 active reset button		
AT	06/03/2021	15:53:43	Administrator	3037 active reset button		
AT	06/03/2021	15:53:44	Administrator	3037 active reset button		
AT	06/03/2021	15:53:44	Administrator	3037 active reset button		
AT	06/03/2021	15:53:54	Administrator	3034 active jog button		
€3	06/03/2021	15:53:54	Administrator	1005 Door and window open alarm		
AT	06/03/2021	15:54:01	Administrator	3037 active reset button		
€3	06/03/2021	15:54:01	Administrator	1005 Door and window open alarm		
AT	06/03/2021	15:54:02	Administrator	3037 active reset button		
€3	06/03/2021	15:54:02	Administrator	1005 Door and window open alarm		
AT	06/03/2021	15:54:04	Administrator	3037 active reset button		
€3	06/03/2021	15:54:04	Administrator	1005 Door and window open alarm		
AT	06/03/2021	15:54:05	Administrator	3034 active jog button		
AT	06/03/2021	15:54:06	Administrator	3037 active reset button		
AT	06/03/2021	15:54:21	Administrator	3037 active reset button		
AT	06/03/2021	15:54:21	Administrator	3037 active reset button		
AT	06/03/2021	15:54:21	Administrator	3037 active reset button		
€3	06/03/2021	15:54:26	Administrator	1005 Door and window open alarm		
AT	06/03/2021	15:54:35	Administrator	3037 active reset button		
₿	06/03/2021	15:54:35	Administrator	1005 Door and window open alarm		
❷	06/03/2021	15:54:36	Administrator	1005 Door and window open alarm		
₿	06/03/2021	15:54:36	Administrator	1007 Inverter fault		
AT	06/03/2021	15:54:36	Administrator	3037 active reset button		
₿	06/03/2021	15:54:36	Administrator	1007 Inverter fault		
AT	06/03/2021	15:54:36	Administrator	3037 active reset button		
€3	06/03/2021	15:54:36	Administrator	1007 Inverter fault		
AT	06/03/2021	15:54:36	Administrator	3037 active reset button		
€3	06/03/2021	15:54:36	Administrator	1007 Inverter fault		
AT	06/03/2021	15:54:36	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 17 / 47

_						Old value	New value
Туре	Date	Time	Operator	No.	Description	Info 1	Info 2
€3	06/03/2021	15:54:36	Administrator	100	Inverter fault		
AT	06/03/2021	15:54:37	Administrator	303	active reset button		
AT	06/03/2021	15:54:37	Administrator	303	active reset button		
AT	06/03/2021	15:54:38	Administrator	303	active start button		
₿	06/03/2021	15:54:41	Administrator	100	Door and window open alarm		
AT	06/03/2021	15:54:45	Administrator	303	active reset button		
₿	06/03/2021	15:54:45	Administrator	100	Door and window open alarm		
ΑT	06/03/2021	15:54:45	Administrator	303	active reset button		
AT	06/03/2021	15:54:45	Administrator	303	active reset button		
AT	06/03/2021	15:54:45	Administrator	303	active reset button		
AT	06/03/2021	15:54:46	Administrator	303	active start button		
₿_	06/03/2021	15:55:16	Administrator	101	Powder feeding time is too long		
AT	06/03/2021	15:55:22	Administrator	303	active reset button		
AT	06/03/2021	15:55:22	Administrator	303	active reset button		
AT	06/03/2021	15:55:22	Administrator	303	active reset button		
AT	06/03/2021	15:55:23	Administrator	303	active start button		
€3	06/03/2021	15:57:31	Administrator	100	Door and window open alarm		
ΑT	06/03/2021	15:57:34	Administrator	303	active reset button		
€3	06/03/2021	15:57:34	Administrator	100	Door and window open alarm		
ΑT	06/03/2021	15:57:34	Administrator	303	active reset button		
AT	06/03/2021	15:57:34	Administrator	303	active reset button		
AT	06/03/2021	15:57:34	Administrator	303	active reset button		
AT	06/03/2021	15:57:34	Administrator	303	active reset button		
AT	06/03/2021	15:57:35	Administrator	303	active start button		
€3	06/03/2021	15:57:47	Administrator	100	Door and window open alarm		
AT	06/03/2021	15:57:51	Administrator	303	active reset button		
₿	06/03/2021	15:57:51	Administrator	100	Door and window open alarm		
❷_	06/03/2021	15:57:51	Administrator	100	Door and window open alarm		
€	06/03/2021	15:57:51	Administrator	100	Inverter fault		
AT	06/03/2021	15:57:52	Administrator	303	active reset button		
₿	06/03/2021	15:57:52	Administrator	100	Inverter fault		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 18 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	15:57:52	Administrator	3037 active reset button		
AT	06/03/2021	15:57:52	Administrator	3037 active reset button		
AT	06/03/2021	15:58:03	Administrator	3035 active start button		
€	06/03/2021	15:59:42	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:05:53	Administrator	1003 Hand wheel spin out alarm		
€	06/03/2021	16:05:53	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:21	Administrator	3037 active reset button		
₿	06/03/2021	16:06:21	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:06:21	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:21	Administrator	3037 active reset button		
₿	06/03/2021	16:06:21	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:06:21	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:21	Administrator	3037 active reset button		
€3	06/03/2021	16:06:21	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:06:21	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:21	Administrator	3037 active reset button		
€3	06/03/2021	16:06:21	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:06:22	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:22	Administrator	3037 active reset button		
₿	06/03/2021	16:06:22	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:06:22	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:22	Administrator	3037 active reset button		
€3	06/03/2021	16:06:22	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:06:22	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:23	Administrator	3037 active reset button		
₿	06/03/2021	16:06:23	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:06:23	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:23	Administrator	3037 active reset button		
€3	06/03/2021	16:06:23	Administrator	1003 Hand wheel spin out alarm		
€	06/03/2021	16:06:23	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:06:24	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 19 / 47

						Old value	New value
Туре	Date	Time	Operator	No.	Description	Info 1	Info 2
€3	06/03/2021	16:06:24	Administrator	100	3 Hand wheel spin out alarm		
€3	06/03/2021	16:06:24	Administrator	100	5 Door and window open alarm		
AT	06/03/2021	16:06:25	Administrator	303	7 active reset button		
€3	06/03/2021	16:06:25	Administrator	100	B Hand wheel spin out alarm		
€3	06/03/2021	16:06:25	Administrator	100	5 Door and window open alarm		
AT	06/03/2021	16:06:25	Administrator	303	7 active reset button		
€3	06/03/2021	16:06:25	Administrator	100	B Hand wheel spin out alarm		
€3	06/03/2021	16:06:25	Administrator	100	5 Door and window open alarm		
AT	06/03/2021	16:06:29	Administrator	300	Speed adjust	2600	2600
AT	06/03/2021	16:06:40	Administrator	303	7 active reset button		
₿	06/03/2021	16:06:40	Administrator	100	B Hand wheel spin out alarm		
€3	06/03/2021	16:06:40	Administrator	100	5 Door and window open alarm		
AT	06/03/2021	16:06:40	Administrator	303	7 active reset button		
€3	06/03/2021	16:06:40	Administrator	100	B Hand wheel spin out alarm		
₿	06/03/2021	16:06:40	Administrator	100	Door and window open alarm		
AT	06/03/2021	16:06:40	Administrator	303	7 active reset button		
₿	06/03/2021	16:06:41	Administrator	100	3 Hand wheel spin out alarm		
₿_	06/03/2021	16:06:41	Administrator	100	Door and window open alarm		
AT	06/03/2021	16:06:54	Administrator	303	7 active reset button		
<b>⊗</b>	06/03/2021	16:06:54	Administrator	100	B Hand wheel spin out alarm		
₿	06/03/2021	16:06:54	Administrator	100	Door and window open alarm		
AT	06/03/2021	16:06:54	Administrator	303	7 active reset button		
₿	06/03/2021	16:06:54	Administrator	100	B Hand wheel spin out alarm		
₿_	06/03/2021	16:06:54	Administrator	100	5 Door and window open alarm		
AT	06/03/2021	16:06:54	Administrator	303	7 active reset button		
<b>⊗</b> _	06/03/2021	16:06:54	Administrator	100	3 Hand wheel spin out alarm		
<b>⊗</b>	06/03/2021	16:06:55	Administrator	100	Door and window open alarm		
AT	06/03/2021	16:06:56	Administrator	303	7 active reset button		
<b>⊗</b>	06/03/2021	16:06:56	Administrator	100	3 Hand wheel spin out alarm		
€3	06/03/2021	16:06:56	Administrator	100	5 Door and window open alarm		
AT	06/03/2021	16:06:56	Administrator	303	7 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 20 / 47

			<u>'</u>		Old value	New value
Гуре	Date	Time	Operator	No. Description	Info 1	Info 2
83	06/03/2021	16:06:56	Administrator	1003 Hand wheel spin out alarm		
=	06/03/2021	16:06:56	Administrator	1005 Door and window open alarm		
				·		
AT	06/03/2021	16:06:56	Administrator	3037 active reset button		
3	06/03/2021	16:06:56	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:06:57	Administrator	1005 Door and window open alarm		
<u> </u>	06/03/2021	16:06:57	Administrator	3037 active reset button		
3	06/03/2021	16:06:57	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:06:57	Administrator	1005 Door and window open alarm		
7	06/03/2021	16:06:57	Administrator	3037 active reset button		
3	06/03/2021	16:06:57	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:06:57	Administrator	1005 Door and window open alarm		
7	06/03/2021	16:06:58	Administrator	3037 active reset button		
3	06/03/2021	16:06:58	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:06:58	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:07:10	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:07:10	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:07:10	Administrator	1041 Following error		
Ī	06/03/2021	16:07:11	Administrator	3037 active reset button		
3	06/03/2021	16:07:11	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:07:12	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:07:12	Administrator	1041 Following error		
Ī	06/03/2021	16:07:12	Administrator	3037 active reset button		
3	06/03/2021	16:07:12	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:07:12	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:07:12	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:07:12	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:07:12	Administrator	1041 Following error		
Ū	06/03/2021	16:07:13	Administrator	3037 active reset button		
3	06/03/2021	16:07:13	Administrator	1003 Hand wheel spin out alarm		
3	06/03/2021	16:07:13	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:07:13	Administrator	1041 Following error		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 21 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	16:07:20	Administrator	3037 active reset button		
€3	06/03/2021	16:07:21	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:07:21	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:07:21	Administrator	1041 Following error		
AT	06/03/2021	16:07:21	Administrator	3037 active reset button		
€3	06/03/2021	16:07:21	Administrator	1003 Hand wheel spin out alarm		
ጨ	06/03/2021	16:07:21	Administrator	1005 Door and window open alarm		
₿	06/03/2021	16:07:21	Administrator	1041 Following error		
AT	06/03/2021	16:07:43	Administrator	3037 active reset button		
€3	06/03/2021	16:07:43	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:07:43	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:07:43	Administrator	3037 active reset button		
€3	06/03/2021	16:07:43	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:07:43	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:07:44	Administrator	3037 active reset button		
₿	06/03/2021	16:07:44	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:07:44	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:07:44	Administrator	3037 active reset button		
₿	06/03/2021	16:07:44	Administrator	1003 Hand wheel spin out alarm		
₿_	06/03/2021	16:07:44	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:07:44	Administrator	3037 active reset button		
₿_	06/03/2021	16:07:44	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:07:44	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:07:44	Administrator	3037 active reset button		
€	06/03/2021	16:07:44	Administrator	1003 Hand wheel spin out alarm		
₿_	06/03/2021	16:07:44	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:07:44	Administrator	3037 active reset button		
❷_	06/03/2021	16:07:44	Administrator	1003 Hand wheel spin out alarm		
€	06/03/2021	16:07:44	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:07:45	Administrator	3037 active reset button		
₿	06/03/2021	16:07:45	Administrator	1003 Hand wheel spin out alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 22 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
€3	06/03/2021	16:07:45	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:10:58	Administrator	3037 active reset button		
8	06/03/2021	16:10:58	Administrator	1003 Hand wheel spin out alarm		
Č	06/03/2021	16:10:58	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:10:58	Administrator	3037 active reset button		
€3	06/03/2021	16:10:58	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:10:58	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:10:58	Administrator	3037 active reset button		
€3	06/03/2021	16:10:58	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:10:58	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:10:59	Administrator	3037 active reset button		
₿	06/03/2021	16:10:59	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:10:59	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:10:59	Administrator	3037 active reset button		
₿	06/03/2021	16:10:59	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:10:59	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:11:02	Administrator	3037 active reset button		
₿	06/03/2021	16:11:02	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:11:02	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:11:03	Administrator	3037 active reset button		
₿	06/03/2021	16:11:03	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:11:03	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:11:03	Administrator	3037 active reset button		
€3	06/03/2021	16:11:03	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:11:03	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:11:03	Administrator	3034 active jog button		
AT	06/03/2021	16:11:04	Administrator	3037 active reset button		
€3	06/03/2021	16:11:04	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:11:04	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:11:04	Administrator	3037 active reset button		
8	06/03/2021	16:11:04	Administrator	1003 Hand wheel spin out alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 23 / 47

						Old value	New value
Туре	Date	Time	Operator	No.	Description	Info 1	Info 2
€3	06/03/2021	16:11:04	Administrator	100	Door and window open alarm		
AT	06/03/2021	16:11:05	Administrator	303	active jog button		
AT	06/03/2021	16:11:07	Administrator	303	active reset button		
€3	06/03/2021	16:11:07	Administrator	100	B Hand wheel spin out alarm		
₿	06/03/2021	16:11:07	Administrator	100	Door and window open alarm		
€3	06/03/2021	16:11:34	Administrator	100	Hand wheel spin out alarm		
€3	06/03/2021	16:11:34	Administrator	100	Door and window open alarm		
€3	06/03/2021	16:11:35	Administrator	100	Insufficient vacuum pressure		
AT	06/03/2021	16:11:36	Administrator	303	active reset button		
€3	06/03/2021	16:11:36	Administrator	100	Hand wheel spin out alarm		
€3	06/03/2021	16:11:36	Administrator	100	Door and window open alarm		
€3	06/03/2021	16:11:36	Administrator	100	Insufficient vacuum pressure		
AT	06/03/2021	16:11:36	Administrator	303	active reset button		
€3	06/03/2021	16:11:36	Administrator	100	Hand wheel spin out alarm		
€3	06/03/2021	16:11:36	Administrator	100	Door and window open alarm		
€3	06/03/2021	16:11:36	Administrator	100	Insufficient vacuum pressure		
AT	06/03/2021	16:11:59	Administrator	300	Speed adjust	2600	2600
₿_	06/03/2021	16:12:05	Administrator	100	Hand wheel spin out alarm		
₿	06/03/2021	16:12:05	Administrator	100	Door and window open alarm		
€3	06/03/2021	16:12:05	Administrator	100	Insufficient vacuum pressure		
₿	06/03/2021	16:12:05	Administrator	101	Insufficient of empty capsules		
₿	06/03/2021	16:12:15	Administrator	100	Hand wheel spin out alarm		
₿	06/03/2021	16:12:15	Administrator	100	Door and window open alarm		
€3	06/03/2021	16:12:15	Administrator	101	Insufficient of empty capsules		
AT	06/03/2021	16:13:09	Administrator	303	active reset button		
<b>⊗</b> _	06/03/2021	16:13:09	Administrator	100	Hand wheel spin out alarm		
₿.	06/03/2021	16:13:09	Administrator	100	Door and window open alarm		
AT	06/03/2021	16:13:12	Administrator	303	active reset button		
<b>⊗</b>	06/03/2021	16:13:12	Administrator	100	Hand wheel spin out alarm		
₿_	06/03/2021	16:13:12	Administrator	100	Door and window open alarm		
AT	06/03/2021	16:13:12	Administrator	303	active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 24 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
€3	06/03/2021	16:13:12	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:13:12	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:15	Administrator	3037 active reset button		
€3	06/03/2021	16:13:15	Administrator	1003 Hand wheel spin out alarm		
<b>83</b>	06/03/2021	16:13:15	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:15	Administrator	3037 active reset button		
<b>83</b>	06/03/2021	16:13:15	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:13:15	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:16	Administrator	3037 active reset button		
₿	06/03/2021	16:13:16	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:13:16	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:16	Administrator	3037 active reset button		
<b>83</b>	06/03/2021	16:13:16	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:13:16	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:36	Administrator	3037 active reset button		
€3	06/03/2021	16:13:36	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:37	Administrator	3037 active reset button		
€3	06/03/2021	16:13:37	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:37	Administrator	3037 active reset button		
₿	06/03/2021	16:13:37	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:40	Administrator	3037 active reset button		
€3	06/03/2021	16:13:40	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:40	Administrator	3037 active reset button		
₿	06/03/2021	16:13:40	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:40	Administrator	3037 active reset button		
€3	06/03/2021	16:13:41	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:41	Administrator	3037 active reset button		
€3	06/03/2021	16:13:41	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:41	Administrator	3037 active reset button		
€	06/03/2021	16:13:41	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:42	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 25 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
€3	06/03/2021	16:13:42	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:42	Administrator	3037 active reset button		
€3	06/03/2021	16:13:42	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:44	Administrator	3037 active reset button		
€3	06/03/2021	16:13:44	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:44	Administrator	3037 active reset button		
€3	06/03/2021	16:13:44	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:57	Administrator	3037 active reset button		
€3	06/03/2021	16:13:57	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:13:58	Administrator	3037 active reset button		
€3	06/03/2021	16:13:58	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:03	Administrator	3037 active reset button		
€3	06/03/2021	16:14:03	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:05	Administrator	3037 active reset button		
₿	06/03/2021	16:14:05	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:06	Administrator	3037 active reset button		
₿	06/03/2021	16:14:06	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:09	Administrator	3037 active reset button		
₿	06/03/2021	16:14:09	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:14:09	Administrator	3037 active reset button		
€3	06/03/2021	16:14:09	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:11	Administrator	3037 active reset button		
₿	06/03/2021	16:14:11	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:14:11	Administrator	3037 active reset button		
€3	06/03/2021	16:14:11	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:24	Administrator	3037 active reset button		
€3	06/03/2021	16:14:24	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:14:24	Administrator	3037 active reset button		
€3	06/03/2021	16:14:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:24	Administrator	3037 active reset button		
€3	06/03/2021	16:14:24	Administrator	1005 Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 26 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	16:14:24	Administrator	3037 active reset button		
€3	06/03/2021	16:14:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:29	Administrator	3037 active reset button		
€3	06/03/2021	16:14:29	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:30	Administrator	3037 active reset button		
€3	06/03/2021	16:14:30	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:30	Administrator	3037 active reset button		
€3	06/03/2021	16:14:30	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:30	Administrator	3037 active reset button		
₿	06/03/2021	16:14:30	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:30	Administrator	3037 active reset button		
€	06/03/2021	16:14:30	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:30	Administrator	3037 active reset button		
8	06/03/2021	16:14:30	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:31	Administrator	3037 active reset button		
€3	06/03/2021	16:14:31	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:31	Administrator	3037 active reset button		
₿	06/03/2021	16:14:31	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:31	Administrator	3037 active reset button		
₿	06/03/2021	16:14:31	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:32	Administrator	3037 active reset button		
₿	06/03/2021	16:14:32	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:14:32	Administrator	3037 active reset button		
₿	06/03/2021	16:14:32	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:32	Administrator	3037 active reset button		
€3	06/03/2021	16:14:32	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:33	Administrator	3037 active reset button		
€3	06/03/2021	16:14:33	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:33	Administrator	3037 active reset button		
₿	06/03/2021	16:14:33	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:14:33	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 27 / 47

					Old value	New value
уре	Date	Time	Operator	No. Description	Info 1	Info 2
3	06/03/2021	16:14:33	Administrator	1005 Door and window open alarm		
AT .	06/03/2021	16:14:34	Administrator	3037 active reset button		
3	06/03/2021	16:14:34	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:34	Administrator	3037 active reset button		
3	06/03/2021	16:14:34	Administrator	1005 Door and window open alarm		
XT.	06/03/2021	16:14:34	Administrator	3037 active reset button		
3	06/03/2021	16:14:34	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:14:42	Administrator	3037 active reset button		
8	06/03/2021	16:14:42	Administrator	1005 Door and window open alarm		
<b>AT</b>	06/03/2021	16:14:42	Administrator	3037 active reset button		
3	06/03/2021	16:14:42	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:14:42	Administrator	3037 active reset button		
3	06/03/2021	16:14:42	Administrator	1005 Door and window open alarm		
XT	06/03/2021	16:14:43	Administrator	3037 active reset button		
3	06/03/2021	16:14:43	Administrator	1005 Door and window open alarm		
AT.	06/03/2021	16:14:43	Administrator	3037 active reset button		
3	06/03/2021	16:14:43	Administrator	1005 Door and window open alarm		
AT.	06/03/2021	16:14:43	Administrator	3037 active reset button		
3	06/03/2021	16:14:43	Administrator	1005 Door and window open alarm		
T	06/03/2021	16:14:43	Administrator	3037 active reset button		
3	06/03/2021	16:14:43	Administrator	1005 Door and window open alarm		
AT .	06/03/2021	16:14:44	Administrator	3037 active reset button		
3	06/03/2021	16:14:44	Administrator	1005 Door and window open alarm		
XT	06/03/2021	16:14:44	Administrator	3037 active reset button		
3	06/03/2021	16:14:44	Administrator	1005 Door and window open alarm		
VI.	06/03/2021	16:14:44	Administrator	3037 active reset button		
3	06/03/2021	16:14:44	Administrator	1005 Door and window open alarm		
V	06/03/2021	16:14:50	Administrator	3037 active reset button		
3	06/03/2021	16:14:50	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:14:51	Administrator	3037 active reset button		
X	06/03/2021	16:14:51	Administrator	1005 Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 28 / 47

			•		Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	16:14:51	Administrator	3037 active reset button		
	06/03/2021	16:14:51	Administrator	1005 Door and window open alarm		
<b>₩</b>				·		
AT	06/03/2021	16:14:51	Administrator	3037 active reset button		
<b>⊗</b>	06/03/2021	16:14:51	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:14:52	Administrator	3037 active reset button		
<b>②</b>	06/03/2021	16:14:52	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:15:04	Administrator	3037 active reset button		
<u>Q</u>	06/03/2021	16:15:04	Administrator	1005 Door and window open alarm		
<u> </u>	06/03/2021	16:15:04	Administrator	1005 Door and window open alarm		
<b>②</b>	06/03/2021	16:15:04	Administrator	1007 Inverter fault		
AT	06/03/2021	16:15:04	Administrator	3037 active reset button		
€	06/03/2021	16:15:04	Administrator	1007 Inverter fault		
AT	06/03/2021	16:15:05	Administrator	3037 active reset button		
8	06/03/2021	16:15:05	Administrator	1007 Inverter fault		
AT	06/03/2021	16:15:05	Administrator	3037 active reset button		
€	06/03/2021	16:15:05	Administrator	1007 Inverter fault		
AT	06/03/2021	16:15:05	Administrator	3037 active reset button		
₿	06/03/2021	16:15:05	Administrator	1007 Inverter fault		
ΑT	06/03/2021	16:15:06	Administrator	3037 active reset button		
€3	06/03/2021	16:15:32	Administrator	1005 Door and window open alarm		
8	06/03/2021	16:15:54	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:15:54	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:16:26	Administrator	3037 active reset button		
8	06/03/2021	16:16:26	Administrator	1005 Door and window open alarm		
Ö	06/03/2021	16:16:26	Administrator	1005 Door and window open alarm		
Ö	06/03/2021	16:16:26	Administrator	1007 Inverter fault		
AT	06/03/2021	16:16:26	Administrator	3037 active reset button		
<u>.</u>	06/03/2021	16:16:26	Administrator	1007 Inverter fault		
AT	06/03/2021	16:16:26	Administrator	3037 active reset button		
€3	06/03/2021	16:16:26	Administrator	1007 Inverter fault		
AT	06/03/2021	16:16:26	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 29 / 47

						Old value	New value
Туре	Date	Time	Operator	No.	Description	Info 1	Info 2
8	06/03/2021	16:16:26	Administrator	1007	nverter fault		
AT	06/03/2021	16:16:26	Administrator	3037	active reset button		
€3	06/03/2021	16:16:26	Administrator	1007	nverter fault		
AT	06/03/2021	16:16:27	Administrator	3037	active reset button		
€3	06/03/2021	16:16:27	Administrator	1007	nverter fault		
AT	06/03/2021	16:16:27	Administrator	3037	active reset button		
€3	06/03/2021	16:16:27	Administrator	1007	nverter fault		
AT	06/03/2021	16:16:27	Administrator	3037	active reset button		
AT	06/03/2021	16:16:28	Administrator	3037	active reset button		
AT	06/03/2021	16:16:29	Administrator	3037	active reset button		
AT	06/03/2021	16:16:29	Administrator	3037	active reset button		
AT	06/03/2021	16:16:30	Administrator	3037	active reset button		
AT	06/03/2021	16:16:30	Administrator	3037	active reset button		
AT	06/03/2021	16:16:33	Administrator	3035	active start button		
₿	06/03/2021	16:16:56	Administrator	1012	Material supply interval is too long		
€3	06/03/2021	16:17:02	Administrator	1005	Door and window open alarm		
₿	06/03/2021	16:17:02	Administrator	1012	Material supply interval is too long		
AT	06/03/2021	16:17:16	Administrator	3037	active reset button		
€3	06/03/2021	16:17:16	Administrator	1005	Door and window open alarm		
€3	06/03/2021	16:17:16	Administrator	1005	Door and window open alarm		
€3	06/03/2021	16:17:16	Administrator	1007	nverter fault		
AT	06/03/2021	16:17:16	Administrator	3037	active reset button		
₿	06/03/2021	16:17:17	Administrator	1007	nverter fault		
AT	06/03/2021	16:17:17	Administrator	3037	active reset button		
₿	06/03/2021	16:17:17	Administrator	1007	nverter fault		
ΑT	06/03/2021	16:17:17	Administrator	3037	active reset button		
€3	06/03/2021	16:17:17	Administrator	1007	nverter fault		
AT	06/03/2021	16:17:17	Administrator	3037	active reset button		
€3	06/03/2021	16:17:17	Administrator	1007	nverter fault		
AT	06/03/2021	16:17:18	Administrator	3037	active reset button		
€3	06/03/2021	16:17:18	Administrator	1007	nverter fault		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 30 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	16:17:18	Administrator	3037 active reset button		
AT	06/03/2021	16:17:21	Administrator	3035 active start button		
<b>83</b>	06/03/2021	16:17:34	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:19:23	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:19:23	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:22:37	Administrator	3037 active reset button		
€3	06/03/2021	16:22:37	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:22:37	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:22:37	Administrator	1003 Hand wheel spin out alarm		
AT	06/03/2021	16:22:37	Administrator	3037 active reset button		
€3	06/03/2021	16:22:37	Administrator	1005 Door and window open alarm		
₿	06/03/2021	16:22:37	Administrator	1007 Inverter fault		
€3	06/03/2021	16:22:37	Administrator	1003 Hand wheel spin out alarm		
AT	06/03/2021	16:22:37	Administrator	3037 active reset button		
€3	06/03/2021	16:22:37	Administrator	1007 Inverter fault		
€3	06/03/2021	16:22:38	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:22:38	Administrator	1007 Inverter fault		
AT	06/03/2021	16:22:38	Administrator	3037 active reset button		
€3	06/03/2021	16:22:38	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:22:38	Administrator	1007 Inverter fault		
AT	06/03/2021	16:22:38	Administrator	3037 active reset button		
€3	06/03/2021	16:22:38	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:22:38	Administrator	1007 Inverter fault		
AT	06/03/2021	16:22:38	Administrator	3037 active reset button		
€3	06/03/2021	16:22:38	Administrator	1003 Hand wheel spin out alarm		
€3	06/03/2021	16:22:38	Administrator	1007 Inverter fault		
AT	06/03/2021	16:22:39	Administrator	3037 active reset button		
€3	06/03/2021	16:22:39	Administrator	1003 Hand wheel spin out alarm		
AT	06/03/2021	16:22:40	Administrator	3037 active reset button		
€3	06/03/2021	16:22:40	Administrator	1003 Hand wheel spin out alarm		
AT	06/03/2021	16:23:10	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 31 / 47

Typo	Date	Time	Operator	No.	Description	Old value Info 1	New value Info 2
Туре	Date	Tillie	Operator	INU.	Jesurpuon .	IIIIO I	IIIIO Z
AT	06/03/2021	16:23:10	Administrator	3037	active reset button		
AT	06/03/2021	16:23:11	Administrator	3037	active reset button		
AT	06/03/2021	16:23:13	Administrator	3037	active reset button		
AT	06/03/2021	16:23:13	Administrator	3037	active reset button		
AT	06/03/2021	16:23:14	Administrator	3037	active reset button		
AT	06/03/2021	16:23:15	Administrator	3035	active start button		
₿	06/03/2021	16:23:25	Administrator	1012	Material supply interval is too long		
AT	06/03/2021	16:23:39	Administrator	3037	active reset button		
AT	06/03/2021	16:23:39	Administrator	3037	active reset button		
AT	06/03/2021	16:23:39	Administrator	3037	active reset button		
AT	06/03/2021	16:23:40	Administrator	3035	active start button		
₿	06/03/2021	16:23:50	Administrator	1012	Material supply interval is too long		
AT	06/03/2021	16:23:59	Administrator	3037	active reset button		
ΑT	06/03/2021	16:24:17	Administrator	3037	active reset button		
AT	06/03/2021	16:24:17	Administrator	3037	active reset button		
ΑT	06/03/2021	16:24:18	Administrator	3037	active reset button		
AT	06/03/2021	16:24:18	Administrator	3035	active start button		
₿	06/03/2021	16:24:48	Administrator	1012	Material supply interval is too long		
AT	06/03/2021	16:24:51	Administrator	3037	active reset button		
AT	06/03/2021	16:24:52	Administrator	3035	active start button		
AT	06/03/2021	16:25:16	Administrator	3036	active stop button		
	06/03/2021	16:25:35	Administrator	1005	Door and window open alarm		
АТ	06/03/2021	16:27:26	Administrator	3037	active reset button		
<b>≅</b>	06/03/2021	16:27:26	Administrator	1005	Door and window open alarm		
₿	06/03/2021	16:27:26	Administrator	1005	Door and window open alarm		
8	06/03/2021	16:27:26	Administrator	1007	nverter fault		
AT	06/03/2021	16:27:26	Administrator	3037	active reset button		
8	06/03/2021	16:27:26	Administrator	1007	nverter fault		
AT	06/03/2021	16:27:26	Administrator	3037	active reset button		
8	06/03/2021	16:27:26	Administrator	1007	nverter fault		
AT	06/03/2021	16:27:26	Administrator	3037	active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 32 / 47

							Old value	New value
Туре	Date	Time	Operator	No.	Description		Info 1	Info 2
€3	06/03/2021	16:27:26	Administrator	100	7 Inverter fault			
AT	06/03/2021	16:27:27	Administrator	303	7 active reset button			
<b>83</b>	06/03/2021	16:27:27	Administrator	100	7 Inverter fault			
AT	06/03/2021	16:27:27	Administrator	303	7 active reset button			
AT	06/03/2021	16:27:30	Administrator	303	5 active start button			
€3	06/03/2021	16:28:08	Administrator	101	1 Powder feeding time is too long			
€3	06/03/2021	16:28:12	Administrator	100	5 Door and window open alarm			
₿	06/03/2021	16:28:12	Administrator	101	1 Powder feeding time is too long			
AT	06/03/2021	16:28:25	Administrator	303	7 active reset button			
₿	06/03/2021	16:28:25	Administrator	100	5 Door and window open alarm			
€3	06/03/2021	16:28:25	Administrator	100	5 Door and window open alarm			
₿	06/03/2021	16:28:25	Administrator	100	7 Inverter fault			
AT	06/03/2021	16:28:25	Administrator	303	7 active reset button			
€	06/03/2021	16:28:26	Administrator	100	7 Inverter fault			
ΑT	06/03/2021	16:28:26	Administrator	303	7 active reset button			
₿	06/03/2021	16:28:26	Administrator	100	7 Inverter fault			
ΑT	06/03/2021	16:28:26	Administrator	303	7 active reset button			
€3	06/03/2021	16:28:26	Administrator	100	7 Inverter fault			
AT	06/03/2021	16:28:26	Administrator	303	7 active reset button			
€3	06/03/2021	16:28:26	Administrator	100	7 Inverter fault			
AT	06/03/2021	16:28:27	Administrator	303	7 active reset button			
AT	06/03/2021	16:28:27	Administrator	303	7 active reset button			
AT	06/03/2021	16:28:28	Administrator	303	5 active start button			
€3	06/03/2021	16:29:00	Administrator	101:	2 Material supply interval is too lo	ong		
AT	06/03/2021	16:29:12	Administrator	303	7 active reset button			
AT	06/03/2021	16:29:12	Administrator	303	7 active reset button			
AT	06/03/2021	16:29:12	Administrator	303	7 active reset button			
AT	06/03/2021	16:29:12	Administrator	303	7 active reset button			
AT	06/03/2021	16:29:13	Administrator	303	5 active start button			
€3	06/03/2021	16:29:43	Administrator	100	Door and window open alarm			
AT	06/03/2021	16:31:23	Administrator	303	7 active reset button			



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 33 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
€3	06/03/2021	16:31:23	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:23	Administrator	3037 active reset button		
€3	06/03/2021	16:31:23	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:24	Administrator	3037 active reset button		
€3	06/03/2021	16:31:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:24	Administrator	3037 active reset button		
€3	06/03/2021	16:31:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:24	Administrator	3037 active reset button		
€3	06/03/2021	16:31:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:25	Administrator	3037 active reset button		
€3	06/03/2021	16:31:25	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:31:25	Administrator	3037 active reset button		
€3	06/03/2021	16:31:25	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:26	Administrator	3037 active reset button		
€	06/03/2021	16:31:26	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:26	Administrator	3037 active reset button		
€3	06/03/2021	16:31:26	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:26	Administrator	3037 active reset button		
€3	06/03/2021	16:31:26	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:27	Administrator	3037 active reset button		
€3	06/03/2021	16:31:27	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:31:32	Administrator	3037 active reset button		
₿	06/03/2021	16:31:32	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:31:32	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:31:32	Administrator	1007 Inverter fault		
AT	06/03/2021	16:31:32	Administrator	3037 active reset button		
€	06/03/2021	16:31:32	Administrator	1007 Inverter fault		
AT	06/03/2021	16:31:33	Administrator	3037 active reset button		
€3	06/03/2021	16:31:33	Administrator	1007 Inverter fault		
AT	06/03/2021	16:31:33	Administrator	3037 active reset button		
€3	06/03/2021	16:31:33	Administrator	1007 Inverter fault		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 34 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	16:31:33	Administrator	3037 active reset button		
<b>€3</b>	06/03/2021	16:31:33	Administrator	1007 Inverter fault		
AT	06/03/2021	16:31:34	Administrator	3037 active reset button		
AT	06/03/2021	16:31:35	Administrator	3035 active start button		
AT	06/03/2021	16:31:54	Administrator	3037 active reset button		
AT	06/03/2021	16:31:54	Administrator	3037 active reset button		
AT	06/03/2021	16:31:55	Administrator	3037 active reset button		
AT	06/03/2021	16:31:55	Administrator	3037 active reset button		
AT	06/03/2021	16:32:03	Administrator	3037 active reset button		
AT	06/03/2021	16:32:03	Administrator	3037 active reset button		
€3	06/03/2021	16:32:03	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:04	Administrator	3037 active reset button		
€3	06/03/2021	16:32:04	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:04	Administrator	3037 active reset button		
€3	06/03/2021	16:32:04	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:05	Administrator	3037 active reset button		
8	06/03/2021	16:32:05	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:05	Administrator	3037 active reset button		
₿_	06/03/2021	16:32:05	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:05	Administrator	3037 active reset button		
€3	06/03/2021	16:32:05	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:06	Administrator	3037 active reset button		
€3	06/03/2021	16:32:06	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:06	Administrator	3037 active reset button		
₿_	06/03/2021	16:32:06	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:06	Administrator	3037 active reset button		
€3	06/03/2021	16:32:07	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:07	Administrator	3037 active reset button		
€3	06/03/2021	16:32:07	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:32:07	Administrator	3037 active reset button		
₿	06/03/2021	16:32:07	Administrator	1005 Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 35 / 47

						Old value	New value
Туре	Date	Time	Operator	No.	Description	 Info 1	Info 2
AT	06/03/2021	16:32:08	Administrator	3037	active reset button		
€3	06/03/2021	16:32:08	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:11	Administrator	3037	active reset button		
8	06/03/2021	16:32:11	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:12	Administrator	3037	active reset button		
€3	06/03/2021	16:32:12	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:12	Administrator	3037	active reset button		
₿	06/03/2021	16:32:12	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:12	Administrator	3037	active reset button		
₿_	06/03/2021	16:32:12	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:13	Administrator	3037	active reset button		
€3	06/03/2021	16:32:13	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:13	Administrator	3037	active reset button		
€3	06/03/2021	16:32:13	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:14	Administrator	3037	active reset button		
€3	06/03/2021	16:32:14	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:15	Administrator	3037	active reset button		
₿_	06/03/2021	16:32:15	Administrator	1005	Door and window open alarm		
ΑT	06/03/2021	16:32:15	Administrator	3037	active reset button		
₿_	06/03/2021	16:32:15	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:17	Administrator	3037	active reset button		
₿_	06/03/2021	16:32:17	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:17	Administrator	3037	active reset button		
₿_	06/03/2021	16:32:17	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:32:18	Administrator	3037	active reset button		
₿_	06/03/2021	16:32:18	Administrator	1005	Door and window open alarm		
₿	06/03/2021	16:32:18	Administrator	1005	Door and window open alarm		
❸_	06/03/2021	16:32:18	Administrator	1007	Inverter fault		
AT	06/03/2021	16:32:18	Administrator	3037	active reset button		
❸_	06/03/2021	16:32:18	Administrator	1007	Inverter fault		
AT	06/03/2021	16:32:19	Administrator	3037	active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 36 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	16:32:21	Administrator	3035 active start button		
€3	06/03/2021	16:32:39	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:19	Administrator	3037 active reset button		
€3	06/03/2021	16:33:19	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:20	Administrator	3037 active reset button		
€3	06/03/2021	16:33:20	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:20	Administrator	3037 active reset button		
₿	06/03/2021	16:33:20	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:33:20	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:20	Administrator	3037 active reset button		
€3	06/03/2021	16:33:20	Administrator	1007 Inverter fault		
€	06/03/2021	16:33:20	Administrator	1007 Inverter fault		
€3	06/03/2021	16:33:20	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:20	Administrator	3037 active reset button		
€3	06/03/2021	16:33:20	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:20	Administrator	3037 active reset button		
₿	06/03/2021	16:33:20	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:21	Administrator	3037 active reset button		
₿_	06/03/2021	16:33:21	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:21	Administrator	3037 active reset button		
₿_	06/03/2021	16:33:21	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:22	Administrator	3037 active reset button		
€3	06/03/2021	16:33:22	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:23	Administrator	3037 active reset button		
₿	06/03/2021	16:33:23	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:23	Administrator	3037 active reset button		
₿_	06/03/2021	16:33:23	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:23	Administrator	3037 active reset button		
₿_	06/03/2021	16:33:23	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:23	Administrator	3037 active reset button		
₿	06/03/2021	16:33:23	Administrator	1005 Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 37 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	16:33:24	Administrator	3037 active reset button		
€3	06/03/2021	16:33:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:24	Administrator	3037 active reset button		
<b>3</b>	06/03/2021	16:33:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:24	Administrator	3037 active reset button		
€3	06/03/2021	16:33:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:24	Administrator	3037 active reset button		
€3	06/03/2021	16:33:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:24	Administrator	3037 active reset button		
€3	06/03/2021	16:33:24	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:33:30	Administrator	3037 active reset button		
€3	06/03/2021	16:33:30	Administrator	1005 Door and window open alarm		
₿	06/03/2021	16:33:30	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:33:30	Administrator	1007 Inverter fault		
AT	06/03/2021	16:33:30	Administrator	3037 active reset button		
8	06/03/2021	16:33:30	Administrator	1007 Inverter fault		
AT	06/03/2021	16:33:31	Administrator	3037 active reset button		
€3	06/03/2021	16:33:31	Administrator	1007 Inverter fault		
AT	06/03/2021	16:33:31	Administrator	3037 active reset button		
€3	06/03/2021	16:33:31	Administrator	1007 Inverter fault		
AT	06/03/2021	16:33:31	Administrator	3037 active reset button		
ΑT	06/03/2021	16:33:33	Administrator	3035 active start button		
€3	06/03/2021	16:34:03	Administrator	1012 Material supply interval is too long		
AT	06/03/2021	16:34:51	Administrator	3037 active reset button		
AT	06/03/2021	16:34:51	Administrator	3037 active reset button		
AT	06/03/2021	16:34:51	Administrator	3037 active reset button		
AT	06/03/2021	16:34:52	Administrator	3035 active start button		
₿_	06/03/2021	16:35:39	Administrator	1012 Material supply interval is too long		
€3	06/03/2021	16:36:18	Administrator	1005 Door and window open alarm		
₿_	06/03/2021	16:36:18	Administrator	1012 Material supply interval is too long		
AT	06/03/2021	16:38:04	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 38 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
€3	06/03/2021	16:38:04	Administrator	1005 Door and window open alarm		
Ö	06/03/2021	16:38:04	Administrator	1005 Door and window open alarm		
Ö	06/03/2021	16:38:04	Administrator	1007 Inverter fault		
AT	06/03/2021	16:38:04	Administrator	3037 active reset button		
₿	06/03/2021	16:38:04	Administrator	1007 Inverter fault		
AT	06/03/2021	16:38:04	Administrator	3037 active reset button		
€3	06/03/2021	16:38:04	Administrator	1007 Inverter fault		
AT	06/03/2021	16:38:07	Administrator	3037 active reset button		
AT	06/03/2021	16:38:07	Administrator	3037 active reset button		
AT	06/03/2021	16:38:07	Administrator	3037 active reset button		
AT	06/03/2021	16:38:09	Administrator	3035 active start button		
€3	06/03/2021	16:38:38	Administrator	1012 Material supply interval is too long		
AT	06/03/2021	16:39:02	Administrator	3037 active reset button		
AT	06/03/2021	16:39:02	Administrator	3037 active reset button		
AT	06/03/2021	16:39:03	Administrator	3037 active reset button		
AT	06/03/2021	16:39:03	Administrator	3037 active reset button		
AT	06/03/2021	16:39:04	Administrator	3035 active start button		
₿	06/03/2021	16:39:09	Administrator	1012 Material supply interval is too long		
AT	06/03/2021	16:39:25	Administrator	3037 active reset button		
AT	06/03/2021	16:39:26	Administrator	3037 active reset button		
AT	06/03/2021	16:39:26	Administrator	3037 active reset button		
AT	06/03/2021	16:39:28	Administrator	3035 active start button		
AT	06/03/2021	16:39:59	Administrator	3035 active start button		
₿	06/03/2021	16:40:46	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:43:35	Administrator	1003 Hand wheel spin out alarm		
₿	06/03/2021	16:43:35	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:44:39	Administrator	3037 active reset button		
€3	06/03/2021	16:44:39	Administrator	1005 Door and window open alarm		
❷	06/03/2021	16:44:40	Administrator	1005 Door and window open alarm		
€3	06/03/2021	16:44:40	Administrator	1007 Inverter fault		
AT	06/03/2021	16:44:40	Administrator	3037 active reset button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 39 / 47

_	5.	<b>T</b> :				Old value	New value
Туре	Date	Time	Operator	No.	Description	Info 1	Info 2
€3	06/03/2021	16:44:40	Administrator	1007	Inverter fault		
AT	06/03/2021	16:44:40	Administrator	3037	active reset button		
€3	06/03/2021	16:44:40	Administrator	1007	Inverter fault		
AT	06/03/2021	16:44:41	Administrator	3037	active reset button		
AT	06/03/2021	16:44:41	Administrator	3037	active reset button		
AT	06/03/2021	16:44:43	Administrator	3035	active start button		
₿	06/03/2021	16:45:28	Administrator	1011	Powder feeding time is too long		
ΑT	06/03/2021	16:45:53	Administrator	3037	active reset button		
AT	06/03/2021	16:45:53	Administrator	3037	active reset button		
AT	06/03/2021	16:45:53	Administrator	3037	active reset button		
AT	06/03/2021	16:45:54	Administrator	3035	active start button		
€3	06/03/2021	16:46:04	Administrator	1011	Powder feeding time is too long		
AT	06/03/2021	16:46:19	Administrator	3037	active reset button		
AT	06/03/2021	16:46:20	Administrator	3037	active reset button		
AT	06/03/2021	16:46:28	Administrator	3037	active reset button		
ΑT	06/03/2021	16:46:28	Administrator	3037	active reset button		
AT	06/03/2021	16:46:28	Administrator	3037	active reset button		
ΑT	06/03/2021	16:46:33	Administrator	3037	active reset button		
AT	06/03/2021	16:46:33	Administrator	3037	active reset button		
€3	06/03/2021	16:46:33	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:46:34	Administrator	3037	active reset button		
€3	06/03/2021	16:46:34	Administrator	1005	Door and window open alarm		
AT	06/03/2021	16:46:35	Administrator	3037	active reset button		
AT	06/03/2021	16:46:35	Administrator	3037	active reset button		
AT	06/03/2021	16:46:36	Administrator	3037	active reset button		
ΑT	06/03/2021	16:46:37	Administrator	3037	active reset button		
AT	06/03/2021	16:46:38	Administrator	3037	active reset button		
AT	06/03/2021	16:46:59	Administrator	3037	active reset button		
AT	06/03/2021	16:46:59	Administrator	3037	active reset button		
AT	06/03/2021	16:46:59	Administrator	3037	active reset button		
AT	06/03/2021	16:47:01	Administrator	3035	active start button		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 40 / 47

_					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
€3	06/03/2021	16:47:11	Administrator	1011 Powder feeding time is too long		
₿	06/03/2021	16:47:19	Administrator	1005 Door and window open alarm		
₿	06/03/2021	16:47:19	Administrator	1011 Powder feeding time is too long		
AT	06/03/2021	16:47:49	Administrator	3037 active reset button		
₿	06/03/2021	16:47:49	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:47:49	Administrator	3037 active reset button		
€3	06/03/2021	16:47:49	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:47:49	Administrator	3037 active reset button		
8	06/03/2021	16:47:49	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:47:50	Administrator	3037 active reset button		
8	06/03/2021	16:47:50	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:47:50	Administrator	3037 active reset button		
×	06/03/2021	16:47:50	Administrator	1005 Door and window open alarm		
AT .	06/03/2021	16:47:51	Administrator	3037 active reset button		
<b>83</b>	06/03/2021	16:47:51	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:47:56	Administrator	3037 active reset button		
<b>83</b>	06/03/2021	16:47:56	Administrator	1005 Door and window open alarm		
<b>≅</b>	06/03/2021	16:47:56	Administrator	1005 Door and window open alarm		
<b>3</b>	06/03/2021	16:47:56	Administrator	1007 Inverter fault		
AT	06/03/2021	16:47:56	Administrator	3037 active reset button		
8	06/03/2021	16:47:56	Administrator	1007 Inverter fault		
AT	06/03/2021	16:47:56	Administrator	3037 active reset button		
8	06/03/2021	16:47:56	Administrator	1007 Inverter fault		
AT	06/03/2021	16:47:57	Administrator	3037 active reset button		
8	06/03/2021	16:47:57	Administrator	1007 Inverter fault		
AT .	06/03/2021	16:47:57	Administrator	3037 active reset button		
8	06/03/2021	16:48:04	Administrator	1005 Door and window open alarm		
<b>ΔT</b>	06/03/2021	16:48:06	Administrator	3037 active reset button		
<b>33</b>	06/03/2021	16:48:06	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:09	Administrator	3037 active reset button		
€3	06/03/2021	16:48:09	Administrator	1005 Door and window open alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 41 / 47

					Old value	New value
Туре	Date	Time	Operator	No. Description	Info 1	Info 2
AT	06/03/2021	16:48:09	Administrator	3037 active reset button		
€3	06/03/2021	16:48:09	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:10	Administrator	3037 active reset button		
8	06/03/2021	16:48:10	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:10	Administrator	3037 active reset button		
€3	06/03/2021	16:48:10	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:11	Administrator	3037 active reset button		
₿	06/03/2021	16:48:11	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:12	Administrator	3037 active reset button		
€3	06/03/2021	16:48:12	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:12	Administrator	3037 active reset button		
€3	06/03/2021	16:48:12	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:12	Administrator	3037 active reset button		
8	06/03/2021	16:48:12	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:13	Administrator	3037 active reset button		
€3	06/03/2021	16:48:13	Administrator	1005 Door and window open alarm		
AT	06/03/2021	16:48:13	Administrator	3037 active reset button		
₿_	06/03/2021	16:48:13	Administrator	1005 Door and window open alarm		
ΑT	06/03/2021	16:48:13	Administrator	3037 active reset button		
₿_	06/03/2021	16:48:13	Administrator	1005 Door and window open alarm		
₿	06/03/2021	16:48:13	Administrator	1005 Door and window open alarm		
₿_	06/03/2021	16:48:13	Administrator	1007 Inverter fault		
AT	06/03/2021	16:48:14	Administrator	3037 active reset button		
₿_	06/03/2021	16:48:14	Administrator	1007 Inverter fault		
AT	06/03/2021	16:48:14	Administrator	3037 active reset button		
₿_	06/03/2021	16:48:14	Administrator	1007 Inverter fault		
AT	06/03/2021	16:48:14	Administrator	3037 active reset button		
AT	06/03/2021	16:48:15	Administrator	3037 active reset button		
AT	06/03/2021	16:48:17	Administrator	3035 active start button		
❷_	06/03/2021	16:48:59	Administrator	1005 Door and window open alarm		
₿	06/03/2021	16:49:05	Administrator	1003 Hand wheel spin out alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 42 / 47

		_			Old value	New value
уре	Date	Time	Operator	No. Description	Info 1	Info 2
3	06/03/2021	16:49:05	Administrator	1005 Door and window open alarm		
Ī	06/03/2021	16:49:44	Administrator	3037 active reset button		
3	06/03/2021	16:49:44	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:49:44	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:49:44	Administrator	1007 Inverter fault		
VI.	06/03/2021	16:49:44	Administrator	3037 active reset button		
3	06/03/2021	16:49:45	Administrator	1007 Inverter fault		
Ū	06/03/2021	16:49:45	Administrator	3037 active reset button		
3	06/03/2021	16:49:45	Administrator	1007 Inverter fault		
Ī	06/03/2021	16:49:45	Administrator	3037 active reset button		
3	06/03/2021	16:49:45	Administrator	1007 Inverter fault		
Ī	06/03/2021	16:49:45	Administrator	3037 active reset button		
•	06/03/2021	16:49:45	Administrator	1007 Inverter fault		
Ī	06/03/2021	16:49:45	Administrator	3037 active reset button		
3	06/03/2021	16:49:45	Administrator	1007 Inverter fault		
Ī	06/03/2021	16:49:46	Administrator	3037 active reset button		
	06/03/2021	16:49:46	Administrator	3037 active reset button		
Ī	06/03/2021	16:49:47	Administrator	3037 active reset button		
I	06/03/2021	16:49:48	Administrator	3035 active start button		
3	06/03/2021	16:50:48	Administrator	1012 Material supply interval is too long		
3	06/03/2021	16:52:14	Administrator	1004 Emergency stop alarm		
3	06/03/2021	16:52:14	Administrator	1012 Material supply interval is too long		
3	06/03/2021	16:52:15	Administrator	1004 Emergency stop alarm		
3	06/03/2021	16:52:15	Administrator	1005 Door and window open alarm		
3	06/03/2021	16:52:15	Administrator	1012 Material supply interval is too long		
•	06/03/2021	17:15:25	Administrator	1004 Emergency stop alarm		
	06/03/2021	17:15:25	Administrator	1005 Door and window open alarm		
•	06/03/2021	17:15:25	Administrator	1012 Material supply interval is too long		
3	06/03/2021	17:15:25	Administrator	1033 Batch not set		
Ū	06/03/2021	17:17:11	Administrator	3033 Create batch	123sat	pq030621for3
3	06/03/2021	17:17:32	Administrator	1004 Emergency stop alarm		



Batch: pq030621format3

Date printed: 06/03/2021 Time printed: 17:22:40 Page 43 / 47

					Old value	New value
Гуре	Date	Time	Operator	No. Description	Info 1	Info 2
8	06/03/2021	17:17:32	Administrator	1005 Door and window open alarm		
8	06/03/2021	17:17:32	Administrator	1009 Insufficient vacuum pressure		
8	06/03/2021	17:17:32	Administrator	1012 Material supply interval is too long		
8	06/03/2021	17:17:32	Administrator	1033 Batch not set		
8 8	06/03/2021	17:18:01	Administrator	1004 Emergency stop alarm		
8	06/03/2021	17:18:01	Administrator	1005 Door and window open alarm		
8	06/03/2021	17:18:01	Administrator	1009 Insufficient vacuum pressure		
8	06/03/2021	17:18:01	Administrator	1010 Insufficient of empty capsules		
₿	06/03/2021	17:18:01	Administrator	1012 Material supply interval is too long		
8	06/03/2021	17:18:01	Administrator	1033 Batch not set		
АТ	06/03/2021	17:19:01	Administrator	3001 Speed adjust	2600	2600
<b>AT</b>	06/03/2021	17:20:14	Administrator	3037 active reset button		
3	06/03/2021	17:20:14	Administrator	1004 Emergency stop alarm		
3	06/03/2021	17:20:14	Administrator	1005 Door and window open alarm		
3	06/03/2021	17:20:14	Administrator	1009 Insufficient vacuum pressure		
AΤ	06/03/2021	17:20:15	Administrator	3037 active reset button		
3	06/03/2021	17:20:15	Administrator	1004 Emergency stop alarm		
3	06/03/2021	17:20:15	Administrator	1005 Door and window open alarm		
3	06/03/2021	17:20:15	Administrator	1009 Insufficient vacuum pressure		
<b>AT</b>	06/03/2021	17:20:15	Administrator	3037 active reset button		
3	06/03/2021	17:20:15	Administrator	1004 Emergency stop alarm		
3	06/03/2021	17:20:15	Administrator	1005 Door and window open alarm		
3	06/03/2021	17:20:16	Administrator	1009 Insufficient vacuum pressure		
AT.	06/03/2021	17:20:16	Administrator	3037 active reset button		
3	06/03/2021	17:20:16	Administrator	1004 Emergency stop alarm		
3	06/03/2021	17:20:16	Administrator	1005 Door and window open alarm		
3	06/03/2021	17:20:16	Administrator	1009 Insufficient vacuum pressure		
VI.	06/03/2021	17:20:16	Administrator	3037 active reset button		
3	06/03/2021	17:20:16	Administrator	1004 Emergency stop alarm		
3	06/03/2021	17:20:16	Administrator	1005 Door and window open alarm		
<u>.</u>	06/03/2021	17:20:16	Administrator	1009 Insufficient vacuum pressure		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 44 / 47

							Old value	New value
Туре	Date	Time	Operator	No.	Description		Info 1	Info 2
AT	06/03/2021	17:20:16	Administrator	3037	active reset button			
€3	06/03/2021	17:20:16	Administrator	1004	Emergency stop alarm			
€3	06/03/2021	17:20:17	Administrator	1005	Door and window open alarm			
€3	06/03/2021	17:20:17	Administrator	1009	Insufficient vacuum pressure			
AT	06/03/2021	17:20:17	Administrator	3037	active reset button			
€3	06/03/2021	17:20:17	Administrator	1004	Emergency stop alarm			
€3	06/03/2021	17:20:17	Administrator	1005	Door and window open alarm			
₿	06/03/2021	17:20:17	Administrator	1009	Insufficient vacuum pressure			
AT	06/03/2021	17:20:17	Administrator	3037	active reset button			
₿	06/03/2021	17:20:18	Administrator	1004	Emergency stop alarm			
€3	06/03/2021	17:20:18	Administrator	1005	Door and window open alarm			
₿	06/03/2021	17:20:18	Administrator	1009	Insufficient vacuum pressure			
AT	06/03/2021	17:20:18	Administrator	3037	active reset button			
₿	06/03/2021	17:20:18	Administrator	1004	Emergency stop alarm			
8	06/03/2021	17:20:18	Administrator	1005	Door and window open alarm			
₿	06/03/2021	17:20:18	Administrator	1009	Insufficient vacuum pressure			
AT	06/03/2021	17:20:18	Administrator	3037	active reset button			
₿	06/03/2021	17:20:18	Administrator	1004	Emergency stop alarm			
₿	06/03/2021	17:20:18	Administrator	1005	Door and window open alarm			
₿	06/03/2021	17:20:19	Administrator	1009	Insufficient vacuum pressure			
AT	06/03/2021	17:20:19	Administrator	3037	active reset button			
₿	06/03/2021	17:20:19	Administrator	1004	Emergency stop alarm			
8	06/03/2021	17:20:19	Administrator	1005	Door and window open alarm			
₿	06/03/2021	17:20:19	Administrator	1009	Insufficient vacuum pressure			
AT	06/03/2021	17:20:19	Administrator	3037	active reset button			
€	06/03/2021	17:20:19	Administrator	1004	Emergency stop alarm			
€3	06/03/2021	17:20:19	Administrator	1005	Door and window open alarm			
€	06/03/2021	17:20:19	Administrator	1009	Insufficient vacuum pressure			
AT	06/03/2021	17:20:19	Administrator	3037	active reset button			
₿	06/03/2021	17:20:19	Administrator	1004	Emergency stop alarm			
€3	06/03/2021	17:20:19	Administrator	1005	Door and window open alarm			



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 45 / 47

						Old value	New value
Туре	Date	Time	Operator	No.	Description	Info 1	Info 2
€3	06/03/2021	17:20:20	Administrator	1009	Insufficient vacuum pressure		
AT	06/03/2021	17:20:20	Administrator	3037	active reset button		
€3	06/03/2021	17:20:20	Administrator	1004	Emergency stop alarm		
₿	06/03/2021	17:20:20	Administrator	1005	Door and window open alarm		
Ø	06/03/2021	17:20:20	Administrator	1009	Insufficient vacuum pressure		
AT	06/03/2021	17:20:21	Administrator	3037	active reset button		
€	06/03/2021	17:20:21	Administrator	1004	Emergency stop alarm		
€3	06/03/2021	17:20:21	Administrator	1005	Door and window open alarm		
₿	06/03/2021	17:20:21	Administrator	1009	Insufficient vacuum pressure		
AT	06/03/2021	17:20:21	Administrator	3037	active reset button		
€	06/03/2021	17:20:21	Administrator	1004	Emergency stop alarm		
€3	06/03/2021	17:20:21	Administrator	1005	Door and window open alarm		
€3	06/03/2021	17:20:21	Administrator	1009	Insufficient vacuum pressure		
AT	06/03/2021	17:20:25	Administrator	3037	active reset button		
€	06/03/2021	17:20:25	Administrator	1004	Emergency stop alarm		
€3	06/03/2021	17:20:25	Administrator	1005	Door and window open alarm		
€	06/03/2021	17:20:25	Administrator	1009	Insufficient vacuum pressure		
AT	06/03/2021	17:20:25	Administrator	3037	active reset button		
€3	06/03/2021	17:20:25	Administrator	1004	Emergency stop alarm		
€3	06/03/2021	17:20:25	Administrator	1005	Door and window open alarm		
€3	06/03/2021	17:20:25	Administrator	1009	Insufficient vacuum pressure		
AT	06/03/2021	17:20:25	Administrator	3037	active reset button		
€3	06/03/2021	17:20:25	Administrator	1004	Emergency stop alarm		
€3	06/03/2021	17:20:25	Administrator	1005	Door and window open alarm		
₿	06/03/2021	17:20:25	Administrator	1009	Insufficient vacuum pressure		
AT	06/03/2021	17:20:25	Administrator	3037	active reset button		
€3	06/03/2021	17:20:25	Administrator	1004	Emergency stop alarm		
Ö	06/03/2021	17:20:25	Administrator	1005	Door and window open alarm		
Ċ.	06/03/2021	17:20:25	Administrator	1009	Insufficient vacuum pressure		
AT	06/03/2021	17:20:26	Administrator	3037	active reset button		
€3	06/03/2021	17:20:26	Administrator	1004	Emergency stop alarm		



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 46 / 47

							Old value	New value
Туре	Date	Time	Operator	No.	Description		Info 1	Info 2
€3	06/03/2021	17:20:26	Administrator	100	5 Door and window open alarm	1		
<b>€</b>	06/03/2021	17:20:26	Administrator	100	9 Insufficient vacuum pressure			
AT	06/03/2021	17:20:26	Administrator	303	7 active reset button			
€3	06/03/2021	17:20:26	Administrator	100	4 Emergency stop alarm			
€3	06/03/2021	17:20:26	Administrator	100	5 Door and window open alarm	1		
€3	06/03/2021	17:20:26	Administrator	100	9 Insufficient vacuum pressure			
AT	06/03/2021	17:20:26	Administrator	303	7 active reset button			
₿	06/03/2021	17:20:26	Administrator	100	4 Emergency stop alarm			
€3	06/03/2021	17:20:26	Administrator	100	5 Door and window open alarm	1		
₿	06/03/2021	17:20:27	Administrator	100	9 Insufficient vacuum pressure			
AT	06/03/2021	17:20:27	Administrator	303	7 active reset button			
₿	06/03/2021	17:20:27	Administrator	100	4 Emergency stop alarm			
8	06/03/2021	17:20:27	Administrator	100	5 Door and window open alarm	1		
₿	06/03/2021	17:20:27	Administrator	100	9 Insufficient vacuum pressure			
AT	06/03/2021	17:20:31	Administrator	303	7 active reset button			
₿	06/03/2021	17:20:31	Administrator	100	4 Emergency stop alarm			
₿	06/03/2021	17:20:32	Administrator	100	5 Door and window open alarm	1		
₿	06/03/2021	17:20:32	Administrator	100	9 Insufficient vacuum pressure			
AT	06/03/2021	17:20:32	Administrator	303	7 active reset button			
₿	06/03/2021	17:20:32	Administrator	100	4 Emergency stop alarm			
₿	06/03/2021	17:20:32	Administrator	100	5 Door and window open alarm	1		
₿	06/03/2021	17:20:32	Administrator	100	9 Insufficient vacuum pressure			
AT	06/03/2021	17:20:32	Administrator	303	7 active reset button			
₿	06/03/2021	17:20:32	Administrator	100	4 Emergency stop alarm			
₿	06/03/2021	17:20:32	Administrator	100	5 Door and window open alarm	1		
₿	06/03/2021	17:20:32	Administrator	100	9 Insufficient vacuum pressure			
AT	06/03/2021	17:20:41	Administrator	303	7 active reset button			
€3	06/03/2021	17:20:42	Administrator	100	5 Door and window open alarm	1		
€3	06/03/2021	17:20:42	Administrator	100	9 Insufficient vacuum pressure			
₿	06/03/2021	17:20:42	Administrator	100	5 Door and window open alarm	1		
8	06/03/2021	17:20:42	Administrator	100	7 Inverter fault			



Batch: pq030621format3

| Date printed: 06/03/2021 | Time printed: 17:22:40 | Page 47 / 47

							Old value	New value
Туре	Date	Time	Operator	No.	Description		Info 1	Info 2
€3	06/03/2021	17:20:42	Administrator	1009	Insufficient vacuum pressure	e		
AT	06/03/2021	17:20:42	Administrator	3037	active reset button			
€3	06/03/2021	17:20:42	Administrator	1007	Inverter fault			
<b>3</b>	06/03/2021	17:20:42	Administrator	1009	Insufficient vacuum pressure	е		
AT	06/03/2021	17:20:44	Administrator	3037	active reset button			
AT	06/03/2021	17:20:44	Administrator	3037	active reset button			
AT	06/03/2021	17:20:44	Administrator	3037	active reset button			
8	06/03/2021	17:20:59	Administrator	1033	Batch not set			
8	06/03/2021	17:21:11	Administrator	1009	Insufficient vacuum pressure	е		
8	06/03/2021	17:21:11	Administrator	1033	Batch not set			
AT	06/03/2021	17:21:27	Administrator	3033	3 Create batch		pq030621for3	pq03062021format3
AT	06/03/2021	17:22:19	Administrator	3033	3 Create batch		pq03062021format3	pq030621format3