



**b** Across the full protocol

clean-adjusted  $X_{\text{opp}}$  drop  $0.0070 \pm 0.0015$

wrong-direction timesteps  $-0.74$  pp

clean aligned command kept  $96.1\%$

torque rate  $+18\%$  to  $+28\%$

