Continuity testing: there *should* be continuity between these pins.

fritzing