## DATA TRACK QUALITY INDEX

TITIK AWAL: BEKASI

**KM AWAL: 10.0** 

**TITIK AKHIR: HALIM** 

KM AKHIR: 17

Lines	Km Awal	Meter Awal	Km Akhir	Meter Akhir	Track Length	TQI_PROF	TQI_ALIGN	TQI_GAGE	TQI_XLEVEL	TQI_TWIST	TQI Total KAI	Class
Line 3	10	0	10	20	20	0.0	0.0	0.88	2.37	5.0	8.25	Very Good
Line 3	10	20	10	40	20	0.71	1.09	0.68	2.53	1.63	6.65	Very Good
Line 3	10	40	10	60	20	1.67	3.18	0.66	1.17	0.92	7.59	Very Good
Line 3	10	60	10	80	20	2.28	2.32	0.59	1.19	0.71	7.09	Very Good
Line 3	10	80	10	100	20	5.43	1.69	0.97	0.61	1.16	9.86	Very Good
Line 3	10	100	10	120	20	4.58	0.78	0.65	0.73	0.99	7.73	Very Good
Line 3	10	120	10	140	20	6.54	0.85	0.79	2.15	1.69	12.02	Very Good
Line 3	10	140	10	160	20	2.1	1.41	0.95	1.07	1.35	6.89	Very Good
Line 3	10	160	10	180	20	3.94	3.37	0.66	1.52	2.25	11.74	Very Good
Line 3	10	180	10	200	20	4.54	2.95	1.07	5.13	5.84	19.53	Very Good
Line 3	10	200	10	220	20	2.08	2.39	0.63	1.4	3.47	9.97	Very Good
Line 3	10	220	10	240	20	1.22	2.34	1.09	2.19	2.52	9.36	Very Good
Line 3	10	240	10	260	20	1.68	2.67	0.45	1.56	1.51	7.88	Very Good
Line 3	10	260	10	280	20	1.82	1.57	0.59	1.47	1.73	7.18	Very Good
Line 3	10	280	10	300	20	1.93	3.87	0.89	2.91	3.9	13.51	Very Good
Line 3	10	300	10	320	20	0.69	2.48	1.54	0.96	0.67	6.35	Very Good
Line 3	10	320	10	340	20	0.63	2.34	1.03	0.62	0.78	5.41	Very Good
Line 3	10	340	10	360	20	1.01	1.55	1.04	1.15	1.07	5.82	Very Good
Line 3	10	360	10	380	20	0.86	1.87	0.88	0.49	0.98	5.07	Very Good
Line 3	10	380	10	400	20	1.97	1.52	1.01	0.45	0.83	5.78	Very Good

Line 3	10	400	10	420	20	0.65	1.01	1.01	0.73	0.82	4.23	Very Good
Line 3	10	420	10	440	20	1.14	1.41	0.63	1.57	2.57	7.33	Very Good
Line 3	10	440	10	460	20	1.88	1.99	0.63	0.9	1.51	6.91	Very Good
Line 3	10	460	10	480	20	1.15	0.8	0.7	0.52	0.61	3.78	Very Good
Line 3	10	480	10	500	20	1.88	1.93	0.88	0.46	0.78	5.92	Very Good
Line 3	10	500	10	520	20	0.68	0.23	0.69	0.73	1.13	3.46	Very Good
Line 3	10	520	10	540	20	0.97	0.0	0.35	0.47	0.77	2.55	Very Good
Line 3	10	540	10	560	20	1.43	0.0	0.74	0.55	0.84	3.56	Very Good
Line 3	10	560	10	580	20	1.1	0.0	0.57	0.59	0.83	3.1	Very Good
Line 3	10	580	10	600	20	1.32	0.0	0.69	0.67	1.35	4.03	Very Good
Line 3	10	600	10	620	20	0.95	0.0	0.87	0.73	0.77	3.33	Very Good
Line 3	10	620	10	640	20	0.0	0.0	0.63	0.69	1.01	2.34	Very Good
Line 3	10	640	10	660	20	0.0	0.0	0.68	0.61	1.0	2.29	Very Good
Line 3	10	660	10	680	20	0.0	0.0	1.13	1.83	1.82	4.78	Very Good
Line 3	10	680	10	700	20	0.0	0.0	2.2	1.91	4.37	8.48	Very Good
Line 3	10	700	10	720	20	0.0	0.0	4.17	4.07	5.78	14.02	Very Good
Line 3	10	720	10	740	20	0.0	0.0	2.56	1.76	3.49	7.81	Very Good
Line 3	10	740	10	760	20	0.0	0.0	1.1	2.67	2.59	6.37	Very Good
Line 3	10	760	10	780	20	0.0	0.0	2.6	4.6	3.73	10.93	Very Good
Line 3	10	780	10	800	20	0.0	0.0	4.11	3.27	5.84	13.23	Very Good
Line 3	10	800	10	820	20	0.0	0.0	3.26	2.61	4.22	10.09	Very Good
Line 3	10	820	10	840	20	9.45	0.0	0.71	1.12	1.32	12.6	Very Good
Line 3	10	840	10	860	20	2.55	0.0	0.68	1.5	1.36	6.09	Very Good
Line 3	10	860	10	880	20	2.75	0.0	1.6	3.2	3.49	11.05	Very Good
Line 3	10	880	10	900	20	1.74	0.0	0.62	0.64	2.91	5.91	Very Good
Line 3	10	900	10	920	20	3.29	0.0	0.47	1.01	1.28	6.06	Very Good
Line 3	10	920	10	940	20	3.6	0.0	0.77	0.74	1.27	6.37	Very Good
Line 3	10	940	10	960	20	4.23	0.0	0.68	0.83	1.18	6.92	Very Good
Line 3	10	960	10	980	20	3.66	0.0	0.72	1.01	1.12	6.52	Very Good
Line 3	10	980	11	0	20	1.1	0.0	0.61	0.73	1.32	3.76	Very Good
					1							

The State   11													
Line   11	Line 3	11	0	11	20	20	1.94	0.0	0.86	0.78	0.96	4.54	Very Good
Line 3	Line 3	11	20	11	40	20	1.7	0.0	0.8	0.83	1.23	4.56	Very Good
Line 3	Line 3	11	40	11	60	20	2.73	0.0	0.63	0.66	0.82	4.84	Very Good
Line 3	Line 3	11	60	11	80	20	7.58	2.73	0.39	0.74	0.92	12.36	Very Good
Line 3	Line 3	11	80	11	100	20	2.03	0.82	0.52	1.17	1.0	5.54	Very Good
Lima	Line 3	11	100	11	120	20	1.31	0.86	0.77	0.89	0.82	4.64	Very Good
Line 3	Line 3	11	120	11	140	20	1.57	0.0	1.03	0.54	0.77	3.9	Very Good
Line 3	Line 3	11	140	11	160	20	3.66	0.0	0.56	0.42	0.59	5.23	Very Good
Line 3	Line 3	11	160	11	180	20	2.29	0.0	0.59	0.49	0.61	3.99	Very Good
Line 3 11 220 11 240 20 4.41 0.0 0.82 1.51 1.88 8.62 Very Good Line 3 11 240 11 260 20 4.74 0.0 0.88 0.55 1.08 7.33 Very Good Line 3 11 280 11 380 20 1.47 0.0 0.61 0.77 1.21 5.97 Very Good Line 3 11 320 11 330 20 11 330 0.0 0.61 0.77 1.21 5.97 Very Good Line 3 11 320 11 330 20 20 3.08 0.0 0.64 2.34 3.3 9.36 Very Good Line 3 11 320 11 340 20 4.88 0.0 0.64 2.34 3.3 9.36 Very Good Line 3 11 340 11 360 20 4.88 0.0 0.66 7.34 0.73 13.51 Very Good Line 3 11 340 11 360 20 2.1 0.0 0.62 8.0 0.98 11.69 Very Good Line 3 11 380 11 380 20 3.33 0.0 0.85 1.44 2.95 8.37 Very Good Line 3 11 380 11 400 20 3.74 0.0 0.85 1.44 2.95 8.37 Very Good Line 3 11 400 11 420 20 1.98 0.0 0.8 0.99 1.13 4.91 Very Good Line 3 11 440 11 440 20 1.87 0.0 0.87 0.78 0.77 1.105 4.46 Very Good Line 3 11 440 11 440 20 1.87 0.0 0.87 0.78 0.77 1.105 4.46 Very Good Line 3 11 460 11 480 20 1.88 0.0 0.87 0.48 0.99 1.13 4.91 Very Good Line 3 11 460 11 480 20 1.88 0.0 0.87 0.48 0.92 3.34 1.89 2.71 7.72 Very Good Line 3 11 460 11 480 20 1.88 0.0 0.87 0.48 0.92 3.34 1.89 2.71 7.72 Very Good Line 3 11 460 11 480 20 1.88 0.0 0.87 0.48 0.53 1.88 2.71 7.72 Very Good Line 3 11 460 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 500 11 500 20 3.42 1.8 0.84 1.15 1.15 6.53 2.33 15.16 Very Good Line 3 11 500 11 500 11 5	Line 3	11	180	11	200	20	1.18	0.0	0.7	0.54	0.83	3.25	Very Good
Line 3 11 240 11 280 20 4.74 0.0 0.98 0.55 1.06 7.33 Very Good Line 3 11 260 11 280 20 3.39 0.0 0.61 0.77 121 5.97 Very Good Line 3 11 300 11 320 20 3.08 0.0 0.61 0.77 121 5.97 Very Good Line 3 11 320 11 340 20 4.08 0.0 0.64 2.34 3.3 9.36 Very Good Line 3 11 340 11 360 20 20 3.08 0.0 0.64 2.34 3.3 9.36 Very Good Line 3 11 340 11 360 20 4.08 0.0 0.62 8.0 0.98 11.69 Very Good Line 3 11 380 11 380 20 3.33 0.0 0.62 8.0 0.98 11.69 Very Good Line 3 11 380 11 400 20 3.74 0.0 0.65 1.44 2.95 8.37 Very Good Line 3 11 400 11 420 20 1.98 0.0 0.8 0.99 1.13 4.91 Very Good Line 3 11 440 11 440 20 1.87 0.0 0.8 0.99 1.13 4.91 Very Good Line 3 11 440 11 460 20 1.87 0.0 0.8 0.99 1.13 4.91 Very Good Line 3 11 440 11 480 20 1.87 0.0 0.8 0.99 1.13 4.8 0.77 1.05 4.46 Very Good Line 3 11 440 11 480 20 1.88 0.0 0.87 0.46 0.92 3.84 Very Good Line 3 11 440 11 480 20 1.98 0.0 0.8 0.99 1.13 4.8 2.71 7.72 Very Good Line 3 11 480 11 480 20 1.98 0.0 0.87 0.46 0.92 3.84 Very Good Line 3 11 480 11 480 20 1.98 0.0 0.87 0.46 0.92 3.84 Very Good Line 3 11 480 11 480 20 1.98 0.0 0.8 0.99 1.15 1.8 2.71 7.72 Very Good Line 3 11 480 11 480 20 1.98 0.0 0.87 0.46 0.92 3.84 Very Good Line 3 11 500 11 500 20 3.42 1.8 0.72 4.72 3.42 11.40 Very Good Line 3 11 500 11 500 20 1.96 0.64 0.53 1.88 2.71 7.72 Very Good Line 3 11 500 11 500 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good Line 3 11 500 11 500 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good Line 3 11 540 11 560 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good Line 3 11 540 11 560 20 1.15 1.19 1.38 0.97 3.0 3.0 2.57 0.11 Very Good Line 3 11 540 11 560 20 1.15 1.19 1.38 0.97 3.0 3.0 2.57 0.11 Very Good Line 3 11 540 11 560 20 1.15 1.19 1.38 0.97 3.0 3.0 2.57 0.11 Very Good Line 3 11 540 11 560 20 1.15 1.19 1.38 0.97 3.0 3.0 2.57 0.11 Very Good Line 3 11 540 11 560 20 1.15 1.19 1.38 0.97 3.0 3.0 2.57 0.11 Very Good Line 3 11 560 11 560 20 1.15 1.19 1.19 1.19 1.19 1.19 1.19 1.19	Line 3	11	200	11	220	20	3.37	0.0	0.7	1.02	1.54	6.63	Very Good
Line 3	Line 3	11	220	11	240	20	4.41	0.0	0.82	1.51	1.88	8.62	Very Good
Line 3	Line 3	11	240	11	260	20	4.74	0.0	0.98	0.55	1.06	7.33	Very Good
Line 3         111         300         111         320         20         3.08         0.0         0.64         2.34         3.3         9.38         Very Good           Line 3         111         320         111         340         20         4.08         0.0         0.76         7.94         0.73         13.51         Very Good           Line 3         111         340         111         360         20         2.1         0.0         0.62         8.0         0.98         11.69         Very Good           Line 3         111         360         11         380         20         3.33         0.0         0.65         1.44         2.95         8.37         Very Good           Line 3         11         400         20         3.74         0.0         0.45         0.96         1.35         6.5         Very Good           Line 3         11         400         11         420         20         1.98         0.0         0.8         0.99         1.13         4.91         Very Good           Line 3         11         420         11         440         20         1.87         0.0         0.78         0.77         1.05         4.46 <td>Line 3</td> <td>11</td> <td>260</td> <td>11</td> <td>280</td> <td>20</td> <td>3.39</td> <td>0.0</td> <td>0.61</td> <td>0.77</td> <td>1.21</td> <td>5.97</td> <td>Very Good</td>	Line 3	11	260	11	280	20	3.39	0.0	0.61	0.77	1.21	5.97	Very Good
Line 3         11         320         11         340         20         4.08         0.0         0.76         7.94         0.73         13.51         Very Good           Line 3         11         340         11         360         20         2.1         0.0         0.62         8.0         0.98         11.69         Very Good           Line 3         11         360         11         380         20         3.33         0.0         0.65         1.44         2.95         8.37         Very Good           Line 3         11         380         11         400         20         3.74         0.0         0.45         0.96         1.35         6.5         Very Good           Line 3         11         400         11         420         20         1.98         0.0         0.8         0.99         1.13         4.91         Very Good           Line 3         11         420         11         440         20         1.87         0.0         0.78         0.77         1.05         4.46         Very Good           Line 3         11         440         11         480         20         1.58         0.0         0.87         0.46	Line 3	11	280	11	300	20	1.47	0.0	0.76	0.65	1.46	4.34	Very Good
Line 3 11 340 11 380 20 2.1 0.0 0.82 8.0 0.98 11.68 Very Good Line 3 11 360 11 380 20 3.33 0.0 0.65 1.44 2.95 8.37 Very Good Line 3 11 380 11 400 20 3.74 0.0 0.45 0.96 1.35 6.5 Very Good Line 3 11 400 11 420 20 1.98 0.0 0.8 0.99 1.13 4.91 Very Good Line 3 11 420 11 440 20 1.87 0.0 0.78 0.77 1.05 4.46 Very Good Line 3 11 440 11 480 20 1.58 0.0 0.87 0.46 0.92 3.84 Very Good Line 3 11 460 11 480 20 1.96 0.64 0.53 1.88 2.71 7.72 Very Good Line 3 11 480 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 550 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good Line 3 11 540 11 560 20 1.19 1.36 0.97 3.03 2.57 9.11 Very Good Line 3 11 560 11 580 20 1.19 1.36 0.97 3.03 2.57 9.11 Very Good Line 3 11 560 11 580 20 1.19 1.36 0.97 3.03 2.57 9.11 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good	Line 3	11	300	11	320	20	3.08	0.0	0.64	2.34	3.3	9.36	Very Good
Line 3 11 360 11 380 20 3.33 0.0 0.65 1.44 2.95 8.37 Very Good Line 3 11 380 11 400 20 3.74 0.0 0.45 0.96 1.35 6.5 Very Good Line 3 11 400 11 420 20 1.98 0.0 0.8 0.99 1.13 4.91 Very Good Line 3 11 420 11 440 20 1.87 0.0 0.78 0.77 1.05 4.46 Very Good Line 3 11 440 11 460 20 1.87 0.0 0.87 0.46 0.92 3.84 Very Good Line 3 11 440 11 480 20 1.58 0.0 0.87 0.46 0.92 3.84 Very Good Line 3 11 460 11 480 20 1.96 0.64 0.53 1.88 2.71 7.72 Very Good Line 3 11 480 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 520 20 2.73 0.96 1.09 9.5 1.6 15.88 Very Good Line 3 11 500 11 540 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good Line 3 11 500 11 540 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good Line 3 11 500 11 540 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good Line 3 11 500 11 560 20 1.19 1.36 0.97 3.03 2.57 9.11 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 20 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good Line 3 11 560 20 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good 20 1.54 1.44 1.45 1.44 1.45 1.45 1.45 1.45	Line 3	11	320	11	340	20	4.08	0.0	0.76	7.94	0.73	13.51	Very Good
Line 3 11 380 11 400 20 3.74 0.0 0.45 0.96 1.35 6.5 Very Good  Line 3 11 400 11 420 20 1.98 0.0 0.8 0.99 1.13 4.91 Very Good  Line 3 11 420 11 440 20 1.87 0.0 0.78 0.77 1.05 4.46 Very Good  Line 3 11 440 11 460 20 1.58 0.0 0.87 0.46 0.92 3.84 Very Good  Line 3 11 460 11 480 20 1.96 0.64 0.53 1.88 2.71 7.72 Very Good  Line 3 11 480 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good  Line 3 11 500 11 520 20 2.73 0.96 1.09 9.5 1.6 15.88 Very Good  Line 3 11 520 11 540 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good  Line 3 11 560 11 580 20 1.99 1.36 0.97 3.03 2.57 9.11 Very Good  Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good	Line 3	11	340	11	360	20	2.1	0.0	0.62	8.0	0.98	11.69	Very Good
Line 3 11 400 11 420 20 1.98 0.0 0.8 0.99 1.13 4.91 Very Good Line 3 11 420 11 440 20 1.87 0.0 0.78 0.77 1.05 4.46 Very Good Line 3 11 440 11 460 20 1.58 0.0 0.87 0.46 0.92 3.84 Very Good Line 3 11 460 11 480 20 1.96 0.64 0.53 1.88 2.71 7.72 Very Good Line 3 11 480 11 500 20 3.42 1.8 0.72 4.72 3.42 14.08 Very Good Line 3 11 500 11 520 20 2.73 0.96 1.09 9.5 1.6 15.88 Very Good Line 3 11 520 11 540 20 1.3 2.14 1.15 8.25 2.33 15.16 Very Good Line 3 11 540 11 560 20 1.19 1.36 0.97 3.03 2.57 9.11 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good	Line 3	11	360	11	380	20	3.33	0.0	0.65	1.44	2.95	8.37	Very Good
Line 3       11       420       11       440       20       1.87       0.0       0.78       0.77       1.05       4.46       Very Good         Line 3       11       440       11       460       20       1.58       0.0       0.87       0.46       0.92       3.84       Very Good         Line 3       11       460       11       480       20       1.96       0.64       0.53       1.88       2.71       7.72       Very Good         Line 3       11       480       11       500       20       3.42       1.8       0.72       4.72       3.42       14.08       Very Good         Line 3       11       500       11       520       20       2.73       0.96       1.09       9.5       1.6       15.88       Very Good         Line 3       11       520       11       540       20       1.3       2.14       1.15       8.25       2.33       15.16       Very Good         Line 3       11       540       11       560       20       1.19       1.36       0.97       3.03       2.57       9.11       Very Good         Line 3       11       560       11	Line 3	11	380	11	400	20	3.74	0.0	0.45	0.96	1.35	6.5	Very Good
Line 3       11       440       11       460       20       1.58       0.0       0.87       0.46       0.92       3.84       Very Good         Line 3       11       460       11       480       20       1.96       0.64       0.53       1.88       2.71       7.72       Very Good         Line 3       11       480       11       500       20       3.42       1.8       0.72       4.72       3.42       14.08       Very Good         Line 3       11       500       11       520       20       2.73       0.96       1.09       9.5       1.6       15.88       Very Good         Line 3       11       520       11       540       20       1.3       2.14       1.15       8.25       2.33       15.16       Very Good         Line 3       11       540       11       560       20       1.19       1.36       0.97       3.03       2.57       9.11       Very Good         Line 3       11       560       11       580       20       1.54       1.43       0.84       1.25       1.26       6.32       Very Good	Line 3	11	400	11	420	20	1.98	0.0	0.8	0.99	1.13	4.91	Very Good
Line 3         11         460         11         480         20         1.96         0.64         0.53         1.88         2.71         7.72         Very Good           Line 3         11         480         11         500         20         3.42         1.8         0.72         4.72         3.42         14.08         Very Good           Line 3         11         500         11         520         20         2.73         0.96         1.09         9.5         1.6         15.88         Very Good           Line 3         11         520         11         540         20         1.3         2.14         1.15         8.25         2.33         15.16         Very Good           Line 3         11         540         11         560         20         1.19         1.36         0.97         3.03         2.57         9.11         Very Good           Line 3         11         560         11         580         20         1.54         1.43         0.84         1.25         1.26         6.32         Very Good	Line 3	11	420	11	440	20	1.87	0.0	0.78	0.77	1.05	4.46	Very Good
Line 3         11         480         11         500         20         3.42         1.8         0.72         4.72         3.42         14.08         Very Good           Line 3         11         500         11         520         20         2.73         0.96         1.09         9.5         1.6         15.88         Very Good           Line 3         11         520         11         540         20         1.3         2.14         1.15         8.25         2.33         15.16         Very Good           Line 3         11         540         11         560         20         1.19         1.36         0.97         3.03         2.57         9.11         Very Good           Line 3         11         560         11         580         20         1.54         1.43         0.84         1.25         1.26         6.32         Very Good	Line 3	11	440	11	460	20	1.58	0.0	0.87	0.46	0.92	3.84	Very Good
Line 3         11         500         11         520         20         2.73         0.96         1.09         9.5         1.6         15.88         Very Good           Line 3         11         520         11         540         20         1.3         2.14         1.15         8.25         2.33         15.16         Very Good           Line 3         11         540         11         560         20         1.19         1.36         0.97         3.03         2.57         9.11         Very Good           Line 3         11         560         11         580         20         1.54         1.43         0.84         1.25         1.26         6.32         Very Good	Line 3	11	460	11	480	20	1.96	0.64	0.53	1.88	2.71	7.72	Very Good
Line 3         11         520         11         540         20         1.3         2.14         1.15         8.25         2.33         15.16         Very Good           Line 3         11         540         11         560         20         1.19         1.36         0.97         3.03         2.57         9.11         Very Good           Line 3         11         560         11         580         20         1.54         1.43         0.84         1.25         1.26         6.32         Very Good	Line 3	11	480	11	500	20	3.42	1.8	0.72	4.72	3.42	14.08	Very Good
Line 3 11 540 11 560 20 1.19 1.36 0.97 3.03 2.57 9.11 Very Good Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good	Line 3	11	500	11	520	20	2.73	0.96	1.09	9.5	1.6	15.88	Very Good
Line 3 11 560 11 580 20 1.54 1.43 0.84 1.25 1.26 6.32 Very Good	Line 3	11	520	11	540	20	1.3	2.14	1.15	8.25	2.33	15.16	Very Good
	Line 3	11	540	11	560	20	1.19	1.36	0.97	3.03	2.57	9.11	Very Good
Line 3 11 580 11 600 20 2.47 1.68 1.24 3.88 2.13 11.4 Very Good	Line 3	11	560	11	580	20	1.54	1.43	0.84	1.25	1.26	6.32	Very Good
	Line 3	11	580	11	600	20	2.47	1.68	1.24	3.88	2.13	11.4	Very Good

				1	1		1		1	1		$\overline{}$
Line 3	11	600	11	620	20	2.37	1.07	0.67	3.81	0.98	8.9	Very Good
Line 3	11	620	11	640	20	1.25	0.99	0.63	3.98	0.44	7.29	Very Good
Line 3	11	640	11	660	20	1.45	1.83	0.69	1.41	2.49	7.87	Very Good
Line 3	11	660	11	680	20	0.93	1.2	0.91	0.65	1.06	4.74	Very Good
Line 3	11	680	11	700	20	0.74	1.78	1.49	0.6	1.02	5.62	Very Good
Line 3	11	700	11	720	20	1.18	1.49	0.95	1.06	1.52	6.19	Very Good
Line 3	11	720	11	740	20	1.03	0.73	0.7	0.37	0.83	3.65	Very Good
Line 3	11	740	11	760	20	1.1	1.04	0.86	1.51	2.35	6.85	Very Good
Line 3	11	760	11	780	20	1.7	1.1	0.95	0.46	1.24	5.44	Very Good
Line 3	11	780	11	800	20	4.96	1.4	0.59	0.52	0.86	8.32	Very Good
Line 3	11	800	11	820	20	3.46	1.15	1.51	0.68	0.92	7.71	Very Good
Line 3	11	820	11	840	20	1.82	2.24	1.45	0.32	0.8	6.63	Very Good
Line 3	11	840	11	860	20	1.05	1.7	1.05	0.91	1.24	5.96	Very Good
Line 3	11	860	11	880	20	1.17	0.95	0.75	1.37	1.82	6.06	Very Good
Line 3	11	880	11	900	20	1.59	1.89	0.94	0.54	0.81	5.77	Very Good
Line 3	11	900	11	920	20	6.88	1.23	0.36	0.45	0.75	9.66	Very Good
Line 3	11	920	11	940	20	2.2	2.0	0.55	2.18	1.39	8.32	Very Good
Line 3	11	940	11	960	20	1.35	0.78	0.61	4.02	0.83	7.58	Very Good
Line 3	11	960	11	980	20	1.5	1.12	0.47	4.18	2.01	9.3	Very Good
Line 3	11	980	12	0	20	2.01	0.68	0.44	2.51	1.75	7.39	Very Good
Line 3	12	0	12	20	20	2.56	1.55	0.7	0.96	1.98	7.75	Very Good
Line 3	12	20	12	40	20	3.64	1.21	0.44	1.83	2.4	9.52	Very Good
Line 3	12	40	12	60	20	2.66	1.14	0.83	0.53	0.65	5.82	Very Good
Line 3	12	60	12	80	20	2.3	1.25	0.52	0.68	1.02	5.77	Very Good
Line 3	12	80	12	100	20	2.75	1.6	0.86	0.76	0.94	6.9	Very Good
Line 3	12	100	12	120	20	2.76	1.97	1.02	0.72	1.43	7.91	Very Good
Line 3	12	120	12	140	20	1.46	1.15	0.73	0.58	0.88	4.8	Very Good
Line 3	12	140	12	160	20	0.92	1.64	0.59	0.74	1.13	5.01	Very Good
Line 3	12	160	12	180	20	1.34	1.49	0.9	0.7	0.93	5.37	Very Good
Line 3	12	180	12	200	20	1.36	2.55	0.88	1.14	1.37	7.32	Very Good
	l	l	I		1	·	1	1		l		

Line 3	12	200	12	220	20	0.85	1.35	0.5	0.58	0.83	4.11	Very Good
Line 3	12	220	12	240	20	0.77	1.8	0.53	0.67	0.94	4.71	Very Good
Line 3	12	240	12	260	20	2.16	1.44	0.67	0.75	1.2	6.22	Very Good
Line 3	12	260	12	280	20	1.92	0.53	0.42	0.67	0.93	4.47	Very Good
Line 3	12	280	12	300	20	1.49	0.76	0.56	1.91	2.54	7.27	Very Good
Line 3	12	300	12	320	20	2.26	2.39	0.65	1.16	1.6	8.06	Very Good
Line 3	12	320	12	340	20	1.75	0.87	0.92	1.17	2.05	6.75	Very Good
Line 3	12	340	12	360	20	2.09	1.62	0.64	0.77	1.16	6.29	Very Good
Line 3	12	360	12	380	20	1.17	1.99	0.79	0.91	1.21	6.07	Very Good
Line 3	12	380	12	400	20	1.85	2.14	0.78	0.57	0.8	6.14	Very Good
Line 3	12	400	12	420	20	3.22	2.17	0.69	0.46	0.88	7.42	Very Good
Line 3	12	420	12	440	20	2.05	2.24	0.4	0.4	0.41	5.51	Very Good
Line 3	12	440	12	460	20	1.0	0.81	0.61	0.63	1.03	4.08	Very Good
Line 3	12	460	12	480	20	1.12	0.86	0.81	0.94	1.53	5.25	Very Good
Line 3	12	480	12	500	20	1.65	1.33	0.55	1.27	1.87	6.68	Very Good
Line 3	12	500	12	520	20	1.36	0.57	0.44	0.63	0.79	3.79	Very Good
Line 3	12	520	12	540	20	1.4	1.11	0.76	0.59	0.78	4.64	Very Good
Line 3	12	540	12	560	20	2.31	1.03	0.62	0.63	1.14	5.73	Very Good
Line 3	12	560	12	580	20	2.26	1.55	0.46	0.72	1.74	6.72	Very Good
Line 3	12	580	12	600	20	2.19	2.02	0.84	4.22	1.07	10.35	Very Good
Line 3	12	600	12	620	20	2.13	2.03	0.48	3.62	0.96	9.22	Very Good
Line 3	12	620	12	640	20	3.25	1.75	0.51	4.17	1.65	11.32	Very Good
Line 3	12	640	12	660	20	2.69	2.33	0.91	0.95	1.13	8.01	Very Good
Line 3	12	660	12	680	20	0.91	1.22	0.47	0.74	1.07	4.41	Very Good
Line 3	12	680	12	700	20	0.94	0.81	0.78	0.41	0.77	3.72	Very Good
Line 3	12	700	12	720	20	1.8	0.84	0.39	0.61	0.66	4.29	Very Good
Line 3	12	720	12	740	20	1.43	0.96	0.53	1.08	0.58	4.57	Very Good
Line 3	12	740	12	760	20	0.77	1.17	0.71	0.67	0.54	3.86	Very Good
Line 3	12	760	12	780	20	0.92	0.96	0.72	1.05	1.27	4.92	Very Good
Line 3	12	780	12	800	20	2.04	3.17	0.53	1.16	0.97	7.88	Very Good
			•									

Line 2													
Line 3	Line 3	12	800	12	820	20	4.12	2.84	0.38	1.3	2.28	10.91	Very Good
Line 3	Line 3	12	820	12	840	20	2.7	0.94	0.51	1.82	3.64	9.61	Very Good
Line 3	Line 3	12	840	12	860	20	1.41	0.75	0.74	3.84	0.77	7.51	Very Good
Line 3	Line 3	12	860	12	880	20	1.04	0.85	0.93	3.31	0.97	7.1	Very Good
Line 3	Line 3	12	880	12	900	20	1.11	0.56	0.55	2.92	1.51	6.65	Very Good
Line 3	Line 3	12	900	12	920	20	1.03	1.36	0.85	1.13	1.61	5.99	Very Good
Line 3	Line 3	12	920	12	940	20	1.02	1.02	0.52	1.2	0.83	4.59	Very Good
Line 3 12 980 13 0 20 121 0.82 0.81 0.3 0.4 3.54 Very Go Line 3 13 0 13 20 20 20 2.33 1.3 0.87 0.5 0.88 5.88 Very Go Line 3 13 20 13 40 20 1.14 0.91 0.77 0.51 0.71 4.03 Very Go Line 3 13 40 13 80 20 1.24 0.82 0.91 0.58 0.88 4.4 Very Go Line 3 13 0 0 13 80 20 1.01 1.0 0.92 0.73 1.08 4.74 Very Go Line 3 13 0 0 13 100 20 2.73 0.9 0.88 1.02 1.34 0.87 Very Go Line 3 13 100 13 120 20 1.03 0.74 0.55 0.4 0.87 3.8 Very Go Line 3 13 100 13 140 20 1.1 1.0 0.88 1.32 1.15 5.46 Very Go Line 3 13 140 13 150 20 1.97 0.87 0.56 0.48 0.51 4.39 Very Go Line 3 13 140 13 150 20 1.97 0.87 0.56 0.48 0.51 4.39 Very Go Line 3 13 160 13 180 20 0.98 0.96 0.52 1.08 1.08 1.08 4.62 Very Go Line 3 13 180 13 200 20 0.98 0.96 0.52 1.08 1.08 1.08 4.62 Very Go Line 3 13 180 13 200 20 0.98 0.96 0.52 1.08 1.08 1.52 5.02 Very Go Line 3 13 13 200 13 240 20 0.98 0.96 0.52 1.08 1.08 1.52 5.02 Very Go Line 3 13 220 13 220 20 0.94 0.57 0.73 1.28 1.52 5.02 Very Go Line 3 13 220 13 220 20 0.98 0.77 0.79 0.62 1.07 3.88 Very Go Line 3 13 220 13 220 20 0.94 0.57 0.73 1.28 1.52 5.02 Very Go Line 3 13 220 13 220 20 0.88 0.7 0.79 0.62 1.07 3.88 Very Go Line 3 13 220 13 220 20 4.19 1.46 0.79 0.77 1.23 8.44 Very Go Line 3 13 280 13 300 20 1.35 1.26 0.88 0.49 0.99 4.98 Very Go Line 3 13 280 13 300 20 1.35 1.26 0.88 0.49 0.99 4.98 Very Go Line 3 13 300 13 300 20 1.35 1.26 0.88 0.49 0.99 4.98 Very Go Line 3 13 300 13 300 20 5.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 300 13 300 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 300 13 300 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 300 13 300 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 300 13 300 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 300 13 300 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 300 13 300 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 300 13 300 20 0.55 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0	Line 3	12	940	12	960	20	1.25	0.98	1.07	0.68	0.98	4.96	Very Good
Line 3 13 0 13 20 20 2.33 1.3 0.87 0.5 0.88 5.88 Very Go Line 3 13 20 13 40 20 1.14 0.91 0.77 0.51 0.71 4.03 Very Go Line 3 13 40 13 60 20 1.24 0.82 0.91 0.56 0.88 4.4 Very Go Line 3 13 60 13 80 20 1.01 1.0 0.92 0.73 1.08 4.74 Very Go Line 3 13 80 13 100 20 2.73 0.9 0.68 1.02 1.34 6.67 Very Go Line 3 13 100 13 120 20 1.03 0.74 0.55 0.4 0.87 3.6 Very Go Line 3 13 120 13 140 20 1.1 1.01 0.88 1.32 1.15 5.48 Very Go Line 3 13 140 13 160 20 1.97 0.87 0.56 0.48 0.51 4.39 Very Go Line 3 13 140 13 160 20 1.97 0.87 0.56 0.48 0.51 4.39 Very Go Line 3 13 160 13 200 20 0.98 1.32 0.37 0.66 0.7 3.99 Very Go Line 3 13 180 13 200 20 0.98 0.96 0.52 1.08 1.08 1.08 4.62 Very Go Line 3 13 180 13 200 20 0.98 0.96 0.52 1.08 1.09 1.09 4.62 Very Go Line 3 13 200 13 220 20 0.88 0.57 0.73 1.28 1.25 5.02 Very Go Line 3 13 200 13 220 20 0.88 0.7 0.79 0.62 1.07 3.89 Very Go Line 3 13 200 13 220 20 0.88 0.7 0.79 0.62 1.07 3.89 Very Go Line 3 13 260 13 260 20 2.11 1.01 0.79 1.19 2.44 7.54 Very Go Line 3 13 260 13 320 20 21 1.15 1.46 0.79 0.77 1.23 8.44 Very Go Line 3 13 260 13 300 13 320 20 2.16 0.0 0.68 0.49 0.99 4.99 Very Go Line 3 13 300 13 320 20 21 1.60 0.0 0.68 0.8 1.37 5.02 Very Go Line 3 13 300 13 320 20 20 2.16 0.0 0.68 0.49 0.99 4.99 Very Go Line 3 13 300 13 320 20 21 6.00 0.68 0.49 0.99 4.99 Very Go Line 3 13 33 300 13 320 20 2.16 0.0 0.68 0.8 0.49 0.99 4.99 Very Go Line 3 13 33 300 13 320 20 2.16 0.0 0.68 0.8 0.77 0.79 0.82 1.07 1.22 8.44 Very Go Line 3 13 33 300 13 330 300 13 340 20 0.55 0.0 1.04 0.43 0.87 2.88 Very Go Line 3 13 330 330 13 340 20 20 0.55 0.0 1.04 0.43 0.87 2.88 Very Go Line 3 13 33 340 13 340 20 0.00 0.00 0.00 0.00 0.00 0.00 0.00	Line 3	12	960	12	980	20	1.4	0.81	0.66	1.11	1.05	5.03	Very Good
Line 3         13         20         13         40         20         1.14         0.91         0.77         0.51         0.71         4.03         Very Go           Line 3         13         40         13         60         20         1.24         0.82         0.91         0.56         0.88         4.4         Very Go           Line 3         13         60         13         80         20         1.01         1.0         0.92         0.73         1.08         4.74         Very Go           Line 3         13         80         13         100         20         2.73         0.9         0.68         1.02         1.34         6.67         Very Go           Line 3         13         100         13         120         20         1.03         0.74         0.55         0.4         0.87         3.6         Very Go           Line 3         13         140         13         140         20         1.1         1.01         0.88         1.32         1.15         5.46         Very Go           Line 3         13         160         13         180         20         0.98         0.96         0.52         1.08         1.08	Line 3	12	980	13	0	20	1.21	0.82	0.81	0.3	0.4	3.54	Very Good
Line 3         13         40         13         60         20         124         0.82         0.91         0.56         0.88         4.4         Very Go           Line 3         13         60         13         80         20         1.01         1.0         0.92         0.73         1.08         4.74         Very Go           Line 3         13         100         13         100         20         2.73         0.9         0.88         1.02         1.34         6.67         Very Go           Line 3         13         100         13         120         20         1.03         0.74         0.55         0.4         0.87         3.6         Very Go           Line 3         13         140         20         1.1         1.01         0.88         1.32         1.15         5.46         Very Go           Line 3         13         140         13         160         20         1.97         0.87         0.56         0.48         0.51         4.39         Very Go           Line 3         13         160         13         180         20         0.98         1.32         0.52         1.08         1.08         4.62         Very	Line 3	13	0	13	20	20	2.33	1.3	0.87	0.5	0.88	5.88	Very Good
Line 3         13         60         13         80         20         1.01         1.0         0.92         0.73         1.08         4.74         Very Go           Line 3         13         80         13         100         20         2.73         0.9         0.68         1.02         1.34         6.67         Very Go           Line 3         13         100         13         120         20         1.03         0.74         0.55         0.4         0.67         3.6         Very Go           Line 3         13         120         13         140         20         1.1         1.01         0.88         1.32         1.15         5.46         Very Go           Line 3         13         140         13         160         20         1.97         0.87         0.56         0.48         0.51         4.39         Very Go           Line 3         13         160         13         180         20         0.98         0.96         0.52         1.08         1.08         4.62         Very Go           Line 3         13         200         20         0.96         1.32         0.37         0.65         0.7         3.99         Ver	Line 3	13	20	13	40	20	1.14	0.91	0.77	0.51	0.71	4.03	Very Good
Line 3 13 80 13 100 20 2.73 0.9 0.68 1.02 1.34 6.67 Very Go Line 3 13 100 13 120 20 1.03 0.74 0.55 0.4 0.87 3.6 Very Go Line 3 13 120 13 140 20 1.1 1.01 0.88 1.32 1.15 5.46 Very Go Line 3 13 140 13 160 20 1.97 0.87 0.56 0.48 0.51 4.39 Very Go Line 3 13 160 13 180 20 0.98 0.96 0.52 1.08 1.08 1.08 4.62 Very Go Line 3 13 180 13 200 20 0.96 1.32 0.37 0.65 0.7 3.99 Very Go Line 3 13 200 13 220 20 0.94 0.57 0.73 1.26 1.52 5.02 Very Go Line 3 13 220 13 240 20 0.68 0.7 0.79 0.62 1.07 3.86 Very Go Line 3 13 240 13 260 20 2.11 1.01 0.79 1.19 2.44 7.54 Very Go Line 3 13 280 13 320 20 1.35 1.26 0.88 0.49 0.99 4.98 Very Go Line 3 13 3 280 13 320 20 2.16 0.0 0.69 0.8 1.37 5.02 Very Go Line 3 13 320 13 340 13 340 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 320 13 340 13 340 20 0.55 0.0 0.0 0.0 0.64 0.73 0.86 2.23 Very Go	Line 3	13	40	13	60	20	1.24	0.82	0.91	0.56	0.88	4.4	Very Good
Line 3 13 100 13 120 20 1.03 0.74 0.55 0.4 0.87 3.6 Very Go Line 3 13 120 13 140 20 1.1 1.01 0.88 1.32 1.15 5.46 Very Go Line 3 13 140 13 160 20 1.97 0.87 0.56 0.48 0.51 4.39 Very Go Line 3 13 160 13 180 20 0.98 0.96 0.52 1.08 1.08 4.62 Very Go Line 3 13 180 13 200 20 0.96 1.32 0.37 0.65 0.7 3.99 Very Go Line 3 13 200 13 220 20 0.94 0.57 0.73 1.26 1.52 5.02 Very Go Line 3 13 220 13 240 20 0.68 0.7 0.79 0.62 1.07 3.86 Very Go Line 3 13 240 13 260 20 2.11 1.01 0.79 1.19 2.44 7.54 Very Go Line 3 13 280 13 300 20 1.35 1.26 0.88 0.49 0.99 4.98 Very Go Line 3 13 3 280 13 300 20 2.16 0.0 0.69 0.8 1.37 5.02 Very Go Line 3 13 320 13 340 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 320 13 340 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 320 13 340 13 360 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go	Line 3	13	60	13	80	20	1.01	1.0	0.92	0.73	1.08	4.74	Very Good
Line 3         13         120         13         140         20         1.1         1.01         0.88         1.32         1.15         5.46         Very Go           Line 3         13         140         13         160         20         1.97         0.87         0.56         0.48         0.51         4.39         Very Go           Line 3         13         160         13         180         20         0.98         0.96         0.52         1.08         1.08         4.62         Very Go           Line 3         13         180         13         200         20         0.96         1.32         0.37         0.65         0.7         3.99         Very Go           Line 3         13         200         13         220         20         0.94         0.57         0.73         1.26         1.52         5.02         Very Go           Line 3         13         220         13         240         20         0.68         0.7         0.79         0.62         1.07         3.86         Very Go           Line 3         13         240         13         280         20         2.11         1.01         0.79         1.19	Line 3	13	80	13	100	20	2.73	0.9	0.68	1.02	1.34	6.67	Very Good
Line 3         13         140         13         160         20         1.97         0.87         0.56         0.48         0.51         4.39         Very Go           Line 3         13         160         13         180         20         0.98         0.96         0.52         1.08         1.08         4.62         Very Go           Line 3         13         180         13         200         20         0.96         1.32         0.37         0.65         0.7         3.99         Very Go           Line 3         13         200         13         220         20         0.94         0.57         0.73         1.26         1.52         5.02         Very Go           Line 3         13         220         13         240         20         0.68         0.7         0.79         0.62         1.07         3.86         Very Go           Line 3         13         240         13         260         20         2.11         1.01         0.79         1.19         2.44         7.54         Very Go           Line 3         13         280         20         4.19         1.46         0.79         0.77         1.23         8.44	Line 3	13	100	13	120	20	1.03	0.74	0.55	0.4	0.87	3.6	Very Good
Line 3         13         160         13         180         20         0.98         0.96         0.52         1.08         1.08         4.62         Very Go           Line 3         13         180         13         200         20         0.96         1.32         0.37         0.65         0.7         3.99         Very Go           Line 3         13         200         13         220         20         0.94         0.57         0.73         1.26         1.52         5.02         Very Go           Line 3         13         220         13         240         20         0.68         0.7         0.79         0.62         1.07         3.86         Very Go           Line 3         13         240         13         260         20         2.11         1.01         0.79         1.19         2.44         7.54         Very Go           Line 3         13         260         13         280         20         4.19         1.46         0.79         0.77         1.23         8.44         Very Go           Line 3         13         280         13         300         20         1.35         1.26         0.88         0.49 <td< td=""><td>Line 3</td><td>13</td><td>120</td><td>13</td><td>140</td><td>20</td><td>1.1</td><td>1.01</td><td>0.88</td><td>1.32</td><td>1.15</td><td>5.46</td><td>Very Good</td></td<>	Line 3	13	120	13	140	20	1.1	1.01	0.88	1.32	1.15	5.46	Very Good
Line 3         13         180         13         200         20         0.96         1.32         0.37         0.65         0.7         3.99         Very Go           Line 3         13         200         13         220         20         0.94         0.57         0.73         1.26         1.52         5.02         Very Go           Line 3         13         220         13         240         20         0.68         0.7         0.79         0.62         1.07         3.86         Very Go           Line 3         13         240         13         260         20         2.11         1.01         0.79         1.19         2.44         7.54         Very Go           Line 3         13         260         13         280         20         4.19         1.46         0.79         0.77         1.23         8.44         Very Go           Line 3         13         280         13         300         20         1.35         1.26         0.88         0.49         0.99         4.98         Very Go           Line 3         13         300         13         320         20         2.16         0.0         0.69         0.8         1	Line 3	13	140	13	160	20	1.97	0.87	0.56	0.48	0.51	4.39	Very Good
Line 3         13         200         13         220         20         0.94         0.57         0.73         1.26         1.52         5.02         Very Go           Line 3         13         220         13         240         20         0.68         0.7         0.79         0.62         1.07         3.86         Very Go           Line 3         13         240         13         260         20         2.11         1.01         0.79         1.19         2.44         7.54         Very Go           Line 3         13         260         13         280         20         4.19         1.46         0.79         0.77         1.23         8.44         Very Go           Line 3         13         280         13         300         20         1.35         1.26         0.88         0.49         0.99         4.98         Very Go           Line 3         13         300         13         320         20         2.16         0.0         0.69         0.8         1.37         5.02         Very Go           Line 3         13         320         13         340         20         0.55         0.0         1.04         0.43         0	Line 3	13	160	13	180	20	0.98	0.96	0.52	1.08	1.08	4.62	Very Good
Line 3         13         220         13         240         20         0.68         0.7         0.79         0.62         1.07         3.86         Very Go           Line 3         13         240         13         260         20         2.11         1.01         0.79         1.19         2.44         7.54         Very Go           Line 3         13         260         13         280         20         4.19         1.46         0.79         0.77         1.23         8.44         Very Go           Line 3         13         280         13         300         20         1.35         1.26         0.88         0.49         0.99         4.98         Very Go           Line 3         13         300         13         320         20         2.16         0.0         0.69         0.8         1.37         5.02         Very Go           Line 3         13         320         13         340         20         0.55         0.0         1.04         0.43         0.87         2.89         Very Go           Line 3         13         340         20         0.55         0.0         1.04         0.43         0.87         2.89 <td< td=""><td>Line 3</td><td>13</td><td>180</td><td>13</td><td>200</td><td>20</td><td>0.96</td><td>1.32</td><td>0.37</td><td>0.65</td><td>0.7</td><td>3.99</td><td>Very Good</td></td<>	Line 3	13	180	13	200	20	0.96	1.32	0.37	0.65	0.7	3.99	Very Good
Line 3         13         240         13         260         20         2.11         1.01         0.79         1.19         2.44         7.54         Very Go           Line 3         13         260         13         280         20         4.19         1.46         0.79         0.77         1.23         8.44         Very Go           Line 3         13         280         13         300         20         1.35         1.26         0.88         0.49         0.99         4.98         Very Go           Line 3         13         300         13         320         20         2.16         0.0         0.69         0.8         1.37         5.02         Very Go           Line 3         13         320         13         340         20         0.55         0.0         1.04         0.43         0.87         2.89         Very Go           Line 3         13         340         13         360         20         0.0         0.0         0.64         0.73         0.86         2.23         Very Go	Line 3	13	200	13	220	20	0.94	0.57	0.73	1.26	1.52	5.02	Very Good
Line 3         13         260         13         280         20         4.19         1.46         0.79         0.77         1.23         8.44         Very Go           Line 3         13         280         13         300         20         1.35         1.26         0.88         0.49         0.99         4.98         Very Go           Line 3         13         300         13         320         20         2.16         0.0         0.69         0.8         1.37         5.02         Very Go           Line 3         13         320         13         340         20         0.55         0.0         1.04         0.43         0.87         2.89         Very Go           Line 3         13         340         13         360         20         0.0         0.0         0.64         0.73         0.86         2.23         Very Go	Line 3	13	220	13	240	20	0.68	0.7	0.79	0.62	1.07	3.86	Very Good
Line 3         13         280         13         300         20         1.35         1.26         0.88         0.49         0.99         4.98         Very Go           Line 3         13         300         13         320         20         2.16         0.0         0.69         0.8         1.37         5.02         Very Go           Line 3         13         320         13         340         20         0.55         0.0         1.04         0.43         0.87         2.89         Very Go           Line 3         13         340         13         360         20         0.0         0.0         0.64         0.73         0.86         2.23         Very Go	Line 3	13	240	13	260	20	2.11	1.01	0.79	1.19	2.44	7.54	Very Good
Line 3         13         300         13         320         20         2.16         0.0         0.69         0.8         1.37         5.02         Very Go           Line 3         13         320         13         340         20         0.55         0.0         1.04         0.43         0.87         2.89         Very Go           Line 3         13         340         13         360         20         0.0         0.0         0.64         0.73         0.86         2.23         Very Go	Line 3	13	260	13	280	20	4.19	1.46	0.79	0.77	1.23	8.44	Very Good
Line 3 13 320 13 340 20 0.55 0.0 1.04 0.43 0.87 2.89 Very Go Line 3 13 340 13 360 20 0.0 0.0 0.64 0.73 0.86 2.23 Very Go	Line 3	13	280	13	300	20	1.35	1.26	0.88	0.49	0.99	4.98	Very Good
Line 3 13 340 13 360 20 0.0 0.0 0.64 0.73 0.86 2.23 Very Go	Line 3	13	300	13	320	20	2.16	0.0	0.69	0.8	1.37	5.02	Very Good
	Line 3	13	320	13	340	20	0.55	0.0	1.04	0.43	0.87	2.89	Very Good
	Line 3	13	340	13	360	20	0.0	0.0	0.64	0.73	0.86	2.23	Very Good
Line 3   13   360   13   380   20   0.0   0.71   0.43   0.83   1.97   Very Go	Line 3	13	360	13	380	20	0.0	0.0	0.71	0.43	0.83	1.97	Very Good
Line 3 13 380 13 400 20 0.0 0.0 0.46 0.78 1.53 2.77 Very Go	Line 3	13	380	13	400	20	0.0	0.0	0.46	0.78	1.53	2.77	Very Good

The color   The													
March   Marc	Line 3	13	400	13	420	20	0.0	0.0	0.78	0.33	0.76	1.88	Very Good
March   Marc	Line 3	13	420	13	440	20	1.5	0.0	2.08	1.46	1.88	6.92	Very Good
Mine	Line 3	13	440	13	460	20	1.14	0.0	0.75	0.77	1.01	3.67	Very Good
Line 3         13         200         13         501         20         0.07         0.07         0.01         0.01         0.01         0.02         0.02         0.07         0.03         0.04         0.02         0.07         0.04         0.04         0.02         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.04         0.02         0.04         0.04         0.02         0.04<	Line 3	13	460	13	480	20	2.71	0.0	0.78	1.22	2.2	6.91	Very Good
Mine	Line 3	13	480	13	500	20	3.41	0.0	0.54	0.65	1.14	5.74	Very Good
Mine	Line 3	13	500	13	520	20	0.97	0.0	0.61	0.68	0.92	3.18	Very Good
Line	Line 3	13	520	13	540	20	0.78	0.0	0.57	0.43	1.18	2.97	Very Good
Third   13	Line 3	13	540	13	560	20	1.09	0.96	0.79	1.32	1.34	5.5	Very Good
Line 3	Line 3	13	560	13	580	20	0.9	0.84	0.92	0.5	0.82	3.99	Very Good
Line 3	Line 3	13	580	13	600	20	0.89	0.43	0.46	0.51	0.78	3.07	Very Good
Line 3 13 660 13 660 20 0.8 0.68 0.54 0.62 0.01 3.56 Very Good Line 3 13 660 13 680 20 1.1 0.83 0.66 0.84 1.2 4.63 Very Good Line 3 13 660 13 700 20 1.04 1.11 0.89 1.49 2.0 6.53 Very Good Line 3 13 700 13 770 20 1.02 0.88 0.55 0.85 1.05 1.05 4.85 Very Good Line 3 13 770 13 770 20 1.02 0.88 0.55 0.58 1.03 0.9 7.18 Very Good Line 3 13 770 13 770 20 1.02 0.88 0.55 0.58 1.03 0.9 7.18 Very Good Line 3 13 770 13 770 20 1.12 2.44 0.52 0.7 1.15 5.54 Very Good Line 3 13 760 13 770 20 1.12 2.44 0.52 0.7 1.15 5.54 Very Good Line 3 13 770 13 770 20 1.12 0.83 1.2 0.94 0.64 1.17 4.77 Very Good Line 3 13 770 13 800 20 1.25 0.89 0.92 0.88 1.03 0.90 1.04 4.96 Very Good Line 3 13 800 13 820 20 1.37 0.99 1.08 0.66 0.62 4.73 Very Good Line 3 13 840 13 860 20 1.148 1.57 0.45 1.05 1.05 1.78 6.33 Very Good Line 3 13 880 13 880 20 1.18 80 20 2.01 1.57 0.84 2.8 2.01 9.02 Very Good Line 3 13 880 13 880 20 20 1.196 0.73 0.81 1.22 1.13 5.65 Very Good Line 3 13 880 13 880 20 2.0 1.55 1.15 0.04 1.7 2.10 7.21 Very Good Line 3 13 880 13 990 13 820 20 1.55 1.15 0.04 1.7 2.10 7.21 Very Good Line 3 13 990 13 990 20 1.55 1.15 0.04 1.7 2.10 7.21 Very Good Line 3 13 990 13 990 20 1.08 0.08 0.68 0.68 0.62 1.11 1.11 1.86 5.44 Very Good Line 3 13 990 13 990 20 1.08 0.08 0.68 0.68 0.8 1.35 5.88 Very Good Line 3 13 990 13 990 20 1.155 1.15 0.04 0.68 0.8 1.15 5.88 Very Good Line 3 13 990 13 990 20 1.180 0.79 0.78 0.78 0.11 1.11 1.86 5.44 Very Good Line 3 13 990 13 990 20 1.180 0.79 0.78 0.78 0.11 1.11 1.86 5.44 Very Good Line 3 13 990 13 990 20 1.190 0.81 0.79 0.78 0.78 0.11 1.11 1.86 5.44 Very Good Line 3 13 990 13 990 13 990 20 1.190 0.81 0.79 0.78 0.78 0.11 1.11 1.186 5.44 0.49 0.49 0.49 0.49 0.49 0.49 0.49 0	Line 3	13	600	13	620	20	1.84	0.82	0.5	0.62	0.75	4.53	Very Good
Line 3         13         660         13         680         20         1.1         0.83         0.66         0.84         1.2         4.63         Very Good           Line 3         13         680         13         700         20         1.04         1.11         0.89         1.49         2.0         6.63         Very Good           Line 3         13         700         13         720         20         1.52         0.88         0.55         0.85         1.05         4.85         Very Good           Line 3         13         720         13         740         20         1.12         2.44         0.52         0.7         1.15         5.94         Very Good           Line 3         13         760         13         780         20         0.83         1.2         0.94         0.64         1.17         4.77         Very Good           Line 3         13         780         13         800         20         1.25         0.89         0.92         0.86         1.04         4.96         Very Good           Line 3         13         800         13         820         20         1.37         0.99         1.08         0.66	Line 3	13	620	13	640	20	1.09	0.93	0.9	0.4	0.87	4.19	Very Good
Line 3 13 680 13 700 20 1.04 1.11 0.89 1.49 2.0 6.53 Very Good Line 3 13 700 13 720 20 1.52 0.88 0.55 0.86 1.05 4.85 Very Good Line 3 13 720 13 740 20 1.12 2.44 0.52 0.7 1.15 5.94 Very Good Line 3 13 780 13 780 20 0.83 1.2 0.94 0.64 1.17 4.77 Very Good Line 3 13 780 13 800 20 1.25 0.89 0.92 0.86 1.04 4.96 Very Good Line 3 13 800 13 820 20 1.37 0.99 1.08 0.66 0.62 4.73 Very Good Line 3 13 820 13 840 20 1.48 1.57 0.45 1.05 1.05 1.78 6.33 Very Good Line 3 13 860 13 880 20 1.48 1.57 0.45 1.05 1.05 1.78 6.33 Very Good Line 3 13 880 13 880 20 1.98 0.73 0.89 1.22 1.13 5.65 Very Good Line 3 13 880 13 880 20 1.98 0.73 0.81 1.22 1.13 5.65 Very Good Line 3 13 880 13 880 20 1.98 0.73 0.81 1.22 1.13 5.65 Very Good Line 3 13 880 13 880 20 1.98 0.73 0.81 1.22 1.13 5.65 Very Good Line 3 13 880 13 880 20 1.98 0.73 0.81 1.22 1.13 5.65 Very Good Line 3 13 880 13 900 20 1.55 1.15 0.84 1.7 2.16 7.21 Very Good Line 3 13 880 13 900 13 920 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 900 13 920 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 980 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 980 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good Line 3 13 940 13 980 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good Line 3 13 940 13 980 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good Line 3 13 940 13 980 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good Line 3 13 940 13 980 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good Line 3 13 940 13 980 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good Line 3 13 940 13 980 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good Line 3 13 940 13 980 20 1.04 2.08 0.6 0.8 5.35 5.88 Very Good Line 3 13 980 13 980 20 1.04 2.08 0.6 0.8 5.35 5.88 Very Good Line 3 13 980 13 980 13 980 20 1.04 2.08 0.6 0.8 5.35 5.88 Very Good Line 3 13 980 13 980 20 1.04 2.08 0.6 0.8 5.35 5.88 Very Good Line 3 13 980 13 980 20 1.04 2.08 0.6 0.8 5.35 5.88 Very Good Line 3 13 980 13 980 20 1.04 2.08 0.6 0.8 5.35 5.88 Very Good Line 3 13 980 13 980 20 1.04 2.08 0.6 0.8 5.35 5.88 Very Good Line 3 13 980 13 980 13 980 20 1.04 2.08 0.6 0.8 5.35 5.88 Very Good L	Line 3	13	640	13	660	20	0.8	0.68	0.54	0.62	0.91	3.56	Very Good
Line 3 13 700 13 720 20 1.52 0.88 0.55 0.85 1.05 4.85 Very Good Line 3 13 720 13 740 20 1.02 3.65 0.58 1.03 0.9 7.18 Very Good Line 3 13 740 13 760 20 1.12 2.44 0.52 0.7 1.15 5.94 Very Good Line 3 13 760 13 780 20 0.83 1.2 0.94 0.64 1.17 4.77 Very Good Line 3 13 780 13 800 20 1.25 0.89 0.92 0.86 1.04 4.96 Very Good Line 3 13 800 13 820 20 1.37 0.99 1.08 0.66 0.62 4.73 Very Good Line 3 13 820 13 840 20 1.48 1.57 0.45 1.05 1.78 6.33 Very Good Line 3 13 840 13 880 20 20 1.48 1.57 0.45 1.05 1.78 6.33 Very Good Line 3 13 880 13 880 20 20 1.48 1.57 0.45 1.05 1.78 6.33 Very Good Line 3 13 880 13 880 20 20 1.96 0.73 0.61 1.22 1.13 5.65 Very Good Line 3 13 880 13 890 20 1.96 0.73 0.61 1.22 1.13 5.65 Very Good Line 3 13 880 13 890 20 1.96 0.73 0.61 1.22 1.13 5.65 Very Good Line 3 13 880 13 990 20 1.55 1.15 0.64 1.7 2.16 7.21 Very Good Line 3 13 890 13 940 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 940 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 940 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 980 20 1.98 0.99 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 980 20 1.98 0.99 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 980 20 1.98 0.99 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 980 20 1.98 0.99 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 980 20 1.98 0.99 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 980 20 1.98 0.99 0.99 0.99 0.99 0.99 0.99 0.99 0	Line 3	13	660	13	680	20	1.1	0.83	0.66	0.84	1.2	4.63	Very Good
Line 3         13         720         13         740         20         1.02         3.65         0.58         1.03         0.9         7.18         Very Good           Line 3         13         740         13         760         20         1.12         2.44         0.52         0.7         1.15         5.94         Very Good           Line 3         13         760         13         780         20         0.83         1.2         0.94         0.64         1.17         4.77         Very Good           Line 3         13         780         13         800         20         1.25         0.89         0.92         0.86         1.04         4.96         Very Good           Line 3         13         800         13         820         20         1.37         0.99         1.08         0.66         0.62         4.73         Very Good           Line 3         13         820         13         840         20         1.48         1.57         0.45         1.05         1.78         6.33         Very Good           Line 3         13         860         20         2.01         1.57         0.64         2.8         2.01         9.02 <td>Line 3</td> <td>13</td> <td>680</td> <td>13</td> <td>700</td> <td>20</td> <td>1.04</td> <td>1.11</td> <td>0.89</td> <td>1.49</td> <td>2.0</td> <td>6.53</td> <td>Very Good</td>	Line 3	13	680	13	700	20	1.04	1.11	0.89	1.49	2.0	6.53	Very Good
Line 3         13         740         13         760         20         1.12         2.44         0.52         0.7         1.15         5.94         Very Good           Line 3         13         760         13         780         20         0.83         1.2         0.94         0.64         1.17         4.77         Very Good           Line 3         13         780         13         800         20         1.25         0.89         0.92         0.86         1.04         4.96         Very Good           Line 3         13         800         13         820         20         1.37         0.99         1.08         0.66         0.62         4.73         Very Good           Line 3         13         820         13         840         20         1.48         1.57         0.45         1.05         1.78         6.33         Very Good           Line 3         13         840         13         860         20         2.01         1.57         0.64         2.8         2.01         9.02         Very Good           Line 3         13         860         13         880         20         1.96         0.73         0.61         1.22	Line 3	13	700	13	720	20	1.52	0.88	0.55	0.85	1.05	4.85	Very Good
Line 3 13 760 13 780 20 0.83 1.2 0.94 0.64 1.17 4.77 Very Good  Line 3 13 780 13 800 20 1.25 0.89 0.92 0.86 1.04 4.96 Very Good  Line 3 13 800 13 820 20 1.37 0.99 1.08 0.66 0.62 4.73 Very Good  Line 3 13 820 13 840 20 1.48 1.57 0.45 1.05 1.78 6.33 Very Good  Line 3 13 840 13 860 20 2.01 1.57 0.64 2.8 2.01 9.02 Very Good  Line 3 13 880 13 880 20 1.96 0.73 0.61 1.22 1.13 5.65 Very Good  Line 3 13 880 13 900 20 2.73 0.82 0.63 3.86 5.93 13.98 Very Good  Line 3 13 900 13 920 20 1.55 1.15 0.64 1.7 2.16 7.21 Very Good  Line 3 13 990 13 940 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good  Line 3 13 990 13 990 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good  Line 3 13 990 13 990 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good	Line 3	13	720	13	740	20	1.02	3.65	0.58	1.03	0.9	7.18	Very Good
Line 3 13 780 13 800 20 1.25 0.89 0.92 0.86 1.04 4.96 Very Good  Line 3 13 800 13 820 20 1.37 0.99 1.08 0.66 0.62 4.73 Very Good  Line 3 13 820 13 840 20 1.48 1.57 0.45 1.05 1.78 6.33 Very Good  Line 3 13 840 13 860 20 2.01 1.57 0.64 2.8 2.01 9.02 Very Good  Line 3 13 860 13 880 20 1.96 0.73 0.61 1.22 1.13 5.65 Very Good  Line 3 13 880 13 900 20 2.73 0.82 0.63 3.86 5.93 13.98 Very Good  Line 3 13 900 13 920 20 1.55 1.15 0.64 1.7 2.16 7.21 Very Good  Line 3 13 920 13 940 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good  Line 3 13 940 13 960 20 1.93 1.09 1.16 0.75 0.82 5.75 Very Good	Line 3	13	740	13	760	20	1.12	2.44	0.52	0.7	1.15	5.94	Very Good
Line 3 13 800 13 820 20 1.37 0.99 1.08 0.66 0.62 4.73 Very Good Line 3 13 820 13 840 20 1.48 1.57 0.45 1.05 1.78 6.33 Very Good Line 3 13 840 13 860 20 2.01 1.57 0.64 2.8 2.01 9.02 Very Good Line 3 13 860 13 880 20 1.96 0.73 0.61 1.22 1.13 5.65 Very Good Line 3 13 880 13 900 20 2.73 0.82 0.63 3.86 5.93 13.98 Very Good Line 3 13 900 13 920 20 1.55 1.15 0.64 1.7 2.16 7.21 Very Good Line 3 13 920 13 940 20 0.81 0.79 0.78 1.11 1.96 5.44 Very Good Line 3 13 940 13 960 20 1.04 2.08 0.6 0.8 1.35 5.88 Very Good Line 3 13 960 13 980 20 1.93 1.09 1.16 0.75 0.82 5.75 Very Good	Line 3	13	760	13	780	20	0.83	1.2	0.94	0.64	1.17	4.77	Very Good
Line 3       13       820       13       840       20       1.48       1.57       0.45       1.05       1.78       6.33       Very Good         Line 3       13       840       13       860       20       2.01       1.57       0.64       2.8       2.01       9.02       Very Good         Line 3       13       860       13       880       20       1.96       0.73       0.61       1.22       1.13       5.65       Very Good         Line 3       13       880       13       900       20       2.73       0.82       0.63       3.86       5.93       13.98       Very Good         Line 3       13       900       13       920       20       1.55       1.15       0.64       1.7       2.16       7.21       Very Good         Line 3       13       920       13       940       20       0.81       0.79       0.78       1.11       1.96       5.44       Very Good         Line 3       13       940       13       960       20       1.04       2.08       0.6       0.8       1.35       5.88       Very Good         Line 3       13       960       13	Line 3	13	780	13	800	20	1.25	0.89	0.92	0.86	1.04	4.96	Very Good
Line 3       13       840       13       860       20       2.01       1.57       0.64       2.8       2.01       9.02       Very Good         Line 3       13       860       13       880       20       1.96       0.73       0.61       1.22       1.13       5.65       Very Good         Line 3       13       880       13       900       20       2.73       0.82       0.63       3.86       5.93       13.98       Very Good         Line 3       13       900       13       920       20       1.55       1.15       0.64       1.7       2.16       7.21       Very Good         Line 3       13       920       13       940       20       0.81       0.79       0.78       1.11       1.96       5.44       Very Good         Line 3       13       940       13       960       20       1.04       2.08       0.6       0.8       1.35       5.88       Very Good         Line 3       13       960       13       980       20       1.93       1.09       1.16       0.75       0.82       5.75       Very Good	Line 3	13	800	13	820	20	1.37	0.99	1.08	0.66	0.62	4.73	Very Good
Line 3         13         860         13         880         20         1.96         0.73         0.61         1.22         1.13         5.65         Very Good           Line 3         13         880         13         900         20         2.73         0.82         0.63         3.86         5.93         13.98         Very Good           Line 3         13         900         13         920         20         1.55         1.15         0.64         1.7         2.16         7.21         Very Good           Line 3         13         920         13         940         20         0.81         0.79         0.78         1.11         1.96         5.44         Very Good           Line 3         13         940         13         960         20         1.04         2.08         0.6         0.8         1.35         5.88         Very Good           Line 3         13         960         13         980         20         1.93         1.09         1.16         0.75         0.82         5.75         Very Good	Line 3	13	820	13	840	20	1.48	1.57	0.45	1.05	1.78	6.33	Very Good
Line 3         13         880         13         900         20         2.73         0.82         0.63         3.86         5.93         13.98         Very Good           Line 3         13         900         13         920         20         1.55         1.15         0.64         1.7         2.16         7.21         Very Good           Line 3         13         920         13         940         20         0.81         0.79         0.78         1.11         1.96         5.44         Very Good           Line 3         13         940         13         960         20         1.04         2.08         0.6         0.8         1.35         5.88         Very Good           Line 3         13         960         13         980         20         1.93         1.09         1.16         0.75         0.82         5.75         Very Good	Line 3	13	840	13	860	20	2.01	1.57	0.64	2.8	2.01	9.02	Very Good
Line 3         13         900         13         920         20         1.55         1.15         0.64         1.7         2.16         7.21         Very Good           Line 3         13         920         13         940         20         0.81         0.79         0.78         1.11         1.96         5.44         Very Good           Line 3         13         940         13         960         20         1.04         2.08         0.6         0.8         1.35         5.88         Very Good           Line 3         13         960         13         980         20         1.93         1.09         1.16         0.75         0.82         5.75         Very Good	Line 3	13	860	13	880	20	1.96	0.73	0.61	1.22	1.13	5.65	Very Good
Line 3         13         920         13         940         20         0.81         0.79         0.78         1.11         1.96         5.44         Very Good           Line 3         13         940         13         960         20         1.04         2.08         0.6         0.8         1.35         5.88         Very Good           Line 3         13         960         13         980         20         1.93         1.09         1.16         0.75         0.82         5.75         Very Good	Line 3	13	880	13	900	20	2.73	0.82	0.63	3.86	5.93	13.98	Very Good
Line 3         13         940         13         960         20         1.04         2.08         0.6         0.8         1.35         5.88         Very Good           Line 3         13         960         13         980         20         1.93         1.09         1.16         0.75         0.82         5.75         Very Good	Line 3	13	900	13	920	20	1.55	1.15	0.64	1.7	2.16	7.21	Very Good
Line 3 13 960 13 980 20 1.93 1.09 1.16 0.75 0.82 5.75 Very Good	Line 3	13	920	13	940	20	0.81	0.79	0.78	1.11	1.96	5.44	Very Good
	Line 3	13	940	13	960	20	1.04	2.08	0.6	0.8	1.35	5.88	Very Good
Line 3 13 980 14 0 20 2.36 0.93 0.7 1.6 1.97 7.57 Very Good	Line 3	13	960	13	980	20	1.93	1.09	1.16	0.75	0.82	5.75	Very Good
	Line 3	13	980	14	0	20	2.36	0.93	0.7	1.6	1.97	7.57	Very Good

Line 3													
Line 3	Line 3	14	0	14	20	20	2.62	2.0	0.73	1.23	1.38	7.96	Very Good
Line 3	Line 3	14	20	14	40	20	1.67	1.2	0.72	0.89	1.48	5.96	Very Good
Line 3	Line 3	14	40	14	60	20	2.54	2.67	0.52	1.12	3.47	10.31	Very Good
Line 3	Line 3	14	60	14	80	20	2.79	4.16	0.98	3.22	6.47	17.61	Very Good
Line 3	Line 3	14	80	14	100	20	12.54	4.25	0.99	6.28	5.47	29.53	Very Good
Line   14	Line 3	14	100	14	120	20	3.95	2.16	1.0	1.35	1.71	10.17	Very Good
Line 3	Line 3	14	120	14	140	20	2.04	1.26	0.84	1.8	2.24	8.17	Very Good
Line 3	Line 3	14	140	14	160	20	2.45	1.24	0.75	2.11	2.12	8.67	Very Good
Line 3 14 200 14 220 20 4495 1.7 0.59 0.74 1.23 9.21 Very Go Line 3 14 220 14 240 20 2.06 2.78 0.39 0.01 1.66 7.78 Very Go Line 3 14 240 14 260 20 7.08 3.27 1.03 1.45 1.00 13.9 Very Go Line 3 14 280 14 280 20 1.46 2.81 0.54 0.78 1.04 6.42 Very Go Line 3 14 280 14 300 20 4.57 0.7 0.3 0.73 0.78 7.08 Very Go Line 3 14 300 14 320 20 4.57 0.7 0.3 0.73 0.76 7.08 Very Go Line 3 14 300 14 320 20 4.23 1.47 0.73 0.77 1.22 8.43 Very Go Line 3 14 320 14 340 20 1.73 2.13 0.83 0.82 0.82 5.94 Very Go Line 3 14 340 14 360 20 2.84 1.32 0.85 0.88 1.55 7.35 Very Go Line 3 14 340 14 360 20 2.86 2.01 0.83 0.89 1.19 7.61 Very Go Line 3 14 360 14 400 20 2.17 2.34 1.11 0.66 1.03 7.3 Very Go Line 3 14 400 14 420 20 2.17 2.34 1.11 0.66 1.03 7.3 Very Go Line 3 14 440 14 460 20 2.45 2.33 0.83 1.46 2.47 9.53 Very Go Line 3 14 440 14 460 20 2.45 2.33 0.83 1.46 2.47 9.53 Very Go Line 3 14 440 14 460 20 2.45 2.33 0.83 1.46 2.47 9.53 Very Go Line 3 14 460 14 480 20 2.17 2.18 0.84 1.47 1.29 8.21 Very Go Line 3 14 460 14 480 20 2.17 2.34 1.11 0.66 1.03 7.3 Very Go Line 3 14 460 14 480 20 2.2 2.17 2.34 1.11 0.66 1.03 7.3 Very Go Line 3 14 460 14 480 20 2.2 2.17 2.34 1.11 0.66 1.03 7.3 Very Go Line 3 14 460 14 480 20 2.2 2.17 2.34 1.11 0.66 1.03 7.3 Very Go Line 3 14 460 14 480 20 2.2 2.17 2.34 1.11 0.66 1.03 7.3 Very Go Line 3 14 460 14 480 20 2.2 2.17 2.34 1.11 0.66 1.03 7.3 Very Go Line 3 14 460 14 480 20 2.2 2.57 2.1 0.64 1.47 1.22 8.21 Very Go Line 3 14 460 14 480 20 2.2 2.77 2.1 0.64 1.47 1.22 8.21 Very Go Line 3 14 460 14 480 20 2.2 2.85 2.35 0.72 2.55 1.8 11.68 Very Go Line 3 14 500 14 500 14 500 20 2.62 2.88 1.15 1.26 2.21 10.11 Very Go Line 3 14 500 14 500 14 500 20 2.62 2.88 1.15 1.26 2.21 10.11 Very Go Line 3 14 500 14 500 14 500 20 2.62 2.88 1.15 1.26 2.21 10.11 Very Go	Line 3	14	160	14	180	20	2.41	0.84	0.59	1.06	1.64	6.55	Very Good
Line 3 14 220 14 240 20 2.05 2.78 0.39 0.91 1.65 7.78 Very Go Line 3 14 240 14 280 20 1.46 2.61 0.54 0.78 1.09 13.9 Very Go Line 3 14 280 14 300 20 4.57 0.7 0.3 0.73 0.78 7.08 Very Go Line 3 14 300 14 320 20 4.57 0.7 0.3 0.73 0.77 1.22 8.43 Very Go Line 3 14 300 14 320 20 1.73 2.13 0.63 0.62 0.82 5.94 Very Go Line 3 14 340 14 360 20 2.88 2.01 0.83 0.99 1.19 7.61 Very Go Line 3 14 380 14 400 20 2.45 2.33 0.83 1.46 2.47 9.53 Very Go Line 3 14 420 14 440 20 20 2.77 2.1 0.64 1.47 1.23 8.21 Very Go Line 3 14 480 14 480 20 20 4.25 2.35 0.72 2.55 1.8 11.68 Very Go Line 3 14 480 14 560 20 2.82 2.88 1.15 1.26 2.21 10.11 Very Go Line 3 14 560 14 560 20 1.81 1.87 0.64 1.17 2.32 8.32 Very Go Line 3 14 560 14 560 20 1.81 1.87 0.64 1.17 2.32 8.32 Very Go Line 3 14 560 14 560 20 1.81 1.87 0.64 1.17 2.32 8.32 Very Go Line 3 14 560 14 560 20 1.81 1.87 0.64 1.17 2.32 8.32 Very Go Line 3 14 560 14 560 20 1.81 1.87 0.64 1.17 2.32 8.32 Very Go Line 3 14 560 14 560 20 1.81 1.87 0.64 1.17 2.32 8.32 Very Go Line 3 14 560 14 560 20 1.81 1.87 0.64 1.17 2.32 8.32 Very Go Line 3 14 560 14 560 20 2.82 2.88 1.15 1.26 2.21 10.11 Very Go Line 3 14 560 14 560 20 1.05 1.83 0.66 0.65 0.61 0.61 4.8 Very Go Line 3 14 560 14 560 20 1.05 1.63 0.66 0.65 0.61 4.8 Very Go Line 3 14 560 14 560 20 1.05 1.63 0.66 0.65 0.61 4.8 Very Go	Line 3	14	180	14	200	20	1.64	1.47	0.53	1.03	0.85	5.53	Very Good
Line 3         14         240         14         260         20         7.06         3.27         1.03         1.45         1.09         13.9         Very Go           Line 3         14         260         14         280         20         1.46         2.61         0.54         0.78         1.04         6.42         Very Go           Line 3         14         280         14         300         20         4.57         0.7         0.3         0.73         0.78         7.08         Very Go           Line 3         14         300         14         320         20         4.23         1.47         0.73         0.77         1.22         8.43         Very Go           Line 3         14         340         20         1.73         2.13         0.63         0.62         0.82         5.94         Very Go           Line 3         14         340         14         360         20         2.84         1.32         0.65         0.98         1.55         7.35         Very Go           Line 3         14         380         14         380         20         2.88         2.01         0.83         0.89         1.18         7.61	Line 3	14	200	14	220	20	4.95	1.7	0.59	0.74	1.23	9.21	Very Good
Line 3         14         280         14         280         20         1.46         2.61         0.54         0.78         1.04         6.42         Very Go           Line 3         14         280         14         300         20         4.57         0.7         0.3         0.73         0.78         7.08         Very Go           Line 3         14         300         14         320         20         4.23         1.47         0.73         0.77         1.22         8.43         Very Go           Line 3         14         320         14         340         20         1.73         2.13         0.63         0.62         0.82         5.94         Very Go           Line 3         14         340         14         380         20         2.84         1.32         0.65         0.98         1.55         7.35         Very Go           Line 3         14         380         14         380         20         2.68         2.01         0.83         0.89         1.19         7.61         Very Go           Line 3         14         400         14         420         20         2.17         2.34         1.1         0.66	Line 3	14	220	14	240	20	2.05	2.78	0.39	0.91	1.65	7.78	Very Good
Line 3         14         280         14         300         20         4.57         0.7         0.3         0.73         0.78         7.08         Very Go           Line 3         14         300         14         320         20         4.23         1.47         0.73         0.77         1.22         8.43         Very Go           Line 3         14         320         14         340         20         1.73         2.13         0.63         0.62         0.82         5.94         Very Go           Line 3         14         340         14         360         20         2.84         1.32         0.65         0.98         1.55         7.35         Very Go           Line 3         14         360         14         380         20         2.68         2.01         0.83         0.89         1.19         7.61         Very Go           Line 3         14         380         14         400         20         3.41         2.94         0.67         0.95         1.18         9.13         Very Go           Line 3         14         400         14         420         20         2.17         2.34         1.1         0.66	Line 3	14	240	14	260	20	7.06	3.27	1.03	1.45	1.09	13.9	Very Good
Line 3 14 300 14 320 20 4.23 1.47 0.73 0.77 1.22 8.43 Very Go Line 3 14 320 14 340 20 1.73 2.13 0.63 0.62 0.82 5.94 Very Go Line 3 14 340 14 360 20 2.84 1.32 0.65 0.98 1.55 7.35 Very Go Line 3 14 360 14 380 20 2.68 2.01 0.83 0.89 1.19 7.61 Very Go Line 3 14 380 14 400 20 3.41 2.94 0.67 0.95 1.18 9.13 Very Go Line 3 14 400 14 420 20 2.17 2.34 1.1 0.66 1.03 7.3 Very Go Line 3 14 420 14 440 20 2.45 2.33 0.83 1.46 2.47 9.53 Very Go Line 3 14 440 14 460 20 2.77 2.1 0.64 1.47 1.23 8.21 Very Go Line 3 14 460 14 480 20 3.3 1.84 0.83 1.95 4.23 12.14 Very Go Line 3 14 460 14 500 20 4.25 2.35 0.72 2.55 1.8 11.68 Very Go Line 3 14 500 14 520 20 1.81 1.87 0.54 1.77 2.32 8.32 Very Go Line 3 14 500 14 540 20 2.62 2.88 1.15 1.26 2.21 10.11 Very Go Line 3 14 540 14 540 20 2.62 2.88 1.15 1.26 2.21 10.11 Very Go	Line 3	14	260	14	280	20	1.46	2.61	0.54	0.78	1.04	6.42	Very Good
Line 3         14         320         14         340         20         1.73         2.13         0.63         0.62         0.82         5.94         Very Go           Line 3         14         340         14         360         20         2.84         1.32         0.65         0.98         1.55         7.35         Very Go           Line 3         14         360         14         380         20         2.68         2.01         0.83         0.89         1.19         7.61         Very Go           Line 3         14         380         14         400         20         3.41         2.94         0.67         0.95         1.18         9.13         Very Go           Line 3         14         400         14         420         20         2.17         2.34         1.1         0.66         1.03         7.3         Very Go           Line 3         14         420         14         440         20         2.45         2.33         0.83         1.46         2.47         9.53         Very Go           Line 3         14         440         14         460         20         2.77         2.1         0.64         1.47	Line 3	14	280	14	300	20	4.57	0.7	0.3	0.73	0.78	7.08	Very Good
Line 3         14         340         14         360         20         2.84         1.32         0.65         0.98         1.55         7.35         Very Go           Line 3         14         360         14         380         20         2.68         2.01         0.83         0.89         1.19         7.61         Very Go           Line 3         14         380         14         400         20         3.41         2.94         0.67         0.95         1.18         9.13         Very Go           Line 3         14         400         14         420         20         2.17         2.34         1.1         0.66         1.03         7.3         Very Go           Line 3         14         420         14         440         20         2.45         2.33         0.83         1.46         2.47         9.53         Very Go           Line 3         14         440         14         440         20         2.77         2.1         0.64         1.47         1.23         8.21         Very Go           Line 3         14         460         14         480         20         3.3         1.84         0.83         1.95         4	Line 3	14	300	14	320	20	4.23	1.47	0.73	0.77	1.22	8.43	Very Good
Line 3         14         360         14         380         20         2.68         2.01         0.83         0.89         1.19         7.61         Very Go           Line 3         14         380         14         400         20         3.41         2.94         0.67         0.95         1.18         9.13         Very Go           Line 3         14         400         14         420         20         2.17         2.34         1.1         0.66         1.03         7.3         Very Go           Line 3         14         420         14         440         20         2.45         2.33         0.83         1.46         2.47         9.53         Very Go           Line 3         14         440         14         460         20         2.77         2.1         0.64         1.47         1.23         8.21         Very Go           Line 3         14         460         14         480         20         3.3         1.84         0.83         1.95         4.23         12.14         Very Go           Line 3         14         480         14         500         20         4.25         2.35         0.72         2.55	Line 3	14	320	14	340	20	1.73	2.13	0.63	0.62	0.82	5.94	Very Good
Line 3         14         380         14         400         20         3.41         2.94         0.67         0.95         1.18         9.13         Very Go           Line 3         14         400         14         420         20         2.17         2.34         1.1         0.66         1.03         7.3         Very Go           Line 3         14         420         14         440         20         2.45         2.33         0.83         1.46         2.47         9.53         Very Go           Line 3         14         440         14         460         20         2.77         2.1         0.64         1.47         1.23         8.21         Very Go           Line 3         14         460         14         480         20         3.3         1.84         0.83         1.95         4.23         12.14         Very Go           Line 3         14         480         14         500         20         4.25         2.35         0.72         2.55         1.8         11.68         Very Go           Line 3         14         500         14         520         20         1.81         1.87         0.54         1.77	Line 3	14	340	14	360	20	2.84	1.32	0.65	0.98	1.55	7.35	Very Good
Line 3         14         400         14         420         20         2.17         2.34         1.1         0.66         1.03         7.3         Very God           Line 3         14         420         14         440         20         2.45         2.33         0.83         1.46         2.47         9.53         Very God           Line 3         14         440         14         460         20         2.77         2.1         0.64         1.47         1.23         8.21         Very God           Line 3         14         460         14         480         20         3.3         1.84         0.83         1.95         4.23         12.14         Very God           Line 3         14         480         14         500         20         4.25         2.35         0.72         2.55         1.8         11.68         Very God           Line 3         14         500         14         520         20         1.81         1.87         0.54         1.77         2.32         8.32         Very God           Line 3         14         520         14         540         20         2.62         2.88         1.15         1.26	Line 3	14	360	14	380	20	2.68	2.01	0.83	0.89	1.19	7.61	Very Good
Line 3         14         420         14         440         20         2.45         2.33         0.83         1.46         2.47         9.53         Very God           Line 3         14         440         14         460         20         2.77         2.1         0.64         1.47         1.23         8.21         Very God           Line 3         14         460         14         480         20         3.3         1.84         0.83         1.95         4.23         12.14         Very God           Line 3         14         480         14         500         20         4.25         2.35         0.72         2.55         1.8         11.68         Very God           Line 3         14         500         14         520         20         1.81         1.87         0.54         1.77         2.32         8.32         Very God           Line 3         14         520         14         540         20         2.62         2.88         1.15         1.26         2.21         10.11         Very God           Line 3         14         540         14         560         20         1.05         1.63         0.66         0.55	Line 3	14	380	14	400	20	3.41	2.94	0.67	0.95	1.18	9.13	Very Good
Line 3         14         440         14         460         20         2.77         2.1         0.64         1.47         1.23         8.21         Very God           Line 3         14         460         14         480         20         3.3         1.84         0.83         1.95         4.23         12.14         Very God           Line 3         14         480         14         500         20         4.25         2.35         0.72         2.55         1.8         11.68         Very God           Line 3         14         500         14         520         20         1.81         1.87         0.54         1.77         2.32         8.32         Very God           Line 3         14         520         14         540         20         2.62         2.88         1.15         1.26         2.21         10.11         Very God           Line 3         14         540         14         560         20         1.05         1.63         0.66         0.55         0.91         4.8         Very God	Line 3	14	400	14	420	20	2.17	2.34	1.1	0.66	1.03	7.3	Very Good
Line 3 14 460 14 480 20 3.3 1.84 0.83 1.95 4.23 12.14 Very Got Line 3 14 480 14 500 20 4.25 2.35 0.72 2.55 1.8 11.68 Very Got Line 3 14 500 14 520 20 1.81 1.87 0.54 1.77 2.32 8.32 Very Got Line 3 14 520 14 540 20 2.62 2.88 1.15 1.26 2.21 10.11 Very Got Line 3 14 540 14 560 20 1.05 1.63 0.66 0.55 0.91 4.8 Very Got Line 3 14 540 14 550 20 1.05 1.63 0.66 0.55 0.91 4.8 Very Got Line 3 14 540 14 550 20 1.05 1.63 0.66 0.55 0.91 4.8 Very Got Line 3 14 540 14 550 20 1.05 1.63 0.66 0.55 0.91 4.8 Very Got Line 3 14 540 14 550 20 1.05 1.63 0.66 0.55 0.91 4.8 Very Got Line 3 14 550 150 150 150 150 150 150 150 150 150	Line 3	14	420	14	440	20	2.45	2.33	0.83	1.46	2.47	9.53	Very Good
Line 3     14     480     14     500     20     4.25     2.35     0.72     2.55     1.8     11.68     Very Got       Line 3     14     500     14     520     20     1.81     1.87     0.54     1.77     2.32     8.32     Very Got       Line 3     14     520     14     540     20     2.62     2.88     1.15     1.26     2.21     10.11     Very Got       Line 3     14     540     14     560     20     1.05     1.63     0.66     0.55     0.91     4.8     Very Got	Line 3	14	440	14	460	20	2.77	2.1	0.64	1.47	1.23	8.21	Very Good
Line 3     14     500     14     520     20     1.81     1.87     0.54     1.77     2.32     8.32     Very God       Line 3     14     520     14     540     20     2.62     2.88     1.15     1.26     2.21     10.11     Very God       Line 3     14     540     14     560     20     1.05     1.63     0.66     0.55     0.91     4.8     Very God	Line 3	14	460	14	480	20	3.3	1.84	0.83	1.95	4.23	12.14	Very Good
Line 3 14 520 14 540 20 2.62 2.88 1.15 1.26 2.21 10.11 Very Gov Line 3 14 540 14 560 20 1.05 1.63 0.66 0.55 0.91 4.8 Very Gov	Line 3	14	480	14	500	20	4.25	2.35	0.72	2.55	1.8	11.68	Very Good
Line 3 14 540 14 560 20 1.05 1.63 0.66 0.55 0.91 4.8 Very God	Line 3	14	500	14	520	20	1.81	1.87	0.54	1.77	2.32	8.32	Very Good
	Line 3	14	520	14	540	20	2.62	2.88	1.15	1.26	2.21	10.11	Very Good
Line 3 14 560 14 580 20 0.57 0.5 0.43 0.76 1.04 3.3 Very Gor	Line 3	14	540	14	560	20	1.05	1.63	0.66	0.55	0.91	4.8	Very Good
	Line 3	14	560	14	580	20	0.57	0.5	0.43	0.76	1.04	3.3	Very Good
Line 3 14 580 14 600 20 0.74 0.69 0.77 0.58 0.7 3.48 Very God	Line 3	14	580	14	600	20	0.74	0.69	0.77	0.58	0.7	3.48	Very Good

148													
The color of the	Line 3	14	600	14	620	20	1.68	1.45	0.86	1.16	2.06	7.22	Very Good
The color of the	Line 3	14	620	14	640	20	0.96	1.75	0.54	0.69	1.38	5.32	Very Good
The color of the	Line 3	14	640	14	660	20	4.38	1.47	0.58	0.73	0.85	8.0	Very Good
Ches	Line 3	14	660	14	680	20	2.65	0.63	0.24	0.85	1.24	5.61	Very Good
Hine 3	Line 3	14	680	14	700	20	0.43	1.34	0.87	0.46	0.86	3.97	Very Good
Mine	Line 3	14	700	14	720	20	0.88	1.47	0.66	0.8	1.01	4.82	Very Good
Line	Line 3	14	720	14	740	20	1.65	0.8	0.69	1.11	1.09	5.34	Very Good
Time	Line 3	14	740	14	760	20	1.34	0.99	0.81	0.93	1.03	5.09	Very Good
Line 3	Line 3	14	760	14	780	20	0.86	1.37	0.67	1.03	1.59	5.53	Very Good
Line 3	Line 3	14	780	14	800	20	1.02	1.13	1.39	0.64	0.87	5.06	Very Good
Line 3	Line 3	14	800	14	820	20	1.2	1.42	0.64	0.51	0.61	4.39	Very Good
Line 3         14         880         14         880         20         2.4         2.12         0.61         1.52         3.08         9.73         Very Good           Line 3         14         880         14         900         20         1.51         3.92         0.52         3.53         3.53         13.01         Very Good           Line 3         14         900         14         920         20         2.13         1.33         1.18         2.31         1.64         8.58         Very Good           Line 3         14         920         14         940         20         1.92         2.01         0.92         0.74         1.5         7.09         Very Good           Line 3         14         940         14         960         20         1.12         1.2         0.71         2.02         2.37         7.42         Very Good           Line 3         14         960         14         980         20         0.73         0.59         0.79         0.98         0.7         3.8         Very Good           Line 3         15         0         15         0         20         0.92         0.8         0.79         0.75	Line 3	14	820	14	840	20	0.74	1.5	0.63	0.57	0.69	4.13	Very Good
Line 3 14 880 14 900 14 920 20 1.51 3.92 0.52 3.53 3.53 13.01 Very Good Line 3 14 920 14 940 20 1.82 2.01 0.92 0.74 1.5 7.09 Very Good Line 3 14 940 14 980 20 14 980 20 1.12 1.2 0.71 2.02 2.37 7.42 Very Good Line 3 14 960 14 980 20 0.73 0.59 0.79 0.98 0.7 3.8 Very Good Line 3 14 980 15 0 20 0.92 0.8 0.79 0.95 0.79 0.98 0.7 3.8 Very Good Line 3 15 0 15 20 20 1.81 1.46 1.84 2.83 2.94 10.89 Very Good Line 3 15 40 15 60 20 1.57 1.32 1.02 0.61 2.85 7.37 Very Good Line 3 15 60 15 80 20 1.57 0.87 0.55 1.73 3.56 8.28 Very Good Line 3 15 80 15 100 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good Line 3 15 80 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good Line 3 15 80 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good Line 3 15 80 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good Line 3 15 100 15 120 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good Line 3 15 100 15 140 20 0.82 1.21 1.09 0.59 0.57 4.28 Very Good Line 3 15 100 15 140 20 0.82 1.21 1.09 0.59 0.57 4.28 Very Good Line 3 15 120 15 140 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 120 15 140 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good	Line 3	14	840	14	860	20	1.18	0.88	0.65	1.28	1.59	5.59	Very Good
Line 3 14 900 14 920 20 213 1.33 1.18 2.31 1.64 8.58 Very Good Line 3 14 940 14 980 20 1.12 1.2 0.71 2.02 2.37 7.42 Very Good Line 3 14 980 14 980 20 0.73 0.59 0.79 0.98 0.7 3.8 Very Good Line 3 14 980 15 0 20 0.82 0.8 0.79 0.76 0.91 4.17 Very Good Line 3 15 0 15 20 20 1.81 1.46 1.84 2.83 2.94 10.89 Very Good Line 3 15 40 15 60 20 1.57 0.87 0.55 1.73 3.56 8.28 Very Good Line 3 15 60 15 80 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good Line 3 15 90 15 100 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good Line 3 15 90 15 100 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good Line 3 15 90 15 100 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good Line 3 15 90 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good Line 3 15 100 15 120 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good Line 3 15 100 15 120 20 1.25 0.96 0.98 1.3 1.17 5.66 Very Good Line 3 15 100 15 140 20 0.82 1.21 1.09 0.59 0.57 4.28 Very Good Line 3 15 120 15 140 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 120 15 140 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 155 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good	Line 3	14	860	14	880	20	2.4	2.12	0.61	1.52	3.08	9.73	Very Good
Line 3         14         920         14         940         20         1.92         2.01         0.92         0.74         1.5         7.09         Very Good           Line 3         14         940         14         960         20         1.12         1.2         0.71         2.02         2.37         7.42         Very Good           Line 3         14         980         14         980         20         0.73         0.59         0.79         0.98         0.7         3.8         Very Good           Line 3         14         980         15         0         20         0.92         0.8         0.79         0.75         0.91         4.17         Very Good           Line 3         15         0         15         20         20         1.81         1.46         1.84         2.83         2.94         10.89         Very Good           Line 3         15         20         15         40         20         1.57         1.32         1.02         0.61         2.85         7.37         Very Good           Line 3         15         40         15         60         20         1.57         0.87         0.55         1.73 <t< td=""><td>Line 3</td><td>14</td><td>880</td><td>14</td><td>900</td><td>20</td><td>1.51</td><td>3.92</td><td>0.52</td><td>3.53</td><td>3.53</td><td>13.01</td><td>Very Good</td></t<>	Line 3	14	880	14	900	20	1.51	3.92	0.52	3.53	3.53	13.01	Very Good
Line 3 14 940 14 960 20 1.12 1.2 0.71 2.02 2.37 7.42 Very Good Line 3 14 960 14 980 20 0.73 0.59 0.79 0.98 0.7 3.8 Very Good Line 3 14 980 15 0 20 0.92 0.8 0.79 0.75 0.91 4.17 Very Good Line 3 15 0 15 20 20 1.81 1.46 1.84 2.83 2.94 10.89 Very Good Line 3 15 20 15 40 20 1.57 1.32 1.02 0.61 2.85 7.37 Very Good Line 3 15 40 15 60 20 1.57 0.87 0.55 1.73 3.56 8.28 Very Good Line 3 15 60 15 80 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good Line 3 15 80 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good Line 3 15 100 15 120 20 1.25 0.96 0.98 1.3 1.17 5.66 Very Good Line 3 15 100 15 120 20 0.82 1.21 1.09 0.59 0.57 4.28 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 160 15 180 20 0.77 0.67 0.72 0.87 1.13 4.16 Very Good	Line 3	14	900	14	920	20	2.13	1.33	1.18	2.31	1.64	8.58	Very Good
Line 3 14 960 14 980 20 0.73 0.59 0.79 0.98 0.7 3.8 Very Good  Line 3 14 980 15 0 20 0.92 0.8 0.79 0.75 0.91 4.17 Very Good  Line 3 15 0 15 20 15 40 20 1.57 1.32 1.02 0.61 2.85 7.37 Very Good  Line 3 15 40 15 80 20 1.57 0.87 0.55 1.73 3.56 8.28 Very Good  Line 3 15 60 15 80 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good  Line 3 15 80 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good  Line 3 15 100 15 120 20 1.25 0.96 0.98 1.3 1.17 5.66 Very Good  Line 3 15 100 15 140 20 0.82 1.21 1.09 0.59 0.57 4.28 Very Good  Line 3 15 160 15 180 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good  Line 3 15 160 15 180 20 0.77 0.67 0.72 0.87 1.13 4.16 Very Good	Line 3	14	920	14	940	20	1.92	2.01	0.92	0.74	1.5	7.09	Very Good
Line 3 14 980 15 0 20 0.92 0.8 0.79 0.75 0.91 4.17 Very Good Line 3 15 0 15 20 20 1.81 1.46 1.84 2.83 2.94 10.89 Very Good Line 3 15 20 15 40 20 1.57 1.32 1.02 0.61 2.85 7.37 Very Good Line 3 15 40 15 60 20 1.57 0.87 0.55 1.73 3.56 8.28 Very Good Line 3 15 60 15 80 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good Line 3 15 80 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good Line 3 15 100 15 120 20 1.25 0.96 0.98 1.3 1.17 5.66 Very Good Line 3 15 120 15 140 20 0.82 1.21 1.09 0.59 0.57 4.28 Very Good Line 3 15 160 15 180 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good Line 3 15 160 15 180 20 0.77 0.67 0.72 0.87 1.13 4.16 Very Good	Line 3	14	940	14	960	20	1.12	1.2	0.71	2.02	2.37	7.42	Very Good
Line 3 15 0 15 40 20 1.81 1.46 1.84 2.83 2.94 10.89 Very Good  Line 3 15 20 15 40 20 1.57 1.32 1.02 0.61 2.85 7.37 Very Good  Line 3 15 40 15 60 20 1.57 0.87 0.55 1.73 3.56 8.28 Very Good  Line 3 15 60 15 80 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good  Line 3 15 80 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good  Line 3 15 100 15 120 20 1.25 0.96 0.98 1.3 1.17 5.66 Very Good  Line 3 15 120 15 140 20 0.82 1.21 1.09 0.59 0.57 4.28 Very Good  Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good  Line 3 15 160 15 180 20 0.77 0.67 0.72 0.87 1.13 4.16 Very Good	Line 3	14	960	14	980	20	0.73	0.59	0.79	0.98	0.7	3.8	Very Good
Line 3         15         20         15         40         20         1.57         1.32         1.02         0.61         2.85         7.37         Very Good           Line 3         15         40         15         60         20         1.57         0.87         0.55         1.73         3.56         8.28         Very Good           Line 3         15         60         15         80         20         1.57         1.4         1.04         4.8         2.48         11.28         Very Good           Line 3         15         80         15         100         20         1.58         1.14         0.61         2.52         1.89         7.72         Very Good           Line 3         15         100         15         120         20         1.25         0.96         0.98         1.3         1.17         5.66         Very Good           Line 3         15         120         15         140         20         0.82         1.21         1.09         0.59         0.57         4.28         Very Good           Line 3         15         140         15         160         20         0.82         0.83         0.5         0.84	Line 3	14	980	15	0	20	0.92	0.8	0.79	0.75	0.91	4.17	Very Good
Line 3 15 40 15 60 20 1.57 0.87 0.55 1.73 3.56 8.28 Very Good  Line 3 15 60 15 80 20 1.57 1.4 1.04 4.8 2.48 11.28 Very Good  Line 3 15 80 15 100 20 1.58 1.14 0.61 2.52 1.89 7.72 Very Good  Line 3 15 100 15 120 20 1.25 0.96 0.98 1.3 1.17 5.66 Very Good  Line 3 15 120 15 140 20 0.82 1.21 1.09 0.59 0.57 4.28 Very Good  Line 3 15 140 15 160 20 0.82 0.83 0.5 0.84 1.32 4.32 Very Good  Line 3 15 160 15 180 20 0.77 0.67 0.72 0.87 1.13 4.16 Very Good	Line 3	15	0	15	20	20	1.81	1.46	1.84	2.83	2.94	10.89	Very Good
Line 3         15         60         15         80         20         1.57         1.4         1.04         4.8         2.48         11.28         Very Good           Line 3         15         80         15         100         20         1.58         1.14         0.61         2.52         1.89         7.72         Very Good           Line 3         15         100         15         120         20         1.25         0.96         0.98         1.3         1.17         5.66         Very Good           Line 3         15         120         15         140         20         0.82         1.21         1.09         0.59         0.57         4.28         Very Good           Line 3         15         140         15         160         20         0.82         0.83         0.5         0.84         1.32         4.32         Very Good           Line 3         15         160         15         180         20         0.77         0.67         0.72         0.87         1.13         4.16         Very Good	Line 3	15	20	15	40	20	1.57	1.32	1.02	0.61	2.85	7.37	Very Good
Line 3         15         80         15         100         20         1.58         1.14         0.61         2.52         1.89         7.72         Very Good           Line 3         15         100         15         120         20         1.25         0.96         0.98         1.3         1.17         5.66         Very Good           Line 3         15         120         15         140         20         0.82         1.21         1.09         0.59         0.57         4.28         Very Good           Line 3         15         140         15         160         20         0.82         0.83         0.5         0.84         1.32         4.32         Very Good           Line 3         15         160         15         180         20         0.77         0.67         0.72         0.87         1.13         4.16         Very Good	Line 3	15	40	15	60	20	1.57	0.87	0.55	1.73	3.56	8.28	Very Good
Line 3         15         100         15         120         20         1.25         0.96         0.98         1.3         1.17         5.66         Very Good           Line 3         15         120         15         140         20         0.82         1.21         1.09         0.59         0.57         4.28         Very Good           Line 3         15         140         15         160         20         0.82         0.83         0.5         0.84         1.32         4.32         Very Good           Line 3         15         160         15         180         20         0.77         0.67         0.72         0.87         1.13         4.16         Very Good	Line 3	15	60	15	80	20	1.57	1.4	1.04	4.8	2.48	11.28	Very Good
Line 3         15         120         15         140         20         0.82         1.21         1.09         0.59         0.57         4.28         Very Good           Line 3         15         140         15         160         20         0.82         0.83         0.5         0.84         1.32         4.32         Very Good           Line 3         15         160         15         180         20         0.77         0.67         0.72         0.87         1.13         4.16         Very Good	Line 3	15	80	15	100	20	1.58	1.14	0.61	2.52	1.89	7.72	Very Good
Line 3         15         140         15         160         20         0.82         0.83         0.5         0.84         1.32         4.32         Very Good           Line 3         15         160         15         180         20         0.77         0.67         0.72         0.87         1.13         4.16         Very Good	Line 3	15	100	15	120	20	1.25	0.96	0.98	1.3	1.17	5.66	Very Good
Line 3 15 160 15 180 20 0.77 0.67 0.72 0.87 1.13 4.16 Very Good	Line 3	15	120	15	140	20	0.82	1.21	1.09	0.59	0.57	4.28	Very Good
	Line 3	15	140	15	160	20	0.82	0.83	0.5	0.84	1.32	4.32	Very Good
Line 3 15 180 15 200 20 0.75 1.81 0.64 1.25 1.19 5.65 Very Good	Line 3	15	160	15	180	20	0.77	0.67	0.72	0.87	1.13	4.16	Very Good
	Line 3	15	180	15	200	20	0.75	1.81	0.64	1.25	1.19	5.65	Very Good

Line 3													
Line 3	Line 3	15	200	15	220	20	0.64	2.44	1.15	0.42	0.58	5.23	Very Good
Line   1   15   290   15   290   20   20   123   131   0.83   1.17   6.5   Viry On	Line 3	15	220	15	240	20	4.42	1.39	0.62	0.6	0.69	7.72	Very Good
Line   15	Line 3	15	240	15	260	20	6.13	1.17	1.31	0.75	1.37	10.73	Very Good
Line 3	Line 3	15	260	15	280	20	2.0	1.23	1.31	0.83	1.12	6.5	Very Good
Line 3	Line 3	15	280	15	300	20	1.64	1.26	1.41	1.01	0.91	6.23	Very Good
Line 3 16 340 15 360 20 1.38 1.08 0.76 1.23 1.42 5.87 Very Go Line 3 16 380 15 380 20 1.45 0.51 0.52 0.88 1.45 4.92 Very Go Line 3 15 380 15 380 20 1.45 0.51 0.52 0.88 2.15 0.55 Very Go Line 3 15 380 15 400 20 1.83 1.18 0.72 0.88 2.15 0.55 Very Go Line 3 15 400 15 420 20 2.76 1.04 0.6 1.53 3.91 9.84 Very Go Line 3 15 440 15 480 20 1.45 0.9 0.88 1.81 3.01 8.83 Very Go Line 3 15 440 15 480 20 1.45 0.9 0.89 1.51 2.25 7.8 Very Go Line 3 15 480 15 480 20 1.45 0.9 0.89 1.51 2.25 7.8 Very Go Line 3 15 480 15 500 20 1.45 0.9 0.89 1.51 2.25 7.8 Very Go Line 3 15 480 15 500 20 3.44 1.91 0.72 2.56 3.46 12.09 Very Go Line 3 15 500 15 500 20 3.37 1.94 0.61 2.5 4.04 12.46 Very Go Line 3 15 500 15 540 20 1.94 0.7 0.62 3.39 5.15 1.181 Very Go Line 3 15 500 15 540 20 1.94 0.7 0.62 3.39 5.15 1.181 Very Go Line 3 15 500 15 560 20 1.94 0.7 0.62 3.39 5.15 1.181 Very Go Line 3 15 560 20 1.5 560 20 1.94 0.7 0.62 3.39 5.15 1.181 Very Go Line 3 15 560 15 680 20 2.42 1.38 0.69 3.33 5.16 1.12.05 Very Go Line 3 15 560 15 680 20 2.42 1.38 0.69 3.33 5.16 1.12.05 Very Go Line 3 15 600 15 660 20 2.42 2.7 0.49 3.20 4.42 1.13 0.64 2.19 3.76 1.041 Very Go Line 3 15 660 15 660 20 2.42 1.8 0.89 5.32 5.14 1.73 Very Go Line 3 15 600 15 660 20 2.42 1.8 0.89 5.32 5.14 1.73 Very Go Line 3 15 600 15 660 20 2.42 1.8 0.89 5.32 5.14 1.73 Very Go Line 3 15 600 15 660 20 2.42 1.8 0.89 5.32 5.14 1.73 Very Go Line 3 15 600 15 660 20 2.42 1.8 0.89 5.32 5.14 1.73 Very Go Line 3 15 600 15 660 20 2.42 1.8 0.89 5.32 5.14 1.73 Very Go Line 3 15 600 15 600 20 2.42 1.8 0.89 5.32 5.14 1.73 Very Go Line 3 15 700 15 700 20 2.14 1.0 0.8 1.66 2.79 3.11 2.52 Very Go Line 3 15 700 15 700 20 2.14 1.0 0.8 1.66 2.29 3.11 2.52 Very Go Line 3 15 700 15 700 20 2.14 1.0 0.8 1.66 0.59 8.83 3.29 0.60 Line 3 15 700 15 700 20 1.18 Very Go Line 3 15 700 15 700 20 1.18 1.80 Very Go Line 3 15 700 15 700 20 1.18 1.80 Very Go Line 3 15 700 15 700 20 1.18 1.80 Very Go Line 3 15 700 15 700 20 1.18 1.80 Very Go Line 3 15 700 15 700 15 700 20 1.18 1.80 Very Go Line 3 15 700 15 700 15 700 20 1.1	Line 3	15	300	15	320	20	1.41	1.74	1.08	0.84	1.35	6.41	Very Good
Line 3	Line 3	15	320	15	340	20	1.0	1.29	0.68	1.17	2.12	6.26	Very Good
Line 3 15 380 15 400 20 1.63 1.18 0.72 0.88 2.15 6.55 Very Gold Line 3 15 400 15 420 20 2.76 1.04 0.6 1.53 3.91 9.84 Very Gold Line 3 15 420 15 440 20 3.13 0.71 0.08 1.31 3.01 8.83 Very Gold Line 3 15 440 15 460 20 1.45 0.9 0.99 1.81 2.55 7.8 Very Gold Line 3 15 460 15 460 20 4.57 1.0 0.82 2.01 3.54 11.84 Very Gold Line 3 15 460 15 500 20 3.44 1.91 0.72 2.56 3.46 12.09 Very Gold Line 3 15 500 15 520 20 3.37 1.94 0.81 2.5 4.04 12.46 Very Gold Line 3 15 500 15 520 20 3.37 1.94 0.81 2.5 4.04 12.46 Very Gold Line 3 15 500 15 520 20 3.37 1.94 0.81 2.5 4.04 12.46 Very Gold Line 3 15 500 15 520 20 3.37 1.94 0.81 2.5 4.04 12.46 Very Gold Line 3 15 500 15 520 20 3.37 1.94 0.81 2.5 4.04 12.46 Very Gold Line 3 15 500 15 520 20 3.37 1.94 0.81 2.5 4.04 12.46 Very Gold Line 3 15 500 15 520 20 3.37 1.94 0.81 2.5 4.04 12.46 Very Gold Line 3 15 500 15 520 20 3.37 1.94 0.81 2.5 4.04 12.46 Very Gold Line 3 15 500 15 500 20 3.14 0.95 1.07 0.82 3.39 5.15 11.81 Very Gold Line 3 15 500 15 500 20 20 3.14 0.95 1.07 2.88 2.8 10.64 Very Gold Line 3 15 500 15 500 20 2.49 1.38 0.69 3.33 5.16 13.05 Very Gold Line 3 15 500 15 500 20 2.49 1.38 0.69 3.33 5.16 13.05 Very Gold Line 3 15 500 15 600 20 2.249 1.38 0.69 3.33 5.16 13.05 Very Gold Line 3 15 600 15 600 20 4.22 2.7 0.49 3.26 4.82 15.58 Very Gold Line 3 15 600 15 600 20 2.05 0.94 0.76 2.88 3.53 9.88 Very Gold Line 3 15 600 15 600 20 2.25 0.94 0.76 2.88 3.53 9.88 Very Gold Line 3 15 600 15 600 20 2.25 0.94 0.76 2.28 3.53 9.88 Very Gold Line 3 15 600 15 600 20 2.26 0.94 0.76 2.28 3.53 9.88 Very Gold Line 3 15 600 15 700 20 2.14 0.08 0.89 0.72 3.11 2.22 9.82 Very Gold Line 3 15 600 15 700 20 2.14 0.09 0.72 3.11 2.22 9.82 Very Gold Line 3 15 700 15 740 20 7.23 2.31 0.08 0.72 3.11 2.22 9.82 Very Gold Line 3 15 700 15 740 20 7.23 2.31 0.08 0.72 3.11 2.22 9.82 Very Gold Line 3 15 740 15 740 20 7.23 2.31 0.08 0.72 3.11 0.07 2.28 0.09 0.09 0.09 0.09 0.09 0.09 0.09 0.0	Line 3	15	340	15	360	20	1.38	1.08	0.76	1.23	1.42	5.87	Very Good
Line 3 15 400 15 420 20 2.76 1.04 0.6 1.63 3.91 9.84 Very Go Line 3 15 420 15 440 20 3.13 0.71 0.68 1.31 3.01 8.83 Very Go Line 3 15 440 15 440 20 3.13 0.71 0.68 1.31 3.01 8.83 Very Go Line 3 15 440 15 440 20 4.57 1.0 0.82 2.01 3.54 11.94 Very Go Line 3 15 480 15 500 20 3.44 1.91 0.72 2.56 3.46 12.09 Very Go Line 3 15 500 15 500 20 3.44 1.91 0.72 2.56 3.46 12.09 Very Go Line 3 15 500 15 540 20 1.94 0.7 0.62 3.39 5.15 11.81 Very Go Line 3 15 500 15 540 20 1.94 0.7 0.62 3.39 5.15 11.81 Very Go Line 3 15 550 15 550 20 3.14 0.95 1.07 2.68 2.8 10.64 Very Go Line 3 15 550 15 550 20 3.14 0.95 1.07 2.68 2.8 10.64 Very Go Line 3 15 550 15 550 20 2.49 1.38 0.69 3.33 5.16 13.05 Very Go Line 3 15 550 15 550 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Go Line 3 15 550 15 600 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Go Line 3 15 600 15 620 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Go Line 3 15 600 15 620 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Go Line 3 15 600 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 620 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 620 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 620 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 620 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 620 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 600 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 600 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 600 15 640 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 600 15 640 20 2.12 1.71 0.69 0.72 3.11 2.92 9.62 Very Go Line 3 15 700 15 720 20 2.18 0.69 0.72 3.11 2.92 9.62 Very Go Line 3 15 700 15 720 20 2.18 0.69 0.72 3.11 2.92 9.62 Very Go Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.00 9.69 Very Go Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.00 9.69 Very Go Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.00 9.69 Very Go Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.00 9.69 Very Go Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.00 9.69 Very Go Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.00 9.69 Very	Line 3	15	360	15	380	20	1.45	0.51	0.52	0.98	1.45	4.92	Very Good
Line 3	Line 3	15	380	15	400	20	1.63	1.18	0.72	0.88	2.15	6.55	Very Good
Line 3	Line 3	15	400	15	420	20	2.76	1.04	0.6	1.53	3.91	9.84	Very Good
Line 3         15         460         15         480         20         4.57         1.0         0.82         2.01         3.54         11.94         Very Go           Line 3         15         480         15         500         20         3.44         1.91         0.72         2.56         3.46         12.09         Very Go           Line 3         15         500         15         520         20         3.37         1.94         0.61         2.5         4.04         12.46         Very Go           Line 3         15         520         15         540         20         1.94         0.7         0.62         3.39         5.15         11.81         Very Go           Line 3         15         540         15         560         20         3.14         0.95         1.07         2.68         2.8         10.64         Very Go           Line 3         15         580         15         580         20         2.49         1.38         0.69         3.33         5.16         13.05         Very Go           Line 3         15         580         15         600         20         4.22         2.7         0.49         3.26	Line 3	15	420	15	440	20	3.13	0.71	0.68	1.31	3.01	8.83	Very Good
Line 3         15         480         15         500         20         3.44         1.91         0.72         2.56         3.46         12.09         Very Go           Line 3         15         500         15         520         20         3.37         1.94         0.61         2.5         4.04         12.46         Very Go           Line 3         15         520         15         540         20         1.94         0.7         0.62         3.39         5.15         11.81         Very Go           Line 3         15         540         15         560         20         3.14         0.95         1.07         2.68         2.8         10.64         Very Go           Line 3         15         560         15         580         20         2.49         1.38         0.69         3.33         5.16         13.05         Very Go           Line 3         15         580         15         600         20         4.22         2.7         0.49         3.26         4.92         15.58         Very Go           Line 3         15         600         15         620         20         2.12         1.71         0.64         2.19	Line 3	15	440	15	460	20	1.45	0.9	0.89	1.61	2.95	7.8	Very Good
Line 3 15 500 15 520 20 3.37 1.94 0.61 2.5 4.04 12.46 Very Go Line 3 15 520 15 540 20 1.94 0.7 0.62 3.39 5.15 11.81 Very Go Line 3 15 540 15 560 20 3.14 0.95 1.07 2.68 2.8 10.64 Very Go Line 3 15 560 15 580 20 2.49 1.38 0.69 3.33 5.16 13.05 Very Go Line 3 15 580 15 600 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Go Line 3 15 680 15 620 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 620 15 640 20 2.05 0.94 0.78 2.68 3.53 9.98 Very Go Line 3 15 660 15 660 20 4.22 1.8 0.85 5.32 5.14 17.33 Very Go Line 3 15 660 15 680 20 2.63 1.09 0.98 1.69 2.79 9.18 Very Go Line 3 15 660 15 700 20 2.18 0.69 0.72 3.11 2.92 9.62 Very Go Line 3 15 700 15 740 20 7.23 2.31 0.78 4.15 10.79 25.26 Very Go Line 3 15 740 15 760 20 11.91 2.66 0.59 8.03 9.8 32.99 Good Line 3 15 740 15 760 20 11.91 2.66 0.59 8.03 9.8 32.99 Good Line 3 15 760 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Go	Line 3	15	460	15	480	20	4.57	1.0	0.82	2.01	3.54	11.94	Very Good
Line 3 15 520 15 540 20 194 0.7 0.62 3.39 5.15 11.81 Very Go Line 3 15 540 15 560 20 3.14 0.95 1.07 2.68 2.8 10.64 Very Go Line 3 15 560 15 560 20 2.49 1.38 0.69 3.33 5.16 13.05 Very Go Line 3 15 580 15 600 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Go Line 3 15 600 15 620 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 620 15 640 20 2.05 0.94 0.78 2.68 3.53 9.88 Very Go Line 3 15 640 15 660 20 4.22 1.8 0.85 5.32 5.14 17.33 Very Go Line 3 15 660 15 680 20 2.63 1.09 0.98 1.69 2.79 9.18 Very Go Line 3 15 680 15 700 20 2.18 0.69 0.72 3.11 2.92 9.62 Very Go Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.09 9.69 Very Go Line 3 15 740 15 760 20 11.91 2.66 0.59 8.03 9.8 32.99 Good Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Go	Line 3	15	480	15	500	20	3.44	1.91	0.72	2.56	3.46	12.09	Very Good
Line 3 15 540 15 560 20 3.14 0.95 1.07 2.68 2.8 10.64 Very Go Line 3 15 560 15 580 20 2.49 1.38 0.69 3.33 5.16 13.05 Very Go Line 3 15 580 15 600 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Go Line 3 15 600 15 620 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go Line 3 15 620 15 640 20 2.05 0.94 0.78 2.68 3.53 9.98 Very Go Line 3 15 640 15 660 20 4.22 1.8 0.85 5.32 5.14 17.33 Very Go Line 3 15 660 15 660 20 2.63 1.09 0.98 1.69 2.79 9.18 Very Go Line 3 15 660 15 700 20 2.18 0.69 0.72 3.11 2.92 9.62 Very Go Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.09 9.69 Very Go Line 3 15 740 15 760 20 11.91 2.66 0.59 8.03 9.8 3.29 Good Line 3 15 740 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Go	Line 3	15	500	15	520	20	3.37	1.94	0.61	2.5	4.04	12.46	Very Good
Line 3 15 560 15 580 20 2.49 1.38 0.69 3.33 5.16 13.05 Very Go  Line 3 15 580 15 600 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Go  Line 3 15 600 15 620 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Go  Line 3 15 620 15 640 20 2.05 0.94 0.78 2.68 3.53 9.98 Very Go  Line 3 15 640 15 660 20 4.22 1.8 0.85 5.32 5.14 17.33 Very Go  Line 3 15 660 15 680 20 2.63 1.09 0.98 1.69 2.79 9.18 Very Go  Line 3 15 680 15 700 20 2.18 0.69 0.72 3.11 2.92 9.62 Very Go  Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.09 9.69 Very Go  Line 3 15 720 15 740 20 7.23 2.31 0.78 4.15 10.79 25.26 Very Go  Line 3 15 760 15 760 20 11.91 2.66 0.59 8.03 9.8 32.99 Good  Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Go	Line 3	15	520	15	540	20	1.94	0.7	0.62	3.39	5.15	11.81	Very Good
Line 3 15 580 15 600 20 4.22 2.7 0.49 3.26 4.92 15.58 Very Gold Line 3 15 600 15 620 20 2.12 1.71 0.64 2.19 3.76 10.41 Very Gold Line 3 15 620 15 640 20 2.05 0.94 0.78 2.68 3.53 9.98 Very Gold Line 3 15 640 15 660 20 4.22 1.8 0.85 5.32 5.14 17.33 Very Gold Line 3 15 660 15 680 20 2.63 1.09 0.98 1.69 2.79 9.18 Very Gold Line 3 15 680 15 700 20 2.18 0.69 0.72 3.11 2.92 9.62 Very Gold Line 3 15 700 15 720 20 2.14 1.0 0.8 1.66 4.09 9.69 Very Gold Line 3 15 720 15 740 20 7.23 2.31 0.78 4.15 10.79 2.526 Very Gold Line 3 15 740 15 760 20 11.91 2.66 0.59 8.03 9.8 32.99 Good Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Gold Line 3 15 760 20 20 20 20 20 20 20 20 20 20 20 20 20	Line 3	15	540	15	560	20	3.14	0.95	1.07	2.68	2.8	10.64	Very Good
Line 3         15         600         15         620         20         2.12         1.71         0.64         2.19         3.76         10.41         Very Got           Line 3         15         620         15         640         20         2.05         0.94         0.78         2.68         3.53         9.98         Very Got           Line 3         15         640         15         660         20         4.22         1.8         0.85         5.32         5.14         17.33         Very Got           Line 3         15         660         15         680         20         2.63         1.09         0.98         1.69         2.79         9.18         Very Got           Line 3         15         680         15         700         20         2.18         0.69         0.72         3.11         2.92         9.62         Very Got           Line 3         15         700         15         720         20         2.14         1.0         0.8         1.66         4.09         9.69         Very Got           Line 3         15         720         15         740         20         7.23         2.31         0.78         4.15	Line 3	15	560	15	580	20	2.49	1.38	0.69	3.33	5.16	13.05	Very Good
Line 3         15         620         15         640         20         2.05         0.94         0.78         2.68         3.53         9.98         Very Got           Line 3         15         640         15         660         20         4.22         1.8         0.85         5.32         5.14         17.33         Very Got           Line 3         15         660         15         680         20         2.63         1.09         0.98         1.69         2.79         9.18         Very Got           Line 3         15         680         15         700         20         2.18         0.69         0.72         3.11         2.92         9.62         Very Got           Line 3         15         700         15         720         20         2.14         1.0         0.8         1.66         4.09         9.69         Very Got           Line 3         15         720         15         740         20         7.23         2.31         0.78         4.15         10.79         25.26         Very Got           Line 3         15         740         15         760         20         11.91         2.66         0.59         8.03	Line 3	15	580	15	600	20	4.22	2.7	0.49	3.26	4.92	15.58	Very Good
Line 3         15         640         15         660         20         4.22         1.8         0.85         5.32         5.14         17.33         Very God           Line 3         15         660         15         680         20         2.63         1.09         0.98         1.69         2.79         9.18         Very God           Line 3         15         680         15         700         20         2.18         0.69         0.72         3.11         2.92         9.62         Very God           Line 3         15         700         15         720         20         2.14         1.0         0.8         1.66         4.09         9.69         Very God           Line 3         15         720         15         740         20         7.23         2.31         0.78         4.15         10.79         25.26         Very God           Line 3         15         740         15         760         20         11.91         2.66         0.59         8.03         9.8         32.99         Good           Line 3         15         760         15         780         20         10.17         2.31         0.67         2.81	Line 3	15	600	15	620	20	2.12	1.71	0.64	2.19	3.76	10.41	Very Good
Line 3         15         660         15         680         20         2.63         1.09         0.98         1.69         2.79         9.18         Very Got           Line 3         15         680         15         700         20         2.18         0.69         0.72         3.11         2.92         9.62         Very Got           Line 3         15         700         15         720         20         2.14         1.0         0.8         1.66         4.09         9.69         Very Got           Line 3         15         720         15         740         20         7.23         2.31         0.78         4.15         10.79         25.26         Very Got           Line 3         15         740         15         760         20         11.91         2.66         0.59         8.03         9.8         32.99         Good           Line 3         15         760         15         780         20         10.17         2.31         0.67         2.81         3.02         18.98         Very Got	Line 3	15	620	15	640	20	2.05	0.94	0.78	2.68	3.53	9.98	Very Good
Line 3         15         680         15         700         20         2.18         0.69         0.72         3.11         2.92         9.62         Very God           Line 3         15         700         15         720         20         2.14         1.0         0.8         1.66         4.09         9.69         Very God           Line 3         15         720         15         740         20         7.23         2.31         0.78         4.15         10.79         25.26         Very God           Line 3         15         740         15         760         20         11.91         2.66         0.59         8.03         9.8         32.99         Good           Line 3         15         760         15         780         20         10.17         2.31         0.67         2.81         3.02         18.98         Very God	Line 3	15	640	15	660	20	4.22	1.8	0.85	5.32	5.14	17.33	Very Good
Line 3         15         700         15         720         20         2.14         1.0         0.8         1.66         4.09         9.69         Very God           Line 3         15         720         15         740         20         7.23         2.31         0.78         4.15         10.79         25.26         Very God           Line 3         15         740         15         760         20         11.91         2.66         0.59         8.03         9.8         32.99         Good           Line 3         15         760         15         780         20         10.17         2.31         0.67         2.81         3.02         18.98         Very God	Line 3	15	660	15	680	20	2.63	1.09	0.98	1.69	2.79	9.18	Very Good
Line 3 15 720 15 740 20 7.23 2.31 0.78 4.15 10.79 25.26 Very God Line 3 15 740 15 760 20 11.91 2.66 0.59 8.03 9.8 32.99 Good Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very God	Line 3	15	680	15	700	20	2.18	0.69	0.72	3.11	2.92	9.62	Very Good
Line 3 15 740 15 760 20 11.91 2.66 0.59 8.03 9.8 32.99 Good Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very Good	Line 3	15	700	15	720	20	2.14	1.0	0.8	1.66	4.09	9.69	Very Good
Line 3 15 760 15 780 20 10.17 2.31 0.67 2.81 3.02 18.98 Very God	Line 3	15	720	15	740	20	7.23	2.31	0.78	4.15	10.79	25.26	Very Good
	Line 3	15	740	15	760	20	11.91	2.66	0.59	8.03	9.8	32.99	Good
Line 3 15 780 15 800 20 5.34 2.23 0.93 1.17 2.22 11.88 Very Go	Line 3	15	760	15	780	20	10.17	2.31	0.67	2.81	3.02	18.98	Very Good
	Line 3	15	780	15	800	20	5.34	2.23	0.93	1.17	2.22	11.88	Very Good

Line 3	Line 3	15	800	15	820	20	3.15	1.17	1.15	1.9	3.35	10.73	Very Good
Une 3	Line 3	15	820	15	840	20	3.12	1.03	0.73	1.82	1.92	8.62	Very Good
Line 3	Line 3	15	840	15	860	20	2.68	2.53	0.65	1.92	3.42	11.21	Very Good
Line 3	Line 3	15	860	15	880	20	3.94	1.31	1.18	4.01	2.51	12.95	Very Good
Line 3	Line 3	15	880	15	900	20	3.51	1.23	0.55	3.82	1.99	11.09	Very Good
Line 3	Line 3	15	900	15	920	20	3.08	1.05	0.86	0.89	1.66	7.55	Very Good
Line 3	Line 3	15	920	15	940	20	1.67	1.08	1.0	1.57	2.22	7.54	Very Good
Line 3 16 980 16 0 20 1.35 0.97 0.67 0.66 1.93 6.88 Very Good Line 3 16 0 16 20 20 1.24 0.71 0.75 0.56 1.77 5.44 Very Good Line 3 16 20 16 40 20 1.82 1.49 1.02 1.13 1.85 7.11 Very Good Line 3 16 6 60 16 80 20 5.89 2.00 1.18 3.39 5.48 18.57 Very Good Line 3 16 80 16 100 20 3.33 1.01 0.57 2.26 4.08 11.57 Very Good Line 3 16 80 10 16 100 20 3.33 1.01 0.57 2.26 4.08 11.50 Very Good Line 3 16 100 16 120 20 1.89 1.59 1.50 1.69 1.60 1.13 5.02 Very Good Line 3 16 100 16 120 20 1.29 1.01 0.57 2.26 4.08 11.05 11.05 Very Good Line 3 16 100 16 120 20 1.89 1.59 1.50 1.64 3.23 6.1 Very Good Line 3 16 150 16 16 160 20 1.29 1.09 1.01 0.54 1.05 1.13 5.02 Very Good Line 3 16 160 160 20 2.21 1.33 0.08 1.64 3.23 6.1 Very Good Line 3 16 160 160 20 2.21 1.33 0.08 1.64 3.23 6.1 Very Good Line 3 16 160 16 160 20 22 2.21 1.33 0.08 1.64 3.23 6.1 Very Good Line 3 16 160 16 160 20 22 2.21 1.33 0.08 1.64 3.22 1.047 Very Good Line 3 16 160 16 160 20 22 2.21 1.33 0.08 1.64 3.22 1.047 Very Good Line 3 16 160 160 20 22 2.21 1.33 0.08 1.58 3.22 1.047 Very Good Line 3 16 180 180 180 20 20 2.28 0.9 0.42 0.98 1.58 3.22 1.047 Very Good Line 3 16 200 16 220 20 22 2.78 0.9 0.48 0.82 0.97 5.06 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 0.48 0.82 0.97 5.06 Very Good Line 3 16 240 16 260 20 2.78 0.9 0.48 0.82 0.97 5.06 Very Good Line 3 16 240 16 260 20 2.48 1.88 0.55 1.81 3.89 0.9 9 Very Good Line 3 16 280 16 280 20 5.66 4.3 0.55 1.81 3.89 0.9 9 Very Good Line 3 16 280 16 300 16 300 20 1.02 1.02 1.02 1.00 1.00 1.00 1.00	Line 3	15	940	15	960	20	1.12	1.19	1.11	0.82	1.54	5.78	Very Good
Line 3 16 0 16 20 20 1.24 0.71 0.76 0.96 1.77 5.44 Very Good Line 3 16 20 16 40 20 1.82 1.49 1.02 1.13 1.85 7.11 Very Good Line 3 16 40 16 60 20 2.3 1.14 0.47 1.9 2.11 7.93 Very Good Line 3 16 60 16 80 20 5.89 2.09 1.18 3.93 5.48 18.57 Very Good Line 3 16 80 16 100 20 3.13 1.01 0.57 2.26 4.08 11.05 Very Good Line 3 16 100 16 120 20 1.89 1.59 1.01 0.57 2.26 4.08 11.05 Very Good Line 3 16 100 16 120 20 1.89 1.59 1.01 0.54 1.05 1.13 5.02 Very Good Line 3 16 140 16 160 20 2.21 1.33 0.88 1.84 3.23 9.1 Very Good Line 3 16 140 16 160 20 2.21 1.33 0.88 1.84 3.23 9.1 Very Good Line 3 16 180 16 180 20 2.0 3.32 1.37 0.98 1.58 3.22 10.47 Very Good Line 3 16 180 16 200 20 4.2 0.96 1.16 1.99 2.57 10.87 Very Good Line 3 16 220 16 220 2.09 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 220 2.09 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 220 2.09 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 220 2.09 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 220 2.09 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 220 2.0 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 220 20 5.86 4.3 0.78 1.81 3.89 9.9 Very Good Line 3 16 220 16 320 20 5.86 4.3 0.78 1.81 3.89 9.9 Very Good Line 3 16 220 16 320 20 5.86 4.3 0.78 1.81 3.89 9.9 Very Good Line 3 16 320 16 320 16 320 20 5.86 4.3 0.78 1.81 3.89 9.9 Very Good Line 3 16 320 16 320 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 320 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 320 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 320 20 1.02 1.59 0.66 1.18 1.51 8.88 Very Good Line 3 16 340 16 320 16 320 20 1.02 1.59 0.66 1.18 1.51 8.88 Very Good Line 3 16 340 16 340 16 340 20 1.02 1.59 0.66 1.18 1.51 8.88 Very Good Line 3 16 340 16 340 16 340 20 1.02 1.02 2.23 0.4 0.4 0.08 1.5 6.13 Very Good Line 3 16 340 16 340 16 340 20 1.02 1.02 2.23 0.4 0.4 0.08 1.5 6.13 Ve	Line 3	15	960	15	980	20	1.97	1.09	0.99	1.25	2.35	7.65	Very Good
Line 3 16 20 16 40 20 1.62 1.49 1.02 1.13 1.86 7.11 Very Good Line 3 16 40 16 60 20 2.3 1.14 0.47 1.9 2.11 7.93 Very Good Line 3 16 80 16 100 20 3.13 1.01 0.57 2.28 4.08 11.05 Very Good Line 3 16 100 16 120 20 1.89 1.59 0.8 1.20 2.00 7.46 Very Good Line 3 16 100 16 120 20 1.89 1.59 0.8 1.20 2.00 7.46 Very Good Line 3 16 140 16 160 20 2.21 1.33 0.88 1.64 3.23 9.1 Very Good Line 3 16 140 16 160 20 2.21 1.33 0.88 1.64 3.23 9.1 Very Good Line 3 16 160 16 16 20 2.21 1.33 0.88 1.58 3.22 10.47 Very Good Line 3 16 160 16 16 20 20 2.21 1.33 0.88 1.58 3.22 10.47 Very Good Line 3 16 160 16 160 20 2.27 1.39 0.98 1.58 3.22 10.47 Very Good Line 3 16 160 160 20 2.27 1.39 0.98 1.58 3.22 10.47 Very Good Line 3 16 160 20 16 20 2.78 0.9 0.48 0.82 0.97 5.98 Very Good Line 3 16 20 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 20 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 220 16 240 20 2.21 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 220 16 220 20 5.66 4.3 0.78 1.94 1.52 1.42 Very Good Line 3 16 220 16 220 20 5.66 4.3 0.78 1.94 1.52 1.42 Very Good Line 3 16 220 16 340 20 1.02 1.57 1.9 0.9 1.04 1.52 1.42 Very Good Line 3 16 320 16 340 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 340 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 340 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 340 20 1.01 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 340 20 1.01 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 340 20 1.01 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 340 20 1.01 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 340 20 1.01 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 340 20 1.01 1.02 1.59 0.66 1.18 1.51 1.88 88 Very Good Line 3 16 340 16 340 16 340 20 1.02 1.02 1.59 0.66 1.02 1.55 1.56 1.30 Very Good Line 3 16 340 16 340 16 340 20 1.02	Line 3	15	980	16	0	20	1.35	0.97	0.67	0.95	1.93	5.88	Very Good
Line 3	Line 3	16	0	16	20	20	1.24	0.71	0.75	0.96	1.77	5.44	Very Good
Line 3 16 60 16 80 20 5.89 2.09 1.18 3.33 5.48 18.57 Very Good Line 3 16 80 16 100 20 3.13 1.01 0.57 2.26 4.08 11.05 Very Good Line 3 16 100 16 120 20 1.69 1.59 0.8 1.29 2.09 7.46 Very Good Line 3 16 120 16 140 20 1.29 1.01 0.54 1.05 1.13 5.02 Very Good Line 3 16 140 16 160 20 221 1.33 0.68 1.64 3.23 8.1 Very Good Line 3 16 160 160 16 180 20 3.32 1.37 0.98 1.58 3.22 10.47 Very Good Line 3 16 180 16 200 20 4.2 0.96 1.16 1.99 2.57 10.87 Very Good Line 3 16 200 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 220 16 280 20 2.18 1.68 0.55 1.81 3.69 3.9 Very Good Line 3 16 280 16 300 20 3.0 1.17 0.66 1.08 1.66 7.56 Very Good Line 3 16 380 16 380 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 380 16 380 20 1.02 2.23 0.4 0.98 1.58 1.51 8.88 Very Good Line 3 16 380 16 380 20 1.02 2.23 0.4 0.98 1.55 6.13 Very Good Line 3 16 380 16 380 20 1.02 2.23 0.4 0.98 1.58 1.51 8.88 Very Good Line 3 16 380 16 380 20 1.02 2.23 0.4 0.98 1.55 6.13 Very Good	Line 3	16	20	16	40	20	1.62	1.49	1.02	1.13	1.85	7.11	Very Good
Line 3 16 80 16 100 20 3.13 1.01 0.57 2.26 4.08 11.05 Very Good Line 3 16 100 16 120 20 1.89 1.59 0.8 1.29 2.09 7.46 Very Good Line 3 16 120 16 140 20 1.29 1.01 0.54 1.05 1.13 5.02 Very Good Line 3 16 140 16 160 20 2.21 1.33 0.68 1.64 3.23 9.1 Very Good Line 3 16 160 16 180 20 3.32 1.37 0.98 1.58 3.22 10.47 Very Good Line 3 16 180 16 200 20 4.2 0.96 1.16 1.99 2.57 10.87 Very Good Line 3 16 200 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 240 16 260 20 2.18 1.88 0.55 1.81 3.69 9.9 Very Good Line 3 16 280 16 300 20 3.0 1.17 0.66 1.08 1.66 7.56 Very Good Line 3 16 300 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 300 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 300 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 340 16 380 20 0.79 3.52 1.03 1.83 1.51 8.88 Very Good Line 3 16 340 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good Line 3 16 340 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good Line 3 16 340 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good	Line 3	16	40	16	60	20	2.3	1.14	0.47	1.9	2.11	7.93	Very Good
Line 3 16 100 16 120 20 1.69 1.59 0.8 1.29 2.08 7.46 Very Good Line 3 16 120 16 140 20 1.29 1.01 0.54 1.05 1.13 5.02 Very Good Line 3 16 140 16 180 20 2.21 1.33 0.68 1.64 3.23 9.1 Very Good Line 3 16 160 16 180 20 3.32 1.37 0.98 1.58 3.22 10.47 Very Good Line 3 16 180 16 200 20 4.2 0.96 1.16 1.99 2.57 10.87 Very Good Line 3 16 200 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 220 16 260 20 2.18 1.68 0.55 1.81 3.69 9.9 Very Good Line 3 16 260 16 280 20 5.66 4.3 0.78 1.94 1.52 14.2 Very Good Line 3 16 320 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 340 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 340 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 360 16 380 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good	Line 3	16	60	16	80	20	5.89	2.09	1.18	3.93	5.48	18.57	Very Good
Line 3 16 120 16 140 20 129 1.01 0.54 1.05 1.13 5.02 Very Good Line 3 16 140 16 160 20 2.21 1.33 0.68 1.64 3.23 9.1 Very Good Line 3 16 160 160 16 180 20 3.32 1.37 0.98 1.58 3.22 10.47 Very Good Line 3 16 180 16 200 20 4.2 0.96 1.16 1.99 2.57 10.87 Very Good Line 3 16 200 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 240 16 260 20 2.18 1.68 0.55 1.81 3.69 9.9 Very Good Line 3 16 280 16 280 20 5.66 4.3 0.78 1.94 1.52 14.2 Very Good Line 3 16 280 16 300 20 3.0 1.17 0.66 1.08 1.66 7.56 Very Good Line 3 16 300 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 300 16 320 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good	Line 3	16	80	16	100	20	3.13	1.01	0.57	2.26	4.08	11.05	Very Good
Line 3 16 140 16 160 20 2.21 1.33 0.68 1.64 3.23 9.1 Very Good Line 3 16 160 160 16 180 20 3.32 1.37 0.98 1.58 3.22 10.47 Very Good Line 3 16 180 16 200 20 4.2 0.96 1.16 1.99 2.57 10.87 Very Good Line 3 16 200 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 240 16 260 20 2.18 1.68 0.55 1.81 3.69 9.9 Very Good Line 3 16 260 16 280 20 5.66 4.3 0.78 1.94 1.52 14.2 Very Good Line 3 16 280 16 300 20 3.0 1.17 0.66 1.08 1.66 7.56 Very Good Line 3 16 320 16 340 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 340 16 380 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 340 16 380 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 340 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good	Line 3	16	100	16	120	20	1.69	1.59	0.8	1.29	2.09	7.46	Very Good
Line 3 16 160 16 180 20 3.32 1.37 0.98 1.58 3.22 10.47 Very Good  Line 3 16 180 16 200 20 4.2 0.96 1.16 1.99 2.57 10.87 Very Good  Line 3 16 200 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good  Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good  Line 3 16 240 16 260 20 2.18 1.68 0.55 1.81 3.69 9.9 Very Good  Line 3 16 260 16 280 20 5.66 4.3 0.78 1.94 1.52 14.2 Very Good  Line 3 16 280 16 300 20 3.0 1.17 0.66 1.08 1.66 7.56 Very Good  Line 3 16 300 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good  Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good  Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good  Line 3 16 380 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good	Line 3	16	120	16	140	20	1.29	1.01	0.54	1.05	1.13	5.02	Very Good
Line 3 16 180 16 200 20 4.2 0.96 1.16 1.99 2.57 10.87 Very Good Line 3 16 200 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 240 16 260 20 2.18 1.68 0.55 1.81 3.69 9.9 Very Good Line 3 16 260 16 280 20 5.66 4.3 0.78 1.94 1.52 14.2 Very Good Line 3 16 280 16 300 20 3.0 1.17 0.66 1.08 1.66 7.56 Very Good Line 3 16 300 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 360 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good	Line 3	16	140	16	160	20	2.21	1.33	0.68	1.64	3.23	9.1	Very Good
Line 3 16 200 16 220 20 2.78 0.9 0.48 0.82 0.97 5.96 Very Good Line 3 16 220 16 240 20 1.57 1.9 0.9 1.04 2.19 7.6 Very Good Line 3 16 240 16 260 20 2.18 1.68 0.55 1.81 3.69 9.9 Very Good Line 3 16 260 16 280 20 5.66 4.3 0.78 1.94 1.52 14.2 Very Good Line 3 16 280 16 300 20 3.0 1.17 0.66 1.08 1.66 7.56 Very Good Line 3 16 300 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good Line 3 16 360 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good	Line 3	16	160	16	180	20	3.32	1.37	0.98	1.58	3.22	10.47	Very Good
Line 3         16         220         16         240         20         1.57         1.9         0.9         1.04         2.19         7.6         Very Good           Line 3         16         240         16         260         20         2.18         1.68         0.55         1.81         3.69         9.9         Very Good           Line 3         16         260         16         280         20         5.66         4.3         0.78         1.94         1.52         14.2         Very Good           Line 3         16         280         16         300         20         3.0         1.17         0.66         1.08         1.66         7.56         Very Good           Line 3         16         300         16         320         20         1.02         1.59         0.66         1.18         1.29         5.74         Very Good           Line 3         16         320         16         340         20         1.11         2.47         0.51         0.9         2.01         7.01         Very Good           Line 3         16         340         16         360         20         0.79         3.52         1.03         1.83	Line 3	16	180	16	200	20	4.2	0.96	1.16	1.99	2.57	10.87	Very Good
Line 3 16 240 16 260 20 2.18 1.68 0.55 1.81 3.69 9.9 Very Good  Line 3 16 260 16 280 20 5.66 4.3 0.78 1.94 1.52 14.2 Very Good  Line 3 16 280 16 300 20 3.0 1.17 0.66 1.08 1.66 7.56 Very Good  Line 3 16 300 16 320 20 1.02 1.59 0.66 1.18 1.29 5.74 Very Good  Line 3 16 320 16 340 20 1.11 2.47 0.51 0.9 2.01 7.01 Very Good  Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good  Line 3 16 360 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good	Line 3	16	200	16	220	20	2.78	0.9	0.48	0.82	0.97	5.96	Very Good
Line 3         16         260         16         280         20         5.66         4.3         0.78         1.94         1.52         14.2         Very Good           Line 3         16         280         16         300         20         3.0         1.17         0.66         1.08         1.66         7.56         Very Good           Line 3         16         300         16         320         20         1.02         1.59         0.66         1.18         1.29         5.74         Very Good           Line 3         16         320         16         340         20         1.11         2.47         0.51         0.9         2.01         7.01         Very Good           Line 3         16         340         16         360         20         0.79         3.52         1.03         1.83         1.51         8.68         Very Good           Line 3         16         360         16         380         20         1.02         2.23         0.4         0.98         1.5         6.13         Very Good	Line 3	16	220	16	240	20	1.57	1.9	0.9	1.04	2.19	7.6	Very Good
Line 3         16         280         16         300         20         3.0         1.17         0.66         1.08         1.66         7.56         Very Good           Line 3         16         300         16         320         20         1.02         1.59         0.66         1.18         1.29         5.74         Very Good           Line 3         16         320         16         340         20         1.11         2.47         0.51         0.9         2.01         7.01         Very Good           Line 3         16         340         16         360         20         0.79         3.52         1.03         1.83         1.51         8.68         Very Good           Line 3         16         360         16         380         20         1.02         2.23         0.4         0.98         1.5         6.13         Very Good	Line 3	16	240	16	260	20	2.18	1.68	0.55	1.81	3.69	9.9	Very Good
Line 3         16         300         16         320         20         1.02         1.59         0.66         1.18         1.29         5.74         Very Good           Line 3         16         320         16         340         20         1.11         2.47         0.51         0.9         2.01         7.01         Very Good           Line 3         16         340         16         360         20         0.79         3.52         1.03         1.83         1.51         8.68         Very Good           Line 3         16         360         16         380         20         1.02         2.23         0.4         0.98         1.5         6.13         Very Good	Line 3	16	260	16	280	20	5.66	4.3	0.78	1.94	1.52	14.2	Very Good
Line 3     16     320     16     340     20     1.11     2.47     0.51     0.9     2.01     7.01     Very Good       Line 3     16     340     16     360     20     0.79     3.52     1.03     1.83     1.51     8.68     Very Good       Line 3     16     360     16     380     20     1.02     2.23     0.4     0.98     1.5     6.13     Very Good	Line 3	16	280	16	300	20	3.0	1.17	0.66	1.08	1.66	7.56	Very Good
Line 3 16 340 16 360 20 0.79 3.52 1.03 1.83 1.51 8.68 Very Good  Line 3 16 360 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good	Line 3	16	300	16	320	20	1.02	1.59	0.66	1.18	1.29	5.74	Very Good
Line 3 16 360 16 380 20 1.02 2.23 0.4 0.98 1.5 6.13 Very Good	Line 3	16	320	16	340	20	1.11	2.47	0.51	0.9	2.01	7.01	Very Good
	Line 3	16	340	16	360	20	0.79	3.52	1.03	1.83	1.51	8.68	Very Good
Line 3 16 380 16 400 20 1.06 0.77 0.85 1.1 1.79 5.58 Very Good	Line 3	16	360	16	380	20	1.02	2.23	0.4	0.98	1.5	6.13	Very Good
	Line 3	16	380	16	400	20	1.06	0.77	0.85	1.1	1.79	5.58	Very Good

Line 3
Ling 3         16         440         16         460         20         0.97         1.74         1.2         0.92         1.71         6.54           Line 3         16         460         16         480         20         0.93         1.98         0.74         0.99         0.78         5.42           Line 3         16         480         16         500         20         0.72         2.61         0.61         0.61         0.92         5.68           Line 3         16         500         16         520         20         1.59         2.64         0.53         1.16         1.91         7.83           Line 3         16         520         16         540         20         1.79         2.3         0.71         1.31         2.28         6.4           Line 3         16         540         16         560         20         1.51         0.99         0.39         0.38         0.74         4.01           Line 3         16         550         16         580         20         1.0         0.75         0.76         0.5         0.73         3.76           Line 3         16         600         16         620<
Line 3 16 460 16 480 20 0.83 1.99 0.74 0.99 0.78 5.42  Line 3 16 480 16 500 20 0.72 2.61 0.81 0.61 0.92 5.68  Line 3 16 500 16 5.20 20 1.59 2.64 0.53 1.16 1.91 7.83  Line 3 16 520 16 540 20 1.79 2.3 0.71 1.31 2.28 8.4  Line 3 16 540 16 560 20 1.51 0.99 0.39 0.39 0.38 0.74 4.01  Line 3 16 580 16 580 20 1.0 0.75 0.76 0.5 0.73 3.76  Line 3 16 580 16 600 20 0.96 0.76 0.5 0.73 3.76  Line 3 16 600 16 620 20 0.96 0.76 0.83 0.7 0.94 3.99  Line 3 16 600 16 620 20 0.99 0.89 0.77 0.77 0.53 0.77 3.59  Line 3 16 640 16 660 20 0.99 0.89 0.77 1.11 1.42 5.17  Line 3 16 680 16 680 20 0.79 0.89 0.77 1.11 1.42 5.17  Line 3 16 680 16 680 20 0.79 0.89 0.89 0.77 1.11 1.42 5.17  Line 3 16 680 16 680 20 0.79 0.79 0.57 0.57 0.61 1.17 3.7  Line 3 16 680 16 680 20 0.79 0.77 0.83 1.37  Line 3 16 680 16 680 20 0.79 0.77 0.57 0.57 0.51 1.17 1.42 5.17  Line 3 16 680 16 680 20 0.79 0.77 0.57 0.57 0.51 1.17 1.42 5.17  Line 3 16 680 16 680 20 0.79 0.77 0.83 1.03 1.82 7.46  Line 3 16 700 16 720 20 2.31 1.47 0.83 1.03 1.82 7.46  Line 3 16 720 16 740 20 2.95 2.0 0.49 0.65 1.28 7.38  Line 3 16 780 16 800 20 1.39 1.04 0.69 4.3 1.13 0.55  Line 3 16 780 16 800 20 5.54 3.88 0.92 5.19 5.89 21.43  Line 3 16 780 16 800 20 5.54 3.88 0.92 5.19 5.89 21.43
Line 3         16         480         16         500         20         0.72         2.61         0.81         0.61         0.92         5.68           Line 3         16         500         16         520         20         1.59         2.84         0.53         1.16         1.91         7.83           Line 3         16         520         16         540         20         1.79         2.3         0.71         1.31         2.28         8.4           Line 3         16         540         16         560         20         1.51         0.99         0.39         0.38         0.74         4.01           Line 3         16         560         16         580         20         1.0         0.75         0.76         0.5         0.73         3.76           Line 3         16         580         16         600         20         0.96         0.76         0.63         0.7         0.94         3.99           Line 3         16         600         16         620         20         0.92         0.66         0.55         0.8         1.19         4.11           Line 3         16         640         16         640 </td
Line 3         16         500         16         520         20         1.59         2.64         0.53         1.16         1.91         7.83           Line 3         16         520         16         540         20         1.79         2.3         0.71         1.31         2.28         8.4           Line 3         16         540         16         560         20         1.51         0.99         0.39         0.38         0.74         4.01           Line 3         16         560         16         580         20         1.0         0.75         0.76         0.5         0.73         3.76           Line 3         16         580         16         600         20         0.96         0.76         0.63         0.7         0.94         3.99           Line 3         16         600         16         620         20         0.92         0.66         0.55         0.8         1.19         4.11           Line 3         16         620         16         640         20         0.93         0.7         0.77         0.53         0.77         3.89           Line 3         16         640         16         660
Line 3         16         520         16         540         20         1.79         2.3         0.71         1.31         2.28         8.4           Line 3         16         540         16         560         20         1.51         0.99         0.39         0.38         0.74         4.01           Line 3         16         560         16         580         20         1.0         0.75         0.76         0.5         0.73         3.76           Line 3         16         580         16         600         20         0.96         0.76         0.63         0.7         0.94         3.99           Line 3         16         600         16         620         20         0.92         0.66         0.55         0.8         1.19         4.11           Line 3         16         620         16         640         20         0.93         0.7         0.77         0.53         0.77         3.69           Line 3         16         640         16         660         20         0.93         0.89         0.77         1.11         1.42         5.17           Line 3         16         660         16         680
Line 3         16         540         16         560         20         1.51         0.99         0.39         0.38         0.74         4.01           Line 3         16         560         16         580         20         1.0         0.75         0.76         0.5         0.73         3.76           Line 3         16         580         16         600         20         0.98         0.76         0.63         0.7         0.94         3.99           Line 3         16         600         16         620         20         0.92         0.66         0.55         0.8         1.19         4.11           Line 3         16         620         16         640         20         0.93         0.7         0.77         0.53         0.77         3.69           Line 3         16         640         16         660         20         0.98         0.89         0.77         1.11         1.42         5.17           Line 3         16         660         16         680         20         0.79         0.57         0.57         0.61         1.17         3.7           Line 3         16         700         16         720 </td
Line 3         16         560         16         580         20         1.0         0.75         0.76         0.5         0.73         3.76           Line 3         16         580         16         600         20         0.96         0.76         0.63         0.7         0.94         3.99           Line 3         16         600         16         620         20         0.92         0.66         0.55         0.8         1.19         4.11           Line 3         16         620         16         640         20         0.93         0.7         0.77         0.53         0.77         3.69           Line 3         16         640         16         660         20         0.98         0.89         0.77         1.11         1.42         5.17           Line 3         16         680         16         680         20         0.79         0.57         0.57         0.61         1.17         3.7           Line 3         16         680         16         700         20         1.09         0.7         0.68         0.59         0.78         3.83           Line 3         16         700         16         720
Line 3         16         580         16         600         20         0.96         0.76         0.63         0.7         0.94         3.99           Line 3         16         600         16         620         20         0.92         0.66         0.55         0.8         1.19         4.11           Line 3         16         620         16         640         20         0.93         0.7         0.77         0.53         0.77         3.69           Line 3         16         640         16         660         20         0.98         0.89         0.77         1.11         1.42         5.17           Line 3         16         660         16         680         20         0.79         0.57         0.57         0.61         1.17         3.7           Line 3         16         680         16         700         20         1.09         0.7         0.68         0.59         0.78         3.83           Line 3         16         700         16         720         20         2.31         1.47         0.83         1.03         1.82         7.46           Line 3         16         720         16         740<
Line 3         16         600         16         620         20         0.92         0.66         0.55         0.8         1.19         4.11           Line 3         16         620         16         640         20         0.93         0.7         0.77         0.53         0.77         3.69           Line 3         16         640         16         660         20         0.98         0.89         0.77         1.11         1.42         5.17           Line 3         16         660         16         680         20         0.79         0.57         0.57         0.61         1.17         3.7           Line 3         16         680         16         700         20         1.09         0.7         0.68         0.59         0.78         3.83           Line 3         16         700         16         720         20         2.31         1.47         0.83         1.03         1.82         7.46           Line 3         16         720         16         740         20         2.95         2.0         0.49         0.65         1.28         7.38           Line 3         16         740         16         760<
Line 3 16 620 16 640 20 0.93 0.7 0.77 0.53 0.77 3.69  Line 3 16 640 16 660 20 0.98 0.89 0.77 1.11 1.42 5.17  Line 3 16 660 16 680 20 0.79 0.57 0.57 0.61 1.17 3.7  Line 3 16 680 16 700 20 1.09 0.7 0.68 0.59 0.78 3.83  Line 3 16 700 16 720 20 2.31 1.47 0.83 1.03 1.82 7.46  Line 3 16 720 16 740 20 2.95 2.0 0.49 0.65 1.28 7.38  Line 3 16 740 16 760 20 2.63 2.2 1.16 2.35 3.34 11.67  Line 3 16 760 16 780 20 1.39 1.04 0.69 4.3 1.13 8.55  Line 3 16 780 16 800 20 3.53 1.01 0.94 1.35 1.24 8.07  Line 3 16 800 16 820 20 5.54 3.88 0.92 5.19 5.89 21.43  Line 3 16 820 16 840 20 1.61 1.32 0.74 1.38 1.49 6.55
Line 3         16         640         16         660         20         0.98         0.89         0.77         1.11         1.42         5.17           Line 3         16         660         16         680         20         0.79         0.57         0.57         0.61         1.17         3.7           Line 3         16         680         16         700         20         1.09         0.7         0.68         0.59         0.78         3.83           Line 3         16         700         16         720         20         2.31         1.47         0.83         1.03         1.82         7.46           Line 3         16         720         16         740         20         2.95         2.0         0.49         0.65         1.28         7.38           Line 3         16         740         16         760         20         2.63         2.2         1.16         2.35         3.34         11.67           Line 3         16         760         16         780         20         1.39         1.04         0.69         4.3         1.13         8.55           Line 3         16         780         16         800
Line 3         16         660         16         680         20         0.79         0.57         0.57         0.61         1.17         3.7           Line 3         16         680         16         700         20         1.09         0.7         0.68         0.59         0.78         3.83           Line 3         16         700         16         720         20         2.31         1.47         0.83         1.03         1.82         7.46           Line 3         16         720         16         740         20         2.95         2.0         0.49         0.65         1.28         7.38           Line 3         16         740         16         760         20         2.63         2.2         1.16         2.35         3.34         11.67           Line 3         16         760         16         780         20         1.39         1.04         0.69         4.3         1.13         8.55           Line 3         16         780         16         800         20         3.53         1.01         0.94         1.35         1.24         8.07           Line 3         16         800         16         820
Line 3       16       680       16       700       20       1.09       0.7       0.68       0.59       0.78       3.83         Line 3       16       700       16       720       20       2.31       1.47       0.83       1.03       1.82       7.46         Line 3       16       720       16       740       20       2.95       2.0       0.49       0.65       1.28       7.38         Line 3       16       740       16       760       20       2.63       2.2       1.16       2.35       3.34       11.67         Line 3       16       760       16       780       20       1.39       1.04       0.69       4.3       1.13       8.55         Line 3       16       780       16       800       20       3.53       1.01       0.94       1.35       1.24       8.07         Line 3       16       800       16       820       20       5.54       3.88       0.92       5.19       5.89       21.43         Line 3       16       820       16       840       20       1.61       1.32       0.74       1.38       1.49       6.55   <
Line 3       16       700       16       720       20       2.31       1.47       0.83       1.03       1.82       7.46         Line 3       16       720       16       740       20       2.95       2.0       0.49       0.65       1.28       7.38         Line 3       16       740       16       760       20       2.63       2.2       1.16       2.35       3.34       11.67         Line 3       16       760       16       780       20       1.39       1.04       0.69       4.3       1.13       8.55         Line 3       16       780       16       800       20       3.53       1.01       0.94       1.35       1.24       8.07         Line 3       16       800       16       820       20       5.54       3.88       0.92       5.19       5.89       21.43         Line 3       16       820       16       840       20       1.61       1.32       0.74       1.38       1.49       6.55
Line 3         16         720         16         740         20         2.95         2.0         0.49         0.65         1.28         7.38           Line 3         16         740         16         760         20         2.63         2.2         1.16         2.35         3.34         11.67           Line 3         16         760         16         780         20         1.39         1.04         0.69         4.3         1.13         8.55           Line 3         16         780         16         800         20         3.53         1.01         0.94         1.35         1.24         8.07           Line 3         16         800         16         820         20         5.54         3.88         0.92         5.19         5.89         21.43           Line 3         16         820         16         840         20         1.61         1.32         0.74         1.38         1.49         6.55
Line 3       16       740       16       760       20       2.63       2.2       1.16       2.35       3.34       11.67         Line 3       16       760       16       780       20       1.39       1.04       0.69       4.3       1.13       8.55         Line 3       16       780       16       800       20       3.53       1.01       0.94       1.35       1.24       8.07         Line 3       16       800       16       820       20       5.54       3.88       0.92       5.19       5.89       21.43         Line 3       16       820       16       840       20       1.61       1.32       0.74       1.38       1.49       6.55
Line 3       16       760       16       780       20       1.39       1.04       0.69       4.3       1.13       8.55         Line 3       16       780       16       800       20       3.53       1.01       0.94       1.35       1.24       8.07         Line 3       16       800       16       820       20       5.54       3.88       0.92       5.19       5.89       21.43         Line 3       16       820       16       840       20       1.61       1.32       0.74       1.38       1.49       6.55
Line 3     16     780     16     800     20     3.53     1.01     0.94     1.35     1.24     8.07       Line 3     16     800     16     820     20     5.54     3.88     0.92     5.19     5.89     21.43       Line 3     16     820     16     840     20     1.61     1.32     0.74     1.38     1.49     6.55
Line 3 16 800 16 820 20 5.54 3.88 0.92 5.19 5.89 21.43  Line 3 16 820 16 840 20 1.61 1.32 0.74 1.38 1.49 6.55
Line 3 16 820 16 840 20 1.61 1.32 0.74 1.38 1.49 6.55
Line 3 16 840 16 860 20 1.61 1.73 0.78 2.65 0.85 7.62
Line 3 16 860 16 880 20 4.74 5.46 0.62 11.7 7.14 29.66
Line 3 16 880 16 900 20 1.52 1.69 0.66 1.63 3.32 8.82
Line 3 16 900 16 920 20 0.99 1.22 0.5 1.77 3.3 7.79
Line 3 16 920 16 940 20 2.46 2.04 0.97 1.55 3.21 10.23
Line 3 16 940 16 960 20 0.94 2.95 0.54 1.61 0.78 6.82
Line 3 16 960 16 980 20 1.06 1.47 0.56 0.71 0.78 4.58
Line 3 16 980 17 0 20 1.45 2.18 0.92 1.67 2.52 8.73

Line 3	17	0	17	20	20	1.38	3.39	2.25	1.46	3.65	12.13	Very Good
Line 3	17	20	17	40	20	3.37	2.83	0.86	2.63	5.87	15.56	Very Good
Line 3	17	40	17	60	20	2.73	4.22	0.83	2.42	3.69	13.9	Very Good
Line 3	17	60	17	80	20	3.81	4.72	0.73	6.75	3.02	19.03	Very Good
Line 3	17	80	17	100	20	2.11	3.41	0.72	2.23	5.7	14.18	Very Good
Line 3	17	100	17	120	20	3.14	3.31	0.84	4.67	10.21	22.17	Very Good
Line 3	17	120	17	140	20	1.74	4.43	0.57	3.17	3.62	13.53	Very Good
Line 3	17	140	17	160	20	1.65	2.68	1.0	1.97	3.24	10.54	Very Good
Line 3	17	160	17	180	20	2.34	0.94	0.64	0.84	2.07	6.83	Very Good
Line 3	17	180	17	200	20	4.18	3.41	0.71	2.72	3.79	14.81	Very Good
Line 3	17	200	17	220	20	4.74	4.38	0.48	5.64	9.69	24.93	Very Good
Line 3	17	220	17	240	20	8.14	4.88	0.48	10.2	7.7	31.39	Good
Line 3	17	240	17	260	20	7.66	4.57	1.08	11.24	12.03	36.58	Good
Line 3	17	260	17	280	20	4.88	5.1	0.66	1.28	1.96	13.88	Very Good
Line 3	17	280	17	300	20	4.17	5.97	0.71	5.35	5.91	22.11	Very Good
Line 3	17	300	17	320	20	4.45	1.51	0.54	2.39	5.16	14.04	Very Good
Line 3	17	320	17	340	20	8.89	0.0	0.8	1.79	1.74	13.21	Very Good
Line 3	17	340	17	360	20	4.18	0.0	0.68	5.31	2.41	12.58	Very Good
Line 3	17	360	17	380	20	0.0	0.0	0.61	2.16	3.75	6.52	Very Good
Line 3	17	380	17	400	20	0.0	0.0	1.31	4.75	9.85	15.92	Very Good
Line 3	17	400	17	420	20	0.0	0.0	1.07	19.16	18.73	38.95	Good
Line 3	17	420	17	440	20	0.0	0.0	0.0	0.0	0.0	0.0	Very Good
Line 3	17	440	17	460	20	0.0	0.0	0.0	0.0	0.0	0.0	Very Good
Line 3	17	460	17	480	20	0.0	0.0	0.0	0.0	0.0	0.0	Very Good
Line 3	17	480	17	500	20	0.0	0.0	0.0	0.0	0.0	0.0	Very Good
Line 3	17	500	17	520	20	0.0	0.0	0.0	0.0	0.0	0.0	Very Good
Line 3	17	520	17	540	20	0.0	0.0	0.0	0.0	0.0	0.0	Very Good
Line 3	17	540	17	560	20	0.0	0.0	0.0	0.0	0.0	0.0	Very Good