3.1. Technical Specifications & Inventory Codes

Component ID	Description	Spec Code	Tolerance	Status
XJ-900-V2	Hydraulic Pump Valve	`ISO-9902:2024`	±0.05mm	Active
TR-440/B	Thermal Sensor Module	`#TEMP_HI_LIMIT`	< 2%	**Critical**
GS-12-Q	Gasket (Rubber)	`MAT-RUB-004`	N/A	Replacement
A113-Z	Control Unit Layout	`LAYER_04_HEX`	5V DC	Pending

Table 1 Note: The XJ-900-V2 requires calibration every 6 months as per spec ISO-9902.



CONFIDENTIAL: This document contains proprietary data. Unauthorized distribution involves a penalty of up to $50,000

CONFIDENTIAL: This document contains proprietary data. Unauthorized distribution involves a penalty of up to $50,000



4. MAINTENANCE PROCEDURES

Make sure you are wearing proper PPE before beginning this maintenance activity. Refer to plant and department specific PPE requirements. Lockout all stored energy sources in the work area using proper procedure. Review lockout placard and follow plant lockout procedures. If you are unclear how to preform this task, ask your supervisor.

4.1. Emergency Shutdown

- Step 1: Press the Red Button immediately.
- Step 2: Disconnect the main power supply (Cable A).
- Step 3: Call the supervisor at ext 440.

CONFIDENTIAL: This document contains proprietary data. Unauthorized distribution involves a penalty of up to $50,000

Table 2 Schedule Table for Periodic Inspections

Activities	Periodic Inspection Schedule
Inspection	
• Make sure the ceiling remains dry	• Every 3 month
• Check the ceiling protection devices	• Every 3 month
• Check for damage and cracks in the ceiling	• Every 3 month
Maintenance	
• Clean the dust regularly or clean it with a damp cloth	• Every month
• Make sure the surface is always dry	• Every month
• Seal cracks and joints	• Every month
Upkeep	
• Do a ceiling repaint	• Every 6 month
• Apply preservatives, or other suitable protective sealants	• Every 6 month

5. LEGACY SYSTEMS (DEPRECATED)

In previous models (XJ-900-V1), the calibration interval was 12 months. However, this caused frequent overheating issues. Do NOT apply this interval to the V2 series.

APPROVED BY: Quality Control Manager - John Doe - 12/05/2025

CONFIDENTIAL: This document contains proprietary data. Unauthorized distribution involves a penalty of up to $50,000