
Command loss
Future stamp (+10 s)
Frozen scan stamp
Clock reset + scan loss
Trigger-to-zero (ms)
0
50
100
150
200
400
600
800
1000
N W P C F O E G